App. B: Petrie Decl., Ex. 2 Part I

ID	Model	RAMAC	Cal./Ga.	DOM	OB5	C	D/O	D/C	ALLEGED	CAUSE	RE#	2	Resolution Gun not returned to Ilion for
7470	600	n/a			Y	s	8-Mar-12	20.0 12	Fired on Safe Release	Not Examined by Product Service	n/a	F	exam
7470	600	nya	_		1		g-Iviat-12	29-Dec-12	Fired on Sale Release	Service	nya	- F	Per Ilion, to restore
7473	700	84371	308 WIN	25-Jan-10	N	S	9-Mar-12	9-Mar-12	Fired on Safe Release	Could Not Duplicate Concern	261242	F	confidence in the rifle will replace, check over and test at no charge
													Per Ilion, replace TPA, clean and test under BLSM
7474	700	n/a	270 WIN	1-Nov-71	N	S	9-Mar-12	9-Mar-12	Fired on Bolt Closing	Improper Maintenance	261183	F	program price
7475	700	27255	300 WSM	20-Jun-06	N	5	9-Mar-12	9-Mar-12	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	261173	F	Per Ilion, replace TPA, clean, test at 1/2 normal cost
7473	700	27233	500 115/11	20 3011 00	17		3 11101 22	2.19.00	roamon	Components	2022/3	- 1	teat at 2/2 from the coat
7476	700	25859	3006 SPRG	1-Nov-95	N	s	9-Mar-12	9-Mar-12	Safety not working properly	Could Not Duplicate Concern	261126	F	Per Ilion, offer to replace TPA clean, test at 1/2 normal cost
7477	700	n/a	243 WIN	1-Apr-69	N	5	9-Mar-12	9-Mar-12	Fired on Bolt Closing	Could Not Duplicate Concern	261003	F	Per Ilion, offer to replace TPA clean and test fire at BLSM program price
				100						Could Not Duplicate			Per Ilion - Replace TA, clean 8
7478	700	85370	223 REM	13-Jul-09	N	S	12-Mar-12	12-Mar-12	Fired on Safe Release	Concern	261360	F	test fire - warranty
										Could Not Duplicate			Per Ilion, can offer to replace TPA, clean, test fire at 1/2
7480	700	26035	3006 SPRG	15-May-97	N	S	13-Mar-12	13-Mar-12	Fired on Safe Release	Concern	261547	F	
7481	700	n/a	243 WIN	1-Mar-67	N	s	13-Mar-12	13-Mar-12	Fired on Safe Release	Altered Adjustments or Components	261535	F	Per Ilion, replace TPA, clean and test under BLSM program price
7482	700	n/a	270 WIN	1-Jun-74	N	s	13-Mar-12	13-Mar-12	Fired on Safe Release	Altered Adjustments or Components	261544	F	Per Ilion, replace TPA, clean, test at BLSM program price
7483	710	27408	270 WIN	14-Feb-05	Y	s	13-Mar-12	13-Mar-12	Safety not working properly	Could Not Duplicate Concern	261474	F	Return as received.
7487	710	27412	7MM REM MA	9-Jun-05	Y	S	15-Mar-12	15-Mar-12	Fired With Safe ON	Could Not Duplicate Concern	261290	F	Per Ilion - Replace w/85635 - M/770, 7MM REM MAG @ n/c
										Altered Adjustments or			
7488	700	n/a	300 RUM	1-Mar-99	N	S	15-Mar-12	15-Mar-12	Fired on Bolt Closing	Components	261747	F	Per Ilion - Quote to repair Gun not returned to Ilion for
7489	700	25777	7MM MAG		N	5	15-Mar-12	29-Dec-12	Fired on Bolt Closing	Other - Unexamined	n/a	F	exam
7490	700	n/a	243 WIN	26-May-77	N	S	15-Mar-12	19-Jun-13	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
7492	700	n/a	270 WIN	1-Oct-76	N	s	16-Mar-12	16-Mar-12	Fired on Safe Release	Improper Maintenance	261422	F	Per Ilion - Quote to repair under BLM
11000000		- 20	- Commence		150	245	009800000000	SOURCE TO	And the second street, and control and con-	Not Examined by Product			Gun not returned to Ilion for
7494		n/a	223 REM		N	5	16-Mar-12	29-Dec-12	Fired on Bolt Closing Unexplained Discharge - No	Service	n/a	F	exam
7495	600	n/a	308 WIN	21-Apr-77	N	s	19.Mar.13	19-Mar-12	Mention of Safety Position	Altered Adjustments or Components	261375	F	Per Ilion - Repair @ n/c - recall
7433	0.00	iya	200 AAIIA	21-Mi-11		3	13-1901-12	13-Wei-12	Fired on Bolt	Altered Adjustments or	2013/3	-	recen
7496	700	n/a	7MM STW	1-Apr-99	N	S	19-Mar-12	19-Mar-12	Opening	Components	262249	F	Per Ilion - Quote to repair
7497	700	27488	7MM08 REM	9-Jan-97	N	5	19-Mar-12	19-Mar-12	Fired on Safe Release Unexplained Discharge - No	Improper Maintenance	262262	F	Per Ilion - Quote to repair
7500	1100	n/a	12 GA		N	5	10.56se 12	19-Mar-12	Mention of Safety Position	Could Not Duplicate Concern	262095	F	Ber Illian - Quete to repair
		1 1 1 1 1								Could Not Duplicate			Per Ilion - Quote to repair
7501	700	n/a	3006 SPRG	1-Feb-70	N	S	19-Mar-12	19-Mar-12	Fired on Bolt Closing	Concern	261932	F	under BLM

			7MM REM						Safety not working	Could Not Duplicate			Per Ilion - Quote to repair @
7502	700	n/a	MA	1-Jul-70	N	S	19-Mar-12	19-Mar-12	properly	Concern	261937	F	a discount
		Software	60000000000000000000000000000000000000	STATES AND S		- 25	120-1-120-2		1214 (11 - 7 24 27 41 7 41 7 4	Could Not Duplicate	=493500	1	
7507	700	29708	270 WIN	27-Aug-92	N	S	20-Mar-12	12-Apr-12	Fired on Safe Release	Concern	264605	F	Per Ilion - Quote to repair
										Altered Adjustments or			
7510	700	85351	223 REM	16-Aug-07	N	S	21-Mar-12	21-Mar-12		Components	262443	F	Per Ilion - Quote to repair
7512	552	25594	22 RF	11-Nov-09	N	S	21-Mar-12	24-Apr-12	Blowback in Face	Case Separation	262451	F	Refunding for rifle
7513	700	n/a	222 REM	1-Apr-72	N	s	21-Mar-12	21-Mar-12	Fired on Bolt Closing	Altered Adjustments or Components	262452	F	Per Ilion, replace TPA, clean, test at BLSM program price
										Altered Adjustments or			Per Ilion, replace TPA, clean and test fire at BLSM
7515	700	n/a	308 WIN	1-Feb-74	N	S	22-Mar-12	22-Mar-12	Fired on Bolt Closing	Components	262074	F	program price
7516	SPT 78	26160	308 WIN	1-Dec-84	Y	s	22-Mar-12	22-Mar-12	Delayed Firing - Firearms	Improper Maintenance	262688	F	
7518	700	n/a	35 WHELEN	1-Jan-99	N	s	22-Mar-12	22-Mar-12	Fired on Safe Release	Improper Maintenance	262621	F	Per Ilion, replaced fire control, mag parts, tested at no charge
7523	700	n/a	3006 SPRG	12-Jun-78	N	s	26-Mar-12	26-Mar-12	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	262844	F	Replace TPA, clean, test at BLSM
7524	700	29694	300 WIN	22-Jun-95	N	s	26-Mar-12	26-Mar-12	Fired on Bolt Closing	Could Not Duplicate Concern	262955	F	Per Ilion, can offer to replace TPA, clean, test at 1/2 norma cost
7528	770	85651	243 WIN	27-Oct-10	N	s		27-Mar-12	Jar-Off - No Mention of Safety Position	Could Not Duplicate	262767	F	Per Ilion, can replace TPA, clean, test fire to restore confidence at no charge
			7MM REM		1000					Could Not Duplicate		100	Per Watkins, replace TPA no
7529	700	n/a	MA	1-Aug-85	N	5	27-Mar-12	12-Apr-12	Fired on Safe Release	Concern Could Not Duplicate	264941	F	charge
7530	700	n/a	222 REM	1-Sep-62	N.	PD/S	27-Mar-12	17-Apr-12	Fired on Safe Release	Concern	264457	F	Quote to repair under BLM
7532	700	n/a	22-250 REM	1-Jan-66	N	s	27-Mar-12	11-Apr-12	Fired on Safe Release	Altered Adjustments or Components	264455	F	Per Ilion - Quote to repair under BLM
7538	700	27315	7MM RUM	13-Jul-11	N	S	29-Mar-12	29-Mar-12	Jar-Off - No Mention of Safety Position	Altered Adjustments or Components	262957	F	Per Ilion - Replace TA @ n/c - warranty
2520	700	27210	3006 SPRG	40 1 02	1	s	20.1442	20.14 47	First on Cata Balanca		252022	F	Deather Contacts and
7539	700	27319	3006 SPRG	19-Jun-03	N	5	29-Mar-12	29-Mar-12	Fired on Safe Release	Improper Maintenance Altered Adjustments or	263023	F	Per Ilion - Quote to repair Per Ilion - Quote to repair
7540	700	n/a	308 WIN	14-May-80	N	s	20.Mar.12	29-Mar-12	Fired on Safe Release	Components	263376	F	under BLM
. 210		1,90	300 11.01	27 11107 00	.,	_	To tree 46	-3 mar 12		Not Examined by Product	200010	1	Gun not returned to Ilion for
7541	770	85634	308 WIN	6-Apr-10	N	5	29-Mar-12	29-Dec-12	Fired on Safe Release	Service	n/a	F	exam
7542	700	n/a	6MM REM	1-Dec-71	N	PD/S	29-Mar-12	17.Apr.12	Fired on Safe Release	Could Not Duplicate Concern	264311	F	Replace TA @ n/c - goodwill gesture
2005030	876,846.0	200020000	2000 TO 1000	545000000000000		95		500 0 5 7 6 7	Newson are needed	Could Not Duplicate	78374775547711 °		Per Ilion - Check over completely, repair as needed
7544	870	25077	12 GA	28-Oct-11	N	5	29-Mar-12	12-Apr-12	Defective Parts	Concern	264594	F	
7545	700	n/a	3006 SPRG	13-Sep-80	N	S	30-Mar-12	30-Mar-12	Improper Safety Design	Improper Maintenance	263222	F	Per Ilion, replace TPA, clean, test fire at BLSM program price
7549	700	27496	308 WIN	21-Jan-97	N	s	2-Apr-12	2-Apr-12	Unexplained Discharge Safe OFF	Could Not Duplicate Concern	263592	F	Per Ilion - Quote to repair
7550	700	n/a	308 WIN	8-Jul-75	N	s	2-Apr-12	2-Apr-12	Fired on Safe Release	Could Not Duplicate Concern	263520	F	Per Ilion - Quote to repair under BLM
7553	721	n/a	3006 SPRG	1-0ct-56	Y	s	2-Apr-12	20-Apr-12	Fired on Safe Release	Improper Maintenance	265253	F	Per Ilion - Quote to repair under BLM

7556	887	82500	12 GA	8-Dec-09	N	s	3-Apr-12	3-Apr-12	Safety not working properly	Could Not Duplicate Concern	263688	F	Per Ilion, check over completely, repair no charge as goodwill
		-								Could Not Duplicate			Per Ilion - Quote to repair
7558	700	n/a	270 WIN	29-Sep-76	N	s	4-Apr-12	4-Apr-12	Fired on Safe Release	Concern	263751	F	under BLM
		19.5	7MM REM					719180		Could Not Duplicate		-11	Per Ilion - Quote to repair
7561	700	n/a	MA	7-Nov-75	N	s	5-Apr-12	5-Apr-12	Fired on Safe Release	Concern	263874	F	under BLM
,,,,,,	7.00	1,00		7 1101 75	7.5		J ripi at	o ripi au	Thea on sale herease	Other - Unspecified or	100074	Ť	or dear bear.
2024		20000	22 LR			nu in		2010-12	Francisco Barrett	Undetermined - Ammunition			Lonoke refunded for ammo
7571		20000	22 LK		N	PI/S	9-Apr-12	22-Jun-12	Excessive Report		n/a	A	Gun not returned to Ilion fo
7572	597	26536	22LR	23-May-03	N	s	9-Apr-12	29-Dec-12	My Gun Blew Up	Not Examined by Product Service	n/a	F	exam
	700	35300	200 14/84			- 2			Front on Coto Bolovia	Could Not Duplicate	251222		Bartillar Contrata
7563	700	25709	308 WIN	19-Dec-05	N	S	10-Apr-12	10-Apr-12	Fired on Safe Release	Concern	264237	F	Per Ilion - Quote to repair
7564	600	n/a	308 WIN	1-Mar-64	Y	s	10-Apr-12	10-Apr-12	Fired on Safe Release	Could Not Duplicate Concern	264222	F	Per Ilion - Repair @ n/c unde recall
7565	700	n/a	3006 SPRG	1-Feb-75	N	s	10-Apr-12	25-Apr-12	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	265527	F	Per Ilion, replace TPA, clean test at BLSM price
		2000								Not Examined by Product	200400		Gun not returned to Ilion fo
7576	700	n/a	3006 SPRG	13-May-80	N	S	11-Apr-12	19-Jun-13	Fired on Safe Release	Service	n/a	F	exam
7578	887	82500	12 GA	26-Aug-09	N	S	12-Apr-12	12-Apr-12	Fired Out of Battery	Could Not Duplicate Concern	264534	F	Per Ilion, adjust as needed at no charge under warranty
	2000000		7MM REM							Altered Adjustments or	46.0.77.00.74		Replace TPA, clean, test at
7579	700	n/a	MA	1-Mar-68	N	5	12-Apr-12	12-Apr-12	Fired on Safe Release	Components	264582	F	BLSM program price
7583	700	n/a			N	PD/S	13-Apr-12	13-Apr-12	Fired on Safe Release	Other - Unexamined	n/a	o	Customer sold the rifle - no name or address of new owner Per Ilion - Quote to repair
7584	700	n/a	2506 REM	1-Mar-67	N	s	16-Apr-12	16-Apr-12	Fired on Safe Release	Improper Maintenance	264815	F	under BLM
7585	700	25616	7MM08 REM	13-Aug-90	N	s		16-Apr-12	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	264774	F	
										Could Not Duplicate		10	Per Ilion, replace TPA, clean
7587	700	25634	30-06 SPRG	22-Apr-86	N	S	16-Apr-12	1-May-12	Fired on Safe Release	Concern	266119	F	test at no charge
0.000		586869077	22-250	estate esta		-,	course of the		\$200 mary And \$200 cm	Could Not Duplicate			Per Ilion, repair as needed a
7588	700	85434	REM	10-Aug-10	N	S	17-Apr-12	17-Apr-12	Blowback in Face	Concern	264922	F	no charge
7590	700	25815	7MM REM MA	7-Sep-04	N	S	18-Apr-12	18-Apr-12	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	265040	F	Per Ilion - Quote to repair
		- 02							y at many	Could Not Duplicate			Per Ilion - Quote to repair
7591	700	n/a	3006 SPRG	1-Apr-66	N	S	18-Apr-12	18-Apr-12	Fired on Safe Release	Concern	265014	F	under BLM
7593	700	27502	7MM STW	8-Jan-98	N	s	19-Apr-12	19-Apr-12	Fired on Safe Release	Could Not Duplicate Concern	265144	F	Per Ilion - Quote to repair
	20000				7	100					SAME PROPERTY OF		Per Ilion - Quote to repair
7594	700	n/a	3006 SPRG	1-Feb-74	N	S	19-Apr-12	19-Apr-12	Fired on Safe Release		265100	F	under BLM
			22-250							Altered Adjustments or			Per D. Evans, adjust as
7596	700	n/a	REM	1-Dec-82	N	5	19-Apr-12	18-May-12	Fired on Safe Release	Components	267783	F	needed at no charge
7601	742	n/a	308 WIN	1-Apr-75	Υ	S	19-Apr-12	31-May-12	Fired With Safe ON	Could Not Duplicate Concern	268042	F	Clean & test fire @ n/c
2000		20	STEEL STREET	20106482	0.50	90	10000	20100-140	ener persona	Could Not Duplicate	200-0-00-00		para areasan was w
7602	700	n/a	270 WIN	1-Jul-74	N	S	19-Apr-12	8-May-12	Fired on Bolt Closing	Concern	266695	F	Repair @ n/c - goodwill
7599	700	25773	3006 SPRG	19-May-89	N	s	20-Apr-12	20-Apr-12	Fired With Safe ON	Improper Maintenance	265180	F	Per Ilion - Quote to repair
7604	7	24782	243 WIN	1-Dec-82	N	5		1	Fired on Safe Release	Could Not Duplicate	265324	F	Can offer to replace TPA, clean, test at 1/2 normal cos

7607	700	n/a	270 WIN	1-Jun-73	N	s	23-Apr-12	23-Anr-12	Fired on Safe Release	Improper Maintenance	265420	F	Per Ilion, replace TPA, clear test at BLSM price
7007	700	1.04	270 17111	A-2011-7.5	- 15	-	EN HOLAE	EJ-PIPI-AE	Theo on suic hereuse	improper mantenance	200420	-	Per Ilion - Quote to repair (
7610	700ML	27574	50 CAL	11-Sep-98	Y	s	24-Apr-12	4-May-12	Fired on Bolt Closing	Improper Maintenance	266504	F	a discount
										Could Not Duplicate			Replace TPA, clean, test a
7613	700	20000	243 WIN	23-Oct-80	N	S	25-Apr-12	25-Apr-12	Fired on Safe Release	Concern	265279	F	BLSM program price
										Altered Adjustments or		-10	Replace TPA, clean, test a
7614	700	25715	308 WIN	16-Jan-98	N	5	25-Apr-12	25-Apr-12	Fired on Safe Release	Components	265456	F	1/2 normal cost
7617	700	n/a	3006 SPRG	1-Aug-71	N	s	25-Apr-12	11-May-12	Fired on Bolt Closing	Could Not Duplicate Concern	267155	F	Can offer to repair TPA, clea and test at BLSM price
7618	660	n/a	243 WIN	1.14	γ	s	25 4 12	25 404 42	Fired on Safe Release	Altered Adjustments or Components	265705	F	Replace TPA, clean, test at charge under recall
/010	000	nya	243 WIIV	1-May-69	- 1	3	20-Apr-12	20-Apr-12	Delayed Firing -	Components	203703		Replace TPA, clean, test a
7619	700	n/a	270 WIN	1-Jan-80	N	s	26-Apr-12	26-Apr-12	Firearms	Improper Maintenance	265787	F	BLSM price
7620	700	n/a	22-250 REM	21-May-76	N	PD/S	26-Apr-12	18-May-12	Fired on Bolt Opening	Improper Maintenance	266418	F	Repair and clean no charge goodwill gesture.
										000			
7630	597	26556	22 LR	18-Dec-98	N	s	2-May-12	2-May-12	Fixed on Bolt Clasies	Other - Unspecified or Undetermined - Firearms	266190	F	Per Ilion - Repair @ n/c
/630	597	26556	ZZ LK	18-Dec-98	N	3	2-May-12	2-May-12	Unexplained Discharge - No Mention of Safety	Could Not Duplicate	266190	-	Could not duplicate - gun
7631	870	25561	20 GA	7-Apr-98	N	PI/S	2-May-12	14-Jun-12	Position	Concern	n/a	F	returned to customer
	2000000		7 MM REM			545	1272 2000		Delayed Firing -	Not Examined by Product			Gun not returned to Ilion f
7633	700	n/a	U		N	5	2-May-12	29-Dec-12	Firearms	Service	n/a	F	exam
			7MM RE									-17	Returned as Received - CS
7637	700	n/a	MAG	19-Dec-88	N	S	3-May-12	3-May-12	Fired on Safe Release	Improper Maintenance	264981	F	spoke to dealer
100000000		0.020	-out-manual	000000000		0.5	The second second		Delayed Firing -				Per Ilion - Quote to repai
7639	700	n/a	3006 SPRG	1-Jul-70	N	5	4-May-12	4-May-12	Firearms	Improper Maintenance	266358	F	under BLM
7640	700	n/a	3006 SPRG	1-Jul-76	N	s	7-May-12	7-May-12	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	266525	F	Per Ilion - Quote to repair under BLM
										AZENDAN GENDENEL			Per Ilion, replace TPA, clea
		5345	2000000	0.0000000000000000000000000000000000000			- 2142 4770 555			Could Not Duplicate			and check over under BLS!
7643	721	n/a	280 REM	1-Jan-54	Y	S	8-May-12	8-May-12	Fired on Bolt Closing	Concern	266735	F	price
7644	700	26283	7MM RUM	1-Feb-01	N	S	8-May-12	8-May-12	Fired on Bolt Closing	Could Not Duplicate Concern	266685	F	Can offer to replace TPA, clean, test at 1/2 normal co Gun not returned to Ilion f
7649	722	n/a	SAVAGE		N	s	8-May-12	29-Dec-12	Fired on Safe Release	Other - Unexamined	n/a	F	exam
2000	700	-6	270 WIN	10.1 03		s		20.44	Seed on Sele Balance	Altered Adjustments or	250042	F	Per Ilion, replace TPA, clea
7650	700	n/a	Z/U WIIN	10-Jan-03	N	3	o-ividy-12	23-ividy-12	Fired on Safe Release	Components	268913	F	test at 1/2 normal cost Per Ilion, as a good-will
7651	700	27140	300 RUM	22-Jan-10	N	s	9-May-12	9-May-12	Fired on Bolt Closing	Altered Adjustments or Components	266897	F	gesture, will repair as need at no charge
7654	581	n/a	22 RF	6-Feb-81	N	s	10-May-12	10-May-12	Fired on Safe Release	Improper Maintenance	266904	F	Per Ilion, clean and test a 1/2 normal cost
, 004	202	104	22.10	316001		-	25 may 12	as may ac	Unexplained	Could Not Duplicate	200207	- 1	Per Ilion, replace TPA, clea
7655	700	n/a	243 WIN	1-Apr-71	N	S	10-May-12	10-May-12	Discharge Safe ON	Concern	266937	F	test at BLSM price
7657	721	n/a	3006 SPRG	1-Jun-61	Y	s	10-May-12	10-May-12		Improper Maintenance	267023	F	Per Ilion, replace TPA, clea test at BLSM price
7668	700	27475	243 WIN	6-Aug-09	N	s	10-May-12	24-Oct-12	Unexplained Discharge - No Mention of Safety Position	Other - Unexamined	n/a	F	Case turned over to Sr Paralegal

									Fired on Bolt				Replace TPA, clean, test at
7659	700	n/a	270 WIN	1-Feb-71	N	s	14-May-12	14-May-12	Opening	Improper Maintenance	267200	F	BLSM program price.
7661	597	26536	17 HMR	18-Mar-03	N	s		24-May-12	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	268829/282170	F	
7664	700	n/a			N	s	15 May 12	21.May.12	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for
7669	870	25568	12 GA	25-Oct-11	N	s			Fired on Bolt Closing	Could Not Duplicate Concern	267417	F	Per Ilion - Repair under
	Check		100000000000000000000000000000000000000			7.07	Testa de la composición			Could Not Duplicate	(200 - 200 ) (200 - 200 )		warranty
7671	700	29663	308 WIN	28-Jul-09	N	S	16-May-12	16-May-12	Fired on Bolt Closing	Concern	267429	F	Per Ilion - Repair at no char
7672	700	n/a	308 WIN	1-Jul-67	N	s	16-May-12	16-May-12	Fired on Safe Release	Could Not Duplicate Concern	267623	F	Per Ilion - Quote to repair under BLM
7673	XP 100	n/a	221 FIREBA	1-Jun-86	Y	s	17-May-12	17-May-12	Fired on Bolt Closing	Could Not Duplicate Concern	267742	F	Per Ilion, repair as needed a no charge under recall
7674	721	n/a	3006 SPRG	1-Jun-49	Υ	s	17-May-12	17-May-12	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	267705	F	
7675	SPT 78	26172	223 REM	16-Mar-89	Υ	s	17-May-12	17-May-12	Fired on Safe Release	Could Not Duplicate Concern	267714	F	Per Ilion - Quote to repair ( a discount
7679	BACR	90704	5.56 NATO	31-Aug-10	N	s	23-May-12	23-May-12	Fired Out of Battery	Could Not Duplicate Concern	268173	F	Per Ilion - Repair as needed n/c
7683	700	n/a	3006 SPRG	1-Jun-71	N	s	24-May-12	24-May-12	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	268868	F	Per Ilion - Quote to repair under BLM
7685	700	27478	3006 SPRG	21-Jun-95	N	s	29-May-12	26-May-12	Fired on Safe Release	Could Not Duplicate Concern	269199	F	Per Ilion - Quote to repair ( a discount
7687 7691	700	n/a	7MM REM MA 7MM REM EX	1-Apr-74	2 2	s	29-May-12	29-May-12 30-May-12	Unexplained Discharge - No Mention of Safety Position Fired on Bolt	Altered Adjustments or Components Could Not Duplicate	269299	F	Per Ilion - Quote to repair under BLM Rifle returned unrepaired customer demand
/691	/00	nya	EX	1-Apr-79	.N	.5	30-(Viay-12	30-Way-12	Opening	Concern Could Not Duplicate	269502	F	Per Ilion - Quote to repair
7693	700	n/a	3006 SPRG	18-Feb-82	N	S	30-May-12	30-May-12	Fired on Safe Release Safety not working	Concern  Altered Adjustments or	269585	F	under BLM  Per Ilion - Repair @ n/c -
7694	660	n/a	243 WIN	1-Sep-68	Υ	S	30-May-12	30-May-12	properly	Components	269496	F	recall
7696	600	n/a			Υ	s	30-May-12		Defective Parts	Not Examined by Product Service		F	Gun not returned to Ilion for exam
7698	721	n/a	3006 SPRG	1-Aug-49	Υ	s	31-May-12	31-May-12	Safety not working properly	Improper Maintenance	269619	F	Per Ilion - Quote to repair under BLM
7700	700	n/a	3006 SPR	27-Feb-76	N	s	31-May-12	28-Jun-12	Fired on Safe Release	Altered Adjustments or Components	273233	F	Per Ilion, replace TPA, clear test at BLSM price
7701	700	n/a	3006 SPRG	9-Feb-77	N	s	1-Jun-12	1-Jun-12	Fired on Bolt Opening	Improper Maintenance	269905	F	Per Ilion - Quote to repair under BLM
7703	700	n/a	3006 SPRG	7-Apr-82	N	s	4-Jun-12	4-Jun-12	Fired on Safe Release	Improper Maintenance	270043	F	Per Ilion - Quote to repair ( a discount
7704	870	25098	12 GA	15-Sep-06	N	s	4-Jun-12	16-Jul-12	Fired Out of Battery	Fired from Contact with Foreign Object	274391	F	Per Ilion - Repair @ n/c
7706	870	25568	12 GA	24-Mar-11	N	S	5-Jun-12	5-Jun-12	Fired on Bolt Closing	Other - Unspecified or Undetermined - Firearms	270191	F	Per Ilion, repair as needed replace TPA, test fire at no charge under warranty
7721	700	27094	270 WIN	22-May-06	N	s	5-Jun-12	22-Jun-12	Ammunition Exploded	Over Pressured Factory Load	272627	A	Per Ilion - Repair @ n/c
7710	700	27503	6.8 REM SP	1-Mar-06	N	s	6-Jun-12	6-Jun-12	Fired on Safe Release	Altered Adjustments or Components	270538	F	Per Ilion, replace TPA, check over, test fire no charge as goodwill

			7MM-08		-					Altered Adjustments or			Per Ilion - Quote to repair @
7724	700	27015	REM	19-Jul-04	N	S	6-Jun-12	20-Jun-12	Fired on Safe Release		272491	F	
													6-1 to 1
44.00	122207	0340	12270000				2000002			120000000000000000000000000000000000000	12000000	1.2	Per Ilion, replace TPA, clean
7712	600	n/a	308 WIN	1-Feb-64	Υ	S	7-Jun-12	7-Jun-12	Fired on Bolt Closing		270553	F	test under recall at no charg
7715	700	-1-	2506 REM	1 14 70	N	s	8-Jun-12	8-Jun-12	Fined on Balt Classes	Altered Adjustments or	270763	F	Per Ilion, replace TPA, clean
//15	700	n/a	2506 REIVI	1-May-70	IN	3	8-Jun-12	8-Jun-12	Fired on Bolt Closing	Components	2/0/63	-	test at BLSM price
													Per Ilion, replace TPA, clean
7716	721	n/a	3006 SPRG	1-Nov-48	Y	s	8-Jun-12	8-Jun-12	Fired on Bolt Closing	Improper Maintenance	270794	F	
													Per Ilion - Quote to repair
7718	700	n/a	270 WIN	1-Sep-71	N	S	11-Jun-12	11-Jun-12	Fired on Safe Release	Improper Maintenance	270889	F	under BLM
									Unexplained				
									Discharge - No	Carried Control of the Control of th			
Table 10 Tab					acc			****	Mention of Safety	Altered Adjustments or			Per Ilion - Quote to repair
7719	700	n/a	270 WIN	1-0ct-66	N	S	11-Jun-12	11-Jun-12	Position	Components	270940	F	
7722	1100	n/a	12 GA		N	PI/S	11 Jun 17	23-Apr-15	Blowback in Face	Not Examined by Product Service	n/a	A	Gun not returned to Ilion fo exam
1122	1100	nya	12 GA		14	PI/S	11-jun-12	23-Apr-13	Blowback in Pace	Service	nya	-	exam
										Other - Unspecified or			
7728	597	26536	17 HMR	29-May-03	N	S	13-Jun-12	29-Jun-12	Fired Out of Battery	Undetermined - Firearms	273242	F	Replacing with #70723
			7MM-08							Could Not Duplicate			Per Ilion, replace TPA, clean,
7732	700	27453	REM	8-May-02	N	S	15-Jun-12	16-Jul-12	Fired on Safe Release	Concern	274072	F	test at 1/2 normal cost
										Other - Unspecified or			
2000			1,00705			200000	P0272V301		1235 1107/07/25	Undetermined -		2	Lonoke resolved with
7733	Wildcat	n/a	22 LR		N	PI/S	15-Jun-12	15-Aug-12	Blowback in Face	Ammunition	n/a	A	10.210.0210.02
	700		3006 SPRG							Could Not Duplicate		F	Repair @ n/c - goodwill
7734	700	n/a	3006 SPRG	1-Sep-79	N	PI/S	18-Jun-12	22-Jun-12	Fired on Safe Release	Concern Could Not Duplicate	272113	F	gesture Per Ilion - Replace TA @ n/c
7739	700	85543	308 WIN	17-Nov-11	N	s	19-Jun-12	10. Jun. 17	Fired on Safe Release	Concern	272204	F	goodwill gesture
1133	700	00043	300 44114	17-100-11	14	3	19-7011-12	13°JUII*12	Fired on Jane Neicase	Concern	272204	- 1	Per Ilion, replace TPA, clean,
7740	700	n/a	3006 SPRG	1-Jan-73	N.	s	19-Jun-12	19-Jun-12	Fired on Bolt Closing	Improper Maintenance	272360	F	test at BLSM price
									Fired on Bolt			1	
7743	700	n/a	223 REM	21-Dec-77	N	S	20-Jun-12	20-Jun-12	Opening	Broken or Missing Parts	272348	F	Per Ilion - Repair @ n/c
AE ACT			300 WIN	*************		77,5				Altered Adjustments or		-10	Per Ilion - Quote to repair
7744	700	n/a	MA	1-Oct-78	N	S	20-Jun-12	20-Jun-12	Fired on Bolt Closing	Components	272384	F	
										Altered Adjustments or			Per Illon - Quote to repair at
7745	581	29848	22 RF	13-Nov-95	Υ	S	20-Jun-12	20-Jun-12	Fired on Bolt Closing	Components	272391	F	discount
										Other - Unspecified or			Replace no charge under
7746	597	26513	22 LR	5-Oct-11	N	s	20-Jun-12	25-Jun-12	Defective Parts	Undetermined - Firearms	272387	F	
7740	237	20010	EE EN	3 000 11	-14	-	20 3011 12	25 3011 12	Derective raits	Ondetermined - Friedrick	272307	1	Owner found his use of
													improper lubricants was the
7767	788	n/a	n/a	2-Sep-81	Y	5	25-Jun-12	28-Jun-12	Fired on Safe Release	Other - Unexamined	n/a	F	
	I Parties terromonic		7							CT - TOTAL CONTROL OF	12400	7	Per Ilion, check over
	H&R Handi-									Could Not Duplicate			completely, repair as needed
7759	Rifle	72500	223 REM	14-May-03	N	5	26-Jun-12	26-Jun-12	Fired on Bolt Closing	Concern	272964	F	
0.000	1222	2000	7MM08	3236-225	555	- 5	1200 102	2210.00		Could Not Duplicate	100000	12	Per Ilion- Quote to repair @
7760	700	25855	REM	8-Aug-02	N	5	26-Jun-12	26-Jun-12	Fired With Safe ON	Concern	273001	F	discount
									Unexplained Discharge - No				
									Mention of Safety				Per Ilion, offer to replace TPA
7763	700	25791	270 WIN	1-May-84	N	s	27-Jun-12	27-Jun-12	Position	Improper Maintenance	273070	F	clean, test at 1/2 normal cos
											2122	Ť	Per Ilion - Quote to repair
7765	700	n/a	270 WIN	17-Jan-79	N	S	28-Jun-12	28-Jun-12	Fired on Safe Release	Improper Maintenance	273106	F	
									Jamming/Feeding	Other - Unspecified or			Per Ilion - Repair as needed
7769	597	80864	22 LR	18-Apr-11	N	S/C	6-Jul-12	18-Jul-12	issues	Undetermined - Firearms	274576	F	@ n/c

7770	770	85633	3006 SPRG	4-Aug-11	N	s	9-Jul-12	2-Aug-12	Unexplained Discharge Safe OFF	Could Not Duplicate Concern	276637	F	As goodwill, will replace TPA check over and test at no charge
7774	597	80914	22 LR	20-Mar-12	N	s	10-Jul-12	23-Aug-12	Fired Out of Battery	Other - Unspecified or Undetermined - Firearms	279595	F	
7775	700	25709	308 WIN	5-Jun-01	N	s	11-Jul-12	4-Jun-13	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
	700	25774	27011111	4771.00						Could Not Duplicate		١.	Per Ilion - Quote to repair @
7776	/00	25771	270 WIN	1-Jul-85	N	S	16-Jul-12	16-Jul-12	Fired on Safe Release	Concern	273752	F	Per Ilion, replace TPA, clean,
7778	700	20000	270 WIN	1-Nov-74	N	S	16-Jul-12	16-Jul-12	Fired on Safe Release	Improper Maintenance	274347	F	
7779	700	n/a	270 WIN	27-Jun-80	N	s	16-Jul-12	16-Jul-12	Fired on Safe Release	Could Not Duplicate Concern	274363	F	Per Ilion, replace TPA, clean, test at BLSM program price
7784	600	n/a	222 REM	18-May-77	Y	s	16-Jul-12	16-Jul-12	Fired on Bolt Closing	Could Not Duplicate Concern	273541	F	Per Ilion - Repair @ n/c
7785	700	25787	243 WIN	1-Dec-06	N	S	16-Jul-12	16-Jul-12	Fired on Bolt Closing	Could Not Duplicate Concern	274406	F	Per Ilion, offer to replace TPA test at 1/2 normal cost
7786	600	20000	308 WIN	1-Jul-66	Y	s	16-Jul-12	16-Jul-12	Fired on Bolt Closing	Altered Adjustments or Components	273743	F	Per Ilion, replace TPA and tes upder recall at no charge
7788	722	n/a	222 REM	1-Dec-51	Y	s	16-Jul-12	16-Jul-12	Fired on Safe Release	Could Not Duplicate Concern	273511	F	Per Ilion, replace TPA, clean, test at BLSM program price
7789	R25	60032	308 WIN	5-Sep-08	N	s	16-Jul-12	17-Aug-12	Jamming/Feeding issues	Could Not Duplicate Concern	273863	F	Replaced bolt, carrier assm no charge
							12-1 3-121/22			Over pressured shell - not	20 A NO. 2 POSCO	T	Per Release - Replace w/85952 - M/7 Predator &
7790	SEVEN	85950	17 REM FB 300 WIN	28-Apr-08	N	PI/S	16-Jul-12	23-Aug-12	Blowback in Face	returned	276278	F	\$286 for medical Per Ilion - Quote to repair at
7791	700	25807	MA	10-May-90	N	s	16-Jul-12	27-Jul-12	Fired on Bolt Closing	Improper Maintenance Altered Adjustments or	275978	F	
7798	700	n/a	3006 SPRG	1-Jan-72	N	s	16-Jul-12	27-Jul-12	Fired on Safe Release	Components	276013	F	under BLM
7787	788	n/a	222	31-Jan-78	Y	s	16-Jul-12	29-Dec-13	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
7793	700	25795	308 WIN	27-Mar-90	N	S	17-Jul-12	17-Jul-12	Delayed Firing - Firearms	Improper Maintenance	273619	F	Per Ilion, offer to replace TPA clean, test at 1/2 normal cost
7800	600	n/a	243 WIN	1-May-74	Y	5	20-Jul-12	20-Jul-12	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	274929	F	Replace TPA, clean, test under recall at no charge
7803	700	27476	270 WIN	17-Jun-97	N	S	23-Jul-12	23-Jul-12	Fired on Safe Release	Improper Maintenance	274883	F	Offer to replace TPA, clean, test fire at 1/2 normal cost
7804	700	25771	270 WIN	1-Jul-85	N	s	23-Jul-12	23-Jul-12	Fired on Bolt Closing	Could Not Duplicate Concern	274986	F	Per Ilion, offer to replace TPA clean, test fire at 1/2 normal
7805	597	26550	22 LR	15-Oct-97	N	s	23-Jul-12	23-Jul-12	Jamming/Feeding issues	Other - Unspecified or Undetermined - Firearms	275042	F	Per Ilion, check completely and repair as needed no charge
7811	597	26513	22 LR	27-Aug-11	N	S	24-Jul-12	24-Jul-12	Fired on Bolt Closing	Broken or Missing Parts	275381	F	Per Ilion, check over completely, repair as needed at no charge under warranty
										Could Not Duplicate			Per Ilion - Repair under
7813	1187	83700	12 GA	7-Sep-11	N	S	26-Jul-12	26-Jul-12	Fired on Bolt Closing	Concern	275793	F	warranty

7816	700	84364	308 WIN	16-Mar-12	N	PD/S	27-Jul-12	23-Aug-12	Unexplained Discharge Safe OFF	Could Not Duplicate Concern	277626	F	Replace TA @ n/c - goodwill gesture
7819	700	85375	7MM REM MA	30-Nov-07	N	S	31-Jul-12	31-Jul-12	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	276168	F	Per Illion, check over, reset trigger pull to specs, test fin at no charge as goodwill
7822	700	26189	22-250 REM	9-Jul-07	N	s	1-Aug-12	1-Aug-12	Fired on Bolt Closing	Altered Adjustments or Components	276382	F	Per Ilion, replace TPA, clean test at 1/2 normal cost
7828	722	n/a	257 ROBERT	1-Jan-51	Y	s	1-Aug-12	28-Aug-12	Fired on Bolt Closing	Altered Adjustments or Components Altered Adjustments or	280160	F	Per Ilion - Quote to repair under BLM
7829	660	n/a	308 WIN	1-Apr-68	Υ	5	2-Aug-12	21-Aug-12	Fired on Safe Release	Components	278342	F	Per Ilion - Repair under recal
7831	700	25793	3006 SPR	22-Oct-08	N	s	6-Aug-12	22-Aug-12	Fired on Bolt Closing	Could Not Duplicate Concern	279244/279232	F	Replace TPA, check, test at n charge to restore confidence Product not returned for
7835	SR 22	n/a	22 LR		N	PI/S	6-Aug-12	29-Oct-12	Exploded Unexplained	Not Examined by Product Service	n/a	А	exam  Can offer to replace TPA,
7911	7	24751	260 REM	3-Feb-99	N	s	6-Aug-12	6-Aug-12	Discharge - No Mention of Safety Position	Could Not Duplicate Concern	280934	F	clean, test fire at 1/2 norma cost to restore confidence in rifle
7836		N/A	N/A		N	PI/S	8-Aug-12	30-Oct-12	Ammunition Exploded	Not Examined by Product Service	n/a	A	Product not returned for exam
7837	Mark II	n/a	22 LR		N	PI/S	9-Aug-12		Ammunition Exploded	Other - Unspecified or Undetermined - Ammunition	n/a	A	
7841	S&W 617	n/a	22 LR		N	PI/S	13-Aug-12	26-Oct-12	Ammunition Exploded	Other - Unspecified or Undetermined - Ammunition	n/a	А	Lonoke reached resolution w/cusotmer
7843	R15	60102	450 Bush	10-Dec-09	N	s	14-Aug-12	30-Aug-12	Fired on Bolt Closing	Could Not Duplicate Concern	280415	F	Per Ilion, check completely, test fire at no charge
7849	700	25711	308 WIN	29-Oct-02	N	5	20-Aug-12	20-Aug-12	Fired on Bolt Closing	Altered Adjustments or Components	278600	F	Replace TPA, clean and test fire at 1/2 normal cost
7851	700	n/a	270 WIN	1-0ct-76	N	S	20-Aug-12	20-Aug-12	Fired on Safe Release	Altered Adjustments or Components	278737	F	Per Ilion, replace TPA, clean and test fire at BLSM price
7852	700	n/a	3006 SPRG	1-Aug-66	N	s	20-Aug-12	20-Aug-12	Fired on Safe Release	Improper Maintenance	277692	F	
7853	700	n/a	7MM REM MA	1-Oct-79	N	s	20-Aug-12	20-Aug-12	Fired on Bolt Closing	Could Not Duplicate Concern	278735	F	Per Ilion, replace TPA, clean, test fire at BLSM program price
7859	BACR	90704	5.56 NATO	25-Aug-10	N	s	20-Aug-12	20-Aug-12	Went Automatic	Other - Unspecified or Undetermined - Firearms	277627	F	Per Ilion, check over completely. Repair as needed at no charge
7862	700	27313	300 WIN	13-Dec-11	N	S			Fired on Bolt Closing	Could Not Duplicate Concern	278194/282317	F	Per Ilion, to restore confidence, we will replace TPA, check and test at no charge
7863	700	26933	7MM REM MA	13-Jan-95	N	5	20-Aug-12	20-Aug-12	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	277790	F	Per Ilion - Quote to repair @
7865	700	n/a	270 WIN	26-Jan-79	N	s	20-Aug-12	20-Aug-12	Fired on Safe Release	Improper Maintenance	277737	F	Per Ilion - Quote to repair under BLM
7864	597	26516	17 HMR	16-Oct-03	N	s	20-Aug-12	16-Jan-13	My Gun Blew Up	Not Examined by Product Service	280513	F	Replace with a Marlin

			7MM REM						Unexplained Discharge - No Mention of Safety	Altered Adjustments or			Per Ilion - Quote to repair @
7866	700	25803	MA	1-Aug-85	N	S	21-Aug-12	21-Aug-12	Position	Components	278679	F	
7867	700	n/a	3006 SPRG	27-Feb-76	N	s	21-Aug-12	21-Aug-12	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	277701	F	Per Ilion - Quote to repair under BLM
										Could Not Duplicate			Per Ilion - Repair under
7869	700	25635	308 WIN	2-Nov-11	N	S	21-Aug-12	21-Aug-12	Fired on Bolt Closing	Concern	278624	F	
7875	700	26287	3006 SPRG	29-Nov-04	N	s	21-Aug-12	5-Sep-12	Fired on Safe Release	Could Not Duplicate Concern	280910	F	Per Ilion - Quote to repair at a discount
7876	700	n/a	3006 SPRG	1-Apr-72	N	s	22-Aug-12	22-Aug-12	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	279447	F	Replace TPA, clean, test at BLSM price
7877	700	n/a	3006 SPRG	1-Jun-76	N	s	27-Aug-12	22-Aug-12	Fired on Safe Release	Improper Maintenance	278087	F	Per Ilion, replace TPA, clean, test at BLSM price
	740	1,94	3000000000	230.70				ee ring se	The distance includes	Improper Assembly by	2,000,	Ť	Tear or dearn price
7878	870	25077	12 GA.	2-Mar-12	N	S	22-Aug-12	6-Sep-12	Defective Parts	Factory	278168	F	Per Ilion, repair no charge
7880	700	84178	30-06 SPG	3-Dec-10	N	s	23 Aug 12	22 Aug 12	Fired on Safe Release	Could Not Duplicate	279293	F	Per Ilion, replace TPA, check over, test fire to restore confidence in rifle at no charge
7880	/00	041/0	30-06 SPG	3-Dec-10	N	3	22-Aug-12	22-Aug-12	Fired on Sale Release	Concern	2/9293	- 1	Replace TPA, clean, test at
7881	700	n/a	270 WIN	21-May-81	N	s	22-Aug-12	22-Aug-12	Fired With Safe ON	Improper Maintenance	279213	F	
7883	700	n/a	3006 SPRG	18-Oct-79	N	s	22-Aug-12	22-Aug-12	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	279470	F	Replace TPA, clean, test fire at BLSM program price
7884	700	n/a	3006 SPRG	1-Oct-71	N	s	22-Aug-12	22-Aug-12	Fired on Bolt Opening	Could Not Duplicate Concern	279273	F	Replace TPA, clean, test at BLSM program price
7887	700	85336	3006 SPRG	18-Jun-12	N	s	24-Aug-12	24-Aug-12	Fired on Bolt Closing	Could Not Duplicate Concern	279687	F	To restore confidence in rifle, will replace TPA, check over and test at no charge
7888	597	80866	22 LR	4-May-11	N	5	24-Aug-12	24-Aug-12	Fired on Bolt Closing	Could Not Duplicate Concern	279231	F	Check over completely, repair as needed at no charge
7893	700	n/a	3006 SPRG		N	s	28-Aug-12	28-Aug-12	Fired on Safe Release	Could Not Duplicate Concern	280100	F	Replace TPA, clean and test under BLSM program price, repair as needed
7895	1187	29882	12 GA	1-Feb-90	N	5		29-Aug-12	Went Automatic	Altered Adjustments or Components	280127	F	Check over completely, repair as needed at 1/2 normal cost as goodwill
7897	700	25771	270 WIN	28-Feb-90	N	5	30-Aug-12	30-Aug-12	Fired With Safe ON	Could Not Duplicate Concern	280159	F	Per Ilion, offer to replace TPA clean, test at 1/2 normal cost
7900	700	25801	17 REM	22-Apr-90	N	s	31-Aug-12	31-Aug-12	Fired on Bolt Closing	Altered Adjustments or Components	280583	F	Per Ilion, replace TPA, clean, test at 1/2 normal cost
7906	660	n/a	308 WIN	1-Sep-69	Υ	s	4-Sep-12	20-Sep-12	Fired on Bolt Closing	Altered Adjustments or Components	282763	F	Per Ilion, replace TPA, clean, test under recall at no charge
7908	700	n/a	222 REM MA	1-Jul-63	N	s	5-Sep-12	5-Sep-12	Fired With Safe ON	Altered Adjustments or Components	280875	F	
7909	700	26023	222 REM	28-Oct-97	N	s	5-Sep-12	5-Sep-12	Fired on Safe Release	Altered Adjustments or Components	280829	F	Per Ilion, offer to replace TPA clean, test fire at 1/2 normal cost

7913	700	84207	308 WIN	10-Jun-09	N	S	7-Sep-12	7-Sep-12	Fired on Bolt Closing	Could Not Duplicate Concern	280643	F	To restore confidence in rifle will replace TPA, check over and test fire at no charge
7927	700	n/a	3006 SPRG	1-Mar-84	N	S	11-Sep-12	21-Sep-12	Fired on Bolt Closing	Improper Maintenance	282932	F	Per Ilion - Quote to repair
7922	700	85471	308 WIN	11-Jun-10	N	s	12-Sep-12	12-Sep-12	Fired on Bolt Closing	Could Not Duplicate Concern	281653	F	To restore confidence in rifle, will replace TPA, check over, test at no charge
7923	700	25793	3006 SPRG	1-Oct-84	N	s	12-Sep-12	12-Sep-12	Safety not working properly	Improper Maintenance	281814	F	Can offer to replace TPA, clean, test at 1/2 normal cost
7924	R-25	60032	308 WIN	28-Apr-09	N	s	12-Sep-12	12-Sep-12	Fired on Bolt Closing	Could Not Duplicate Concern	281742	F	
7925	Handi-Rifle	72532	44 REM MAG	26-Aug-11	N	PD/S	12-Sep-12	19-Sep-12	Light Trigger Pull	Broken or Missing Parts	282564	F	Per Ilion - Repair @ n/c - warranty
7926	600	n/a	308 WIN	1-Apr-77	Y	s	12-Sep-12	3-Oct-12	Fired on Safe Release	Altered Adjustments or Components	284053	F	Per Ilion, can offer to replace TPA at 1/2 normal cost.
7928	597	26550	22 LR	7-Apr-99	N	PD/S	12-Sep-12	2-Nov-12	Fired Out of Battery	Other - Unspecified or Undetermined - Firearms	286201	F	Replace with #26550
7929	700	n/a	3006 SPRG	1-Sep-70	N	S	13-Sep-12	13-Sep-12	Fired on Bolt Closing	Improper Maintenance Could Not Duplicate	281823	F	Replace TPA, clean and test at BLSM program price Per Ilion, replace TPA, clean,
7930	700	n/a	270 WIN	1-Mar-84	N	s	13-Sep-12	13-Sep-12	Fired on Safe Release		281976	F	
7931	597	26550	22 LR	28-Apr-11	N	S	13-Sep-12	13-Sep-12	Delayed Firing - Firearms	Altered Adjustments or Components	281948	F	
7932	597	26513	22 LR	1-Jun-09	N	s	13-Sep-12	13-Sep-12	Fired Out of Battery	Other - Unspecified or Undetermined - Firearms	281826	F	Per Ilion, check over completely, repair as needed at no charge
7944	700	27476	270 WIN	20-Jul-99	N	S	17-Sep-12	17-Sep-12	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	282314	F	Per Ilion - Quote to repair
7946	700	n/a	308 WIN	1-Apr-67	N	S	17-Sep-12	27-Sep-12	Fired on Bolt Closing	Improper Maintenance	283581	F	
7948	700	n/a	308 WIN	1-Sep-69	N	s	18-Sep-12	4-Oct-12	Fired on Safe Release	Could Not Duplicate Concern	284229	F	Can offer to replace TPA, clean, test at BLSM price
7951	700	27482	300 WIN MA	29-Jul-01	N	5	20-Sep-12	20-Sep-12	Fired on Bolt Closing	Improper Maintenance	282516	F	Per Ilion, replace TPA, clean and test fire at 1/2 cost
7952	700	25787	243 WIN	29-Aug-87	N	S	20-Sep-12	20-Sep-12	Other - Firearms	Needs Updated Parts	282504	F	Per Ilion, replace TPA, check over and test fire under sear cam recall at no charge
7954	700	n/a	243 WIN	1-Nov-71	N	s	20-Sep-12	3-Oct-12	Fired on Safe Release	Could Not Duplicate Concern	284078	F	Per Ilion - Quote to repair under BLM
7955	597	26550	22 LR	29-Jan-01	N	S	21-Sep-12	21-Sep-12	Fail to Fire	Could Not Duplicate Concern	282930	F	
7956	700	n/a	3006 SPRG 7MM REM	1-May-83	N	s	21-Sep-12	21-Sep-12	Improper Safety Design	Improper Maintenance	282931	F	Replace TPA, clean and test at 1/2 cost Per Ilion - Quote to repair
7959	700	n/a	MA	9-May-77	N	s	21-Sep-12	4-Oct-12	Fired on Bolt Closing	Improper Maintenance	284269	F	under BLM
7957	700	26939	338 WIN MA	13-Apr-95	N	s	21-Sep-12	29-Dec-13	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
7963	700	25777	7MM MAG	12-Dec-89	N	s	24-Sep-12	23-May-13	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam

	15000000	100,000,000	70109/177771	1-11 STEERANDS		700	Secretary on the	2000000000000	A PORT OF THE PROPERTY.	Could Not Duplicate	0.004000		LANGE PURKEN FRANKLISSENSE
7966	40-XB	27225	308 WIN	13-Apr-09	N	S	25-Sep-12	26-Oct-12	Fired on Bolt Closing	Concern	287031	F	
			71.41.6574.										Can offer to replace TPA,
2022	700	212	7MM REM	22 14 00			20.0 12	20.0 12	First on Coto Datases	Could Not Duplicate	202424		clean, test at BLSM program
7972	700	n/a	MA	22-Mar-80	N	S	26-Sep-12	26-Sep-12	Fired on Safe Release	Concern	283421	F	price
			7MM-08							Could Not Duplicate			Per Consumer Service Dept.
7973	700	27485	REM	19-Jun-01	N	s	26-Sep-12	27-Sep-12	Fired on Bolt Closing	Concern	283538	r	Replace TA @ n/c - goodwil
1313	700	27403	7MM REM	13 7011 01	1.4	-	EO SEP AE	er Jep at	The off bott closing	Concern	203330		Per Ilion - Quote to repair
7975	700	n/a	EX	23-Jul-79	N	s	26-Sep-12	27-Sep-12	Fired on Safe Release	Improper Maintenance	283543	F	under BLM
			7MM REM			-	10 000 10	L. Gop II		Altered Adjustments or	200010	1	Per Ilion - Quote to repair
7976	700	n/a	MA	1-Oct-71	N	s	26-Sep-12	26-Sep-12	Fired on Bolt Closing	Components	283221	F	under BLM
											7033337113		Replace TPA no charge as
									Unexplained	Could Not Duplicate			goodwill to restore
7977	1187	n/a	12 GA	22-May-12	N	PD/S	26-Sep-12	30-Nov-12	Discharge Safe ON	Concern	286125	F	confidence
										Other - Unspecified or			
									Ammunition	Undetermined -			
7980		n/a	270 WIN		N	PI/S	26-Sep-12	12-Nov-12	Exploded	Ammunition	n/a	Α	Lonoke replaced ammo
										4			
conse			0.0000000000000000000000000000000000000			4.6				Altered Adjustments or			Replace TPA, clean and test
7978	700	n/a	270 WIN	1-Mar-84	N	S	27-Sep-12	27-Sep-12	Fired on Safe Release	Components	283401	F	fire at 1/2 normal cost
										Could Not Duplicate			
7990	700	84370	223 REM	28-Jan-09	N	S	27-Sep-12	15-Oct-12	Fired on Safe Release	Concern	285297	F	Per Ilion - Replace TA @ n/o
													and the second s
											*******		Per Ilion, replace TPA, checi
7984	700	27572	50 CAL	25-Oct-97	Υ	S	1-Oct-12	1-0ct-12	Fired on Safe Release	As received Follows Down	283678	F	
													Per Release - repair firearm
		200							Safety not working	***********			@ n/c. Refund for vet bills
7985	Para GI45	n/a	45 ACP		N	PI/S	1-Oct-12	18-Oct-12	properly	As received Follows Down	n/a	F	\$3,479.77
									Unexplained				
									Discharge - No	***************************************			n to the way
7007	700	wh	24214/81	* * * * * * * * * * * * * * * * * * * *			20412	20-112	Mention of Safety	Altered Adjustments or	202067		Replace TPA, clean and test
7987	700	n/a	243 WIN 7MM REM	1-May-67	N	S	2-Oct-12	2-Oct-12	Position	Components	283967	F	
7992	700	25777	MA	18-Jan-96	N	s	3-Oct-12	3-Oct-12	Fired on Safe Release	Altered Adjustments or Components	284011	F	Per Ilion - Quote to repair @ a discount
7992	700	23111	19164	10-1011-30	14	3	3-001-12	3-001-12	Fired on sale nelease	Components	204011	F	auscount
			338 WIN										Repaired @ n/c - Consumer
7994	700	29696	MA	3-Mar-97	N	s	3-Oct-12	3-Oct-12	Fired on Bolt Closing	Improper Maintenance	284097	E	Serv. Dept. removed charge
7224	700	23030	100	3 17(01 37	- 14	-	J OUT IL	J OCT AL	The a on boil closing	Could Not Duplicate	20103)	T.	Per Ilion - Quote to repair @
7995	700	25793	270 WIN	14-Jan-02	N	S	3-Oct-12	3-Oct-12	Fired on Bolt Closing	Concern	284140	F	a discount
,,,,,,			300 H&H			-			Delayed Firing -	Could Not Duplicate	20.12.12	Ť	Per Ilion - Quote to repair @
7999	700	n/a	MA	1-May-83	N	s	4-Oct-12	4-Oct-12	Firearms	Concern	284294	F	a discount
						-		1.001.00	77.1.44.7.75	Could Not Duplicate		1	Per Ilion - Replace TA & test
8001	700	84467	308 WIN	2-Jun-10	N	5	4-Oct-12	4-Oct-12	Fired on Safe Release		284361	F	warranty
8004	Ruger .22	n/a	22		N	5	4-Oct-12	4-Oct-12	Blowback in Face	Other - Unexamined	n/a	A	Lonoke resolved
		-			-				Delayed Firing -	Altered Adjustments or			
8006	700	n/a	243 WIN	1-Apr-69	N	s	5-Oct-12	5-Oct-12	Firearms	Components	284292	F	Per Ilion - Repair under BLN
			7MM-08	A						Altered Adjustments or			Per Ilion - Quote to repair @
8007	7	24741	REM	5-May-98	N	s	5-Oct-12	5-Oct-12	Fired on Safe Release	Components	284515	F	a discount
				- Ci.						250			
										Altered Adjustments or			Per Ilion, replace TPA, clean
8008	700	27478	3006 SPRG	22-Mar-96	N	S	5-Oct-12	5-Oct-12	Fired on Safe Release	Components	284517	F	test at 1/2 normal cost
			27 (1994) (1994)										
			7MM REM			l	l						Per Ilion, replace TPA, clean
8020	700	29692	MA	20-Mar-96	N	S	10-Oct-12	10-Oct-12	Fired on Bolt Closing	Improper Maintenance	284646	F	test fire at 1/2 normal cost
										Altered Adjustments or			Per Ilion, replace TPA, clean
8021	700	25793	3006 SPRG	1-Jun-84	N	S	10-Oct-12	10-Oct-12	Fired on Bolt Closing	Components	284997	F	test at 1/2 normal cost
									GGC NOTE TO				
			**********						Unexplained	Altered Adjustments or			Per Ilion, replace TPA, clean
8023	700	n/a	270 WIN	28-Apr-76	N	S		10-Oct-12	Discharge Safe ON	Components	284897		test at BLSM program price

			1							Could Not Duplicate			Replace TPA, clean, test at n
8024	700	n/a	3006 SPRG	2-Feb-81	N	PD/S	10-Oct-12	10-Oct-12	Fired on Bolt Closing	Concern	284940	F	charge as goodwill
8026	700	n/a	3006 SPRG	1-Jun-79	N	s	10-Oct-12	17-Oct-12	Fired on Safe Release	Altered Adjustments or Components	285828	F	Per Ilion, replace TPA, clean test at BLSM program price
8030	700ML	27580	50 CAL	8-Aug-97	Y	5	11-Oct-12	25-Oct-12	Fired on Safe Release	Broken or Missing Parts	286761	F	Per Ilion, connector broken Repair in exchange at no charge
8052	700	n/a	270 WIN		N	PD/S	12-Oct-12	24-Jun-13	Unexplained Discharge - No Mention of Safety Position	Not Examined by Product Service	n/a	F	Gun not returned to Ilion fo
8035	700	n/a	243 WIN	10-Apr-79	N	s	15-Oct-12	15-Oct-12	Fired on Bolt Closing	Altered Adjustments or Components	284998	F	Per Ilion - Quote to repair under BLM
8037	887	82503	12 GA	29-Jun-10	2	s	15-Oct-12	15-Oct-12	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate	285001	F	Per Ilion - Replace TA & test
0037	007	02303	12.00	23-3011-20	- 14	-	13-04-12	13-001-12	7 Catton	Concern	203001	-	G-17C
8038	700	n/a	7MM REM MA	1-Sep-65	N	s	15-Oct-12	26-Oct-12	Fired on Safe Release	Could Not Duplicate Concern	286987	F	Per Ilion, replace TPA, clean, test at BLSM program price
8040	700	27476	270 WIN	18-Mar-97	N	5	15-Oct-12	23-Oct-12	Fired on Safe Release	Could Not Duplicate Concern	286498	F	Per Ilion, replace TPA, clean test at 1/2 normal cost
8041	Llama pistol	n/a	22 LR		N	s	15-Oct-12	6-Mar-13	Ammunition Exploded	Other - Unexamined	n/a	A	Lonoke resolved
8042	1100	25260	20 GA	9-Jul-76	N	S	16-Oct-12	16-Oct-12	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	285444	F	Per Ilion, check over, test fin at 1/2 normal cost
8043	700	27586	50 CAL	5-Sep-97	Y	PI/S	16-Oct-12	16-Oct-12	Fired on Safe Release	Defective Trigger Assembly	285595	F	Per Ilion - Replace TA & clear @ n/c
8044	770	85633	3006 SPRG	17-Feb-10	N	s	16-Oct-12	bearing and	Fired on Safe Release	Could Not Duplicate Concern	285527	F	Per Ilion - Replace TA & test @ n/c
													Per Ilion - Quote to repair at
8045	710	27410	3006 SPRG	25-May-06	Y	S	16-Oct-12	16-Oct-12	Fired on Bolt Closing	Improper Maintenance	285585	F	discount Per Ilion - Quote to repair
8046	700	n/a	3006 SPRG	1-Aug-69	N	S	17-Oct-12	17-Oct-12	Fired on Bolt Closing	Improper Maintenance	285279	F	under BLM
8047	700	25773	3006 SPRG	13-Nov-93	N	S	17-Oct-12	17-Oct-12	Fired on Safe Release	Worn parts or components	285282	F	Per Ilion - Quote to repair @ a discount
8048	700	27094	270 WIN	10-May-10	N	s	17-Oct-12	17-Oct-12	Fired on Safe Release	Could Not Duplicate Concern	285608	F	Per Ilion, replace TPA, check over and test fire at no charge under warranty
8057	700	27140	300 RUM	14-Apr-08	N	s	18-Oct-12	18-Oct-12	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	285839	F	Per Ilion, offer to replace TPA clean, test fire at 1/2 normal cost
8058	700	84463	338 LAPUA	30-Mar-12	N	s	18-Oct-12	18-Oct-12	Fired on Bolt Closing	Could Not Duplicate Concern	285885	F	Per lion: Repair at no charge
8059	700	25739	308 WIN	28-Mar-07	N	5	18-Oct-12	18-Oct-12	Fired on Safe Release	Could Not Duplicate Concern	285931	F	Per Ilion, will replace TPA, check over and test at no charge
8061	700	n/a	7MM REM MA	3-Jul-75	N	s	18-Oct-12	18-Oct-12	Unexplained Discharge Safe ON	Improper Maintenance	285970	F	Per Ilion, replace TPA, clean test at BLSM program price
8067	700	n/a	7MM REM MA	5-Dec-80	N	s	19-Oct-12	19-Oct-12		Altered Adjustments or Components	286029		Per Ilion, replace TPA, clean test at BLSM program price
8075	700	n/a	3006 SPRG	1-Feb-71	N	5	22-Oct-12	2000 100	Fired on Bolt Closing	Could Not Duplicate Concern	288116	F	Per Ilion - Quote to repair

										Could Not Duplicate		1.0	Per Ilion, offer to replace TPA
8072	700	26989	3006 SPRG	15-May-98	N	S	23-Oct-12	23-Oct-12	Fired on Safe Release	Concern	286019	F	
										STOREST STATE OF THE			Per Ilion, offer to replace TP/
		26813458	V.000-000-000-000-0	1000 S000 NO-005000	8857.7		**************************************			Could Not Duplicate			clean and test fire at 1/2
8077	700	25711	308 WIN	8-Jan-07	N	S	24-Oct-12	24-Oct-12	Fired on Bolt Closing	Concern	286297	F	
										2=32255 SEE NO. 2			To restore confidence in rifle
response a		55,400,600	1-1-0-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1							Could Not Duplicate			will replace TPA, check over
8080	700	84176	243 WIN	25-Mar-10	N	S	25-Oct-12	25-Oct-12	Fired on Safe Release	Concern	286796	F	
										Could Not Duplicate			Per Ilion - Quote to repair
8081	700	n/a	308 WIN	1-Aug-73	N	S	25-Oct-12	25-Oct-12	Fired on Safe Release	Concern	286783	F	under BLM
										Altered Adjustments or		100	Per Ilion - Quote to repair
8082	700	n/a	270 WIN	1-May-75	N	S	25-Oct-12	25-Oct-12	Fired on Safe Release	Components	286826	F	under BLM
									GW New W	22 2 2 2			
0.000		V			045.57		C-0.001 NO 100YO V		Unexplained	Other - Unspecified or			a dispersional annual de morale
8086	770	85637	243 WIN	13-Aug-08	N	5	26-Oct-12	16-Nov-12	Discharge Safe ON	Undetermined - Firearms	286984	F	Refunding for rifle
										ABSTRACT III			
		6550	100000000000							Could Not Duplicate		17.50	Per Ilion, replace TPA, clean
8087	600	n/a	222 REM	1-Mar-74	Y	5	26-Oct-12	26-Oct-12	Fired on Safe Release	Concern	286957	F	test at BLSM program price
									Unexplained				
									Discharge - No	02/10/09/20/20/20/20			Replace TPA to restore
									Mention of Safety	Could Not Duplicate			confidence, clean, test no
8088	770	85656	3006 SPRG	31-Jul-09	N	5	26-Oct-12	8-Nov-12	Position	Concern	286965	F	and the second second
													Per Ilion, to restore
													confidence in rifle will replac
									Delayed Firing -	Could Not Duplicate			TPA, clean and test at no
8089	770	85633	3006 SPRG	18-Oct-11	N	S	26-Oct-12	26-Oct-12	Ammunition	Concern	286967	F	
		L.							Lanca and the same of the same	Altered Adjustments or			Per Ilion - Quote to repair @
8091	700	26196	204 RUGER	20-Mar-06	N	S	26-Oct-12	27-Nov-12	Fired on Safe Release	Components	289893	F	a discount
										27 CZ-WINE			Per Ilion, can offer to replace
			l							Altered Adjustments or			TPA, clean and test at 1/2
8093	700	25771	270 WIN	19-Sep-89	N	5	29-Oct-12	29-Oct-12	Fired on Safe Release	Components	287197	F	normal cost
										Altered Adjustments or			Per Ilion, replace TPA, clean,
8095	700	n/a	3006 SPRG	20-Aug-76	N	S	29-Oct-12	29-Oct-12	Fired on Safe Release	Components	287111	F	test at BLSM program price
													Per Ilion, check over and
8096	700	27582	54 CAL	4-Jun-96	Υ	S	29-Oct-12	29-Oct-12	Fired on Safe Release	Broken or Missing Parts	287196	F	repair TPA at no charge.
		l'							Fired on Bolt	Could Not Duplicate			Per Ilion - Quote to repair
8054	700	n/a	3006 SPRG	1-Nov-72	N	S	30-Oct-12	30-Oct-12	Opening	Concern	287490	F	under BLM
													Per Ilion, to restore
													confidence in rifle, offer to
			7MM08							Could Not Duplicate			replace TPA, clean, test at 1/
8102	7	24786	REM	9-Jan-98	N	S	31-Oct-12	31-Oct-12	Fired on Bolt Closing	Concern	287645	F	
8107	522	29792	22 LR	25-Oct-95	Υ	S	1-Nov-12	9-Nov-12	Went Automatic	Broken or Missing Parts	287712	F	Return as received
8110	Benelli	n/a	12 GA		N	5	1-Nov-12	6-Mar-13	Case Separation	Other - Unexamined	n/a	A	Lonoke resolved
													Per Ilion, offer to replace TPA
										Could Not Duplicate			clean, test at BLSM program
8111	700	n/a	270 WIN	1-Feb-71	N	5	2-Nov-12	2-Nov-12	Fired on Bolt Closing	Concern	287526	F	price
													Per Ilion, can offer to replace
									and the state of t	Could Not Duplicate			TPA, clean, check over at 1/2
8114	700	27580	50 CAL	7-Apr-97	Y	S	2-Nov-12	2-Nov-12	Fired on Safe Release	Concern	287717	F	normal cost
										Altered Adjustments or			Per Ilion, replace TPA, clean
8116	700	20000	6MM REM	1-Apr-72	N	S	5-Nov-12	5-Nov-12	Fired on Safe Release	Components	288079	F	test at BLSM program price
										Could Not Duplicate			Per Ilion - Replace TA & test
8118	700	84177	270 WIN	23-Jul-12	N	S	5-Nov-12	26-Nov-12	Fired on Safe Release	Concern	290108	F	
									Ammunition		97,000,000		
1,02980	597	n/a	17 HMR	24-Mar-03	N	S	5-Nov-12	3-Dec-12	Exploded	Other - Unexamined	290054	F	Convert to .22 WMR
8120					10		1					- 1	
8120												100	
8120										Could Not Duplicate			Per Ilion, replace TPA, clean,

8123	870	25568	12 GA	30-Jan-02	N	PI/S	6-Nov-12		Fired With Safe ON	Other - Unexamined		F	Gun not returned to Ilion for exam
										Altered Adjustments or			Replace TA, remove bolt loc & test @ n/c - goodwill
8127	700	n/a	3006 SPRG		N	PD/S	7-Nov-12	12-Doc-12	Fired on Bolt Closing	Components	290673	F	gesture
0121	700	ilya	7MM REM		14	FUIS	7-1400-12	13-060-12	Fired on Boit Closing	components	2300/3	r	Per Release - Replace
8125	770	85654	MA	15-Sep-11	N	PI/S	7-Nov-12	7-Jan-13	Defective Parts	Sent in for Evaluation	292398	F	w/84187 in exchange
UALJ	770	03034	100	TO OTHER	1.4	1113	7-1404-42	7-2411-2-3	Derective Forts	Altered Adjustments or	272330	·	Per Ilion - Quote to repair
8128	700	n/a	6MM REM	1-Jun-70	N	s	8-Nov-12	8-Nov-12	Fired on Bolt Closing	Components	288463/461/465/460	F	under BLM
		.,,,		2331170				2.1141.24	Unexplained Discharge - No	ACCOMPANY NEEDS			7410(7410(700))
8129	Versa Max	81048	12 GA	28-Feb-12	N	S	8-Nov-12	8-Nov-12	Mention of Safety Position	Could Not Duplicate Concern	288443	F	Per Ilion - Repair as needed a test @ n/c
8129	A6129 IAI9X	01040	12 GA	28-FED-12	IN	3	8-1VOV-12	8-1VOV-12	Position	Altered Adjustments or	288443	r	Per Ilion - Quote to repair
8130	700	n/a	3006 SPRG	1-Apr-73	N	S	8-Nov-12	8-Nov-12	Fired on Safe Release	Components	288471	F	under BLM
0130	700	11/4	3000 3FNG	1-Apr-75	14	3	0-NOV-12	0-1404-15	Fired on Sale Nelease	components	2004/1	-	Per Ilion, replace TPA, clean
8132	700	n/a	270 WIN		N	S	8-Nov-12	8-Nov-12	Fired on Safe Release	Could Not Duplicate Concern	287200	F	and test at BLSM program
	11. 1.4.1											П	
										Could Not Duplicate			Replace TPA, test no charge
8133	770	85633	3006 SPR	5-Mar-12	N	PI/S	8-Nov-12	10-Dec-12	Fired on Safe Release	Concern	290494	F	to restore confidence
												Ĥ	Per Ilion - Quote to repair @
8136	700	27474	243 WIN	12-Aug-98	N	S	9-Nov-12	9-Nov-12	Fired on Safe Release	Improper Maintenance	288683	F	a discount
										Altered Adjustments or			Replace TA under recall @
8143	600	n/a	222 REM	1-Apr-64	Y	S	12-Nov-12	30-Nov-12	Defective Parts	Components	290773	F	n/c
	100000								Unexplained Discharge - No Mention of Safety				Refunding \$339.19 for
8149	Excel Auto	72350	12 GA	2-Jun-10	N	s	12-Nov-12	7-Dec-12	Position	Sent in for Evaluation	290511	F	firearm
0145	Execinate	72330	11 00	23411 20		-	11 1101 11	, pec in	roadon	SCITCITI FOI EVENUETON	230311	Ė	No product sent for
8146	700	n/a	243 WIN		N	S	12-Nov-12	21-May-13	Fired on Safe Release	Other - Unexamined	n/a	F	inspection
						120				Could Not Duplicate	27257		Per Ilion - Replace TA & test
8151	700	84370	223 REM	23-Mar-09	N	5	13-Nov-12	13-Nov-12	Fired on Bolt Closing	Concern	288901	F	@ n/c
8152	742	n/a	3006 SPRG	1-Jul-70	Y	s	13-Nov-12	13-Nov-12	Fired With Safe ON	Could Not Duplicate Concern	289033	F	Per Ilion - Quote to check over & test at 1/2 normal cost
					·								Per Ilion - Replace TA, clean I
8161	600	n/a	243 WIN	1-Jun-67	Y	S	13-Nov-12	11-Dec-12	Defective Parts	Sent in for Evaluation	291919	F	test under recall
8165	PARDNER	72096	12 GA	7-Feb-11	N	s	15-Nov-12	15-Nov-12	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	289269	F	Per Ilion, check over completely. Repair as needed at no charge under warranty
	Z.828902		~ 33250 Mile	=8-530000000		11.0				Altered Adjustments or			Per Ilion - Quote to repair @
8166	541	29824	22 RF	2-Mar-90	Υ	5	15-Nov-12	15-Nov-12	Fired on Safe Release	Components	289334	F	1/2 normal cost
						2			1 11 15 2000	Not Examined by Product			Gun not returned to Ilion for
8169	7	20000	308 WIN		N	S	15-Nov-12	5-Jun-13	Fired on Safe Release	Service		F	exam
8170	600	n/a	243 WIN	1-Jul-74	γ	5	16-Nov-12	16-Nov-12	Fired on Safe Release Delayed Firing -	Could Not Duplicate Concern	289051	F	Per Ilion - Replace TA under recall @ n/c
8171	700	25791	270 WIN	7-Nov-89	N	s	16-New-17	16-Nov-12	Firearms	Improper Maintenance	289516	F	Ilion repaired at no charge
01/1	700	23731	270 44114	7-1404-03	14	3	10-1404-15	10-1404-12	Filedina	Could Not Duplicate	207310		To restore confidence -
8177	700	85435	308 WIN	19-Apr-12	N	PI/PD/S	19-Nov-12	27-Dec-12	Fired With Safe ON	Concern	292419	F	replace TA, clean & test
		1								Altered Adjustments or			Repair @ n/c - goodwill
8179	7600	n/a	270 WIN	1-Mar-82	N	PD/S	19-Nov-12	14-Dec-12	Fired on Bolt Closing	Components	291209	F	gesture
	Second.		Catholic Addition	52.55 T. 12.51		9.7			60 KL MENCEK	Could Not Duplicate	50502550		Per Ilion - Quote to repair
8184	700	n/a	308 WIN	1-Aug-71	N	S	21-Nov-12	9-Jan-13	Fired on Safe Release	Concern	295446	F	under BLM
									Unexplained Discharge - No Mention of Safety	Altered Adjustments or			Per Ilion, replace TPA, clean
8187	660	n/a	222 REM	1-Jun-68	Y	S	26-Nov-12	26-Nov-12	Position	Components	289964	F	test at no charge under reca
			7MM REM							Could Not Duplicate		П	Per Ilion, replace TPA, clean,
8188	700	n/a	MA	23-Mar-79	N	s	20 11-1-12	20.11-12	Fired on Bolt Closing	Concern	289653	F	test at BLSM price

8189	700	85435	308 WIN	18-Jul-12	N.	s	26-Nov-12	26-Nov-12	Fired on Bolt Closing	Could Not Duplicate Concern	289945	F	Per Ilion, replace TPA, check over and test at no charge
8190	700	n/a	243 WIN	1-Sep-71	N	S	26-Nov-12	26-Nov-12	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	290142	F	Per Ilion, replace TPA, clean test at BLSM program price
8191	710	27416	243 WIN	3-Mar-06	N	S	26-Nov-12	26-Nov-12	Jar-Off Safe OFF	Could Not Duplicate Concern	290112	F	Per Ilion, can offer replace TPA, clean and test fire with slave mag at 1/2 normal cos
8192	700	n/a	25-06		N	s	26-Nov-12	26-Nov-12	Fired on Safe Release		n/a	F	Customer had local gunsmith change the trigger
8196	870	81221	20 GA	21-Aug-09	N	s	27-Nov-12	27-Nov-12	Fired With Safe ON	Could Not Duplicate Concern	289274	F	Per lion: Repair at no charge
8197	700	n/a	3006 SPRG	1-Jul-68	N	s	27-Nov-12	27-Nov-12	Fired on Bolt Closing	Could Not Duplicate Concern	289855	F	Per Ilion, replace TPA, clean, test at BLSM program price
8199	600	n/a	6MM REM	20-Jun-75	Υ	s	27-Nov-12	27-Nov-12	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	289966	F	Per Ilion, replace TPA, clean, test at no charge under reca
8200	700	27173	270 WSM	21-Jun-07	N	S	27-Nov-12	27-Nov-12	Fired on Safe Release		289617	F	Per Ilion, to restore confidence will replace TPA, clean and test fire no charge
8202	SPT 78	26164	3006 SPRG	1-Jul-84	N	s	27-Nov-12	27-Nov-12	Fired on Safe Release	Altered Adjustments or Components	290036	F	Per Ilion - Quote to repair @ 1/2 normal cost
8211	7	86052	308 WIN	2-Aug-07	N	5			Fired on Safe Release	Could Not Duplicate	290255	F	Per Ilion, will replace TPA, check over and test at no charge as goodwill
8219	700	n/a	308 WIN	1-May-78	N	PI/S	27-Nov-12	28-Dec-17	Fired on Bolt Closing	Improper Maintenance	293160	F	Perform BLM @ n/c - goodwill gesture
8203	870	n/a	12 GA	1-Jan-00	N	S		22-May-13	Jamming/Feeding	Other - Unexamined	n/a	F	No product sent for inspection
		100						12					Product not sent for
8205	700 Mossberg	n/a	25-06 REM		N	S	27-Nov-12	21-May-13	Fired With Safe ON	Other - Unexamined	n/a	F	Inspection No Additional Info. From
8208	590 Flex	n/a	12 GA		N	s	27-Nov-12	29-Dec-13	Case Separation	Other - Unexamined	n/a	F	Lonoke
8231	700	n/a	3006 SPRG	25-Mar-76	N	s	27-Nov-12	16-Jan-13	Fired on Safe Release	Altered Adjustments or Components	296691	F	Per Ilion - Quote to repair under BLM
8270	870	81282	12 GA	23-Aug-12	N	s	27-Nov-12		Warning Inadequate Firearm	Defective Parts	n/a		Replacing scopes with 2 Simmons ProHunter scopes
8210	105	90689	12 GA	16-Mar-09	N	s	28-Nov-12	28-Nov-12	Fired on Bolt Closing	Could Not Duplicate Concern	289207	F	Per Ilion, repair as needed and test at no charge
8212	710	27410	3006 SPRG	2-Jun-04	N	5	28-Nov-12	28-Nov-12	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	290249	F	Per Ilion, check over completely, repair as needed at no charge
8213	700	n/a	7MM REM MA	7-Dec-81	N	5	28-Nov-12	28-Nov-12	Improper Safety Design	Could Not Duplicate Concern	290218	E	Per Ilion, replace TPA, clean, test at BLSM program price
		27408							Unexplained Discharge - No Mention of Safety			F	
8215	710	27408	270 WIN	3-Dec-01	Y	S	28*NOV-12	13-D∞-12	Position	As received Follows Down  Not Examined by Product	290386	-	Replacing with 770 Gun not returned to Ilion for
8216	700	25791	270 WIN	26-Feb-02	N	PD/S	28-Nov-12	7-Jun-13	Fired on Safe Release		n/a	F	exam

									Fired on Bolt				No product sent for
8221	700	n/a	n/a		N	S	28-Nov-12	23-May-13	Opening	Other - Unexamined	n/a	F	inspection
-25.000			250400021220000	SEA 5 355		- 65	15039 550		And Alexander	Could Not Duplicate			Per Ilion - Quote to repair @
8235	710	27410	3006 SPRG	1-Dec-05	Y	S	28-Nov-12	7-Jan-13	Fired on Bolt Closing	Concern	294933	F	1/2 normal cost
													Per Ilion - Quote to repair
8222	700	n/a	3006 SPRG	1-Jun-74	N	S	29-Nov-12	29-Nov-12	Fired on Safe Release	Improper Maintenance	290646	F	under BLM
20223	700	0.92	7MM REM	520450210	1201	12	120000000		Delayed Firing -		2000000	12	
8223	700	n/a	MA	1-0ct-77	N	5	29-Nov-12	29-Nov-12	Firearms	Improper Maintenance	290468	F	Per Ilion - Quote under BLM
		- 2							Safety not working	Altered Adjustments or			Per Ilion - Quote to repair
8224	700	n/a	308 WIN	1-0ct-72	N.	S	29-Nov-12	29-Nov-12	properly	Components	290485	F	
8227	Excel Auto	72350	12 GA	5-Jun-10	N	s	20 Nov. 17	20 Nov. 12	Fired on Bolt Closing	Could Not Duplicate Concern	290489	F	Per Ilion - Check over & repa @ n/c
8221	Excel Auto	72330	12 GA	2-1011-10	IN	3	23-MOA-15	29-NOV-12	Fired on Boit Closing	Concern	290489	F	Per Ilion, repair TPA, clean,
8239	700	n/a	3006 SPRG	27-Aug-76	N	s	30-Nov-12	30-Nov-12	Safety not working properly	Altered Adjustments or Components	290583	F	test at no charge per M.
													Per Ilion, replace TPA, check
										Could Not Duplicate			test to restore confidence in
8240	700	27167	3006 SPRG	5-Oct-06	N	5	30-Nov-12	30-Nov-12	Fired on Safe Release	Concern	290648	F	rifle at no charge as goodwi
2222	2222	11000	202222	350000000000000000000000000000000000000	550	100	12272000754	50.000.000		Altered Adjustments or	9,137,000,00		Upgrade to Model 7600 at
8242	760	n/a	280 REM	1-Feb-64	Υ	S	30-Nov-12	14-Dec-12	Fired on Bolt Closing	Components	290653	F	special price
													Decilion and a TD:
0242	700	225.00	FOCAL	70465			30 Nov. 12	20 Nov. 47	Florid on Code Date	Bankan on Missian Desir	200720	-	Per Ilion, replace TPA, checi
8243	700	27580	50 CAL	7-Oct-96	Υ	S	3U-NOV-12	3U-NOV-12	Fired on Safe Release	Broken or Missing Parts	290738	F	over, clean at no charge
										Altered Advistments or			Per Ilion, replace TPA, clean
0244	SPT 78	26164	3006 SPRG	111	Y	s	20 0 12	20 11 12	Fired on Safe Release	Altered Adjustments or	290645	F	
8244	SP1 78	20104	3006 SPRG	14-Jun-86	1	3	30-NOV-12	3U-1VOV-12	Fired on Sale Kelease	Components Could Not Duplicate	290645	- 1	
8250	700	27573	50 CAL	25-Jul-02	N	s	3-Dec-12	3.Doc.13	Fired on Safe Release	Could Not Duplicate Concern	290887	F	Per Ilion - Quote to repair at 1/2 normal cost
6230	.700	21313	30 CAL	25-101-02	14	3	3-060-12	3-060-12	rined on sale nelease	Concern	230007	- 1	Per Ilion - Quote to repair @
8251	7	24788	308 WIN	1-Sep-84	N	S	3-Dec-12	3-Dec-12	Fired on Safe Release	Improper Maintenance	290895	F	1/2 normal cost
0631	-	24700	300 1111	1-3cp-04	- 14	-	3-000-12	3-000-12	Filed Oil Sale Nelease	improper maintenance	230033	- 1	Per Ilion - Replace TA, clean 8
8252	600	n/a	243 WIN	1-Apr-74	Y	5	3-Dec-12	3-Dec-12	Fired on Safe Release	Broken or Missing Parts	290937	F	test under recall
		74.4				_	5.000.40	5.0.0.00	, , , , , , , , , , , , , , , , , , , ,	and the same of th		- 1	Per Ilion, repair as needed a
8253	CARBON 15	90689	223 REM	20-Jan-12	N	s	3-Dec-12	3-Dec-12	Went Automatic	Broken or Missing Parts	291033	F	
-		11111111111		***************	-								Per Ilion - Quote to repair @
8255	700	25773	3006 SPRG	6-Jun-96	N	S	3-Dec-12	3-Dec-12	Fired on Safe Release	Improper Maintenance	290963	F	1/2 normal cost
24-233EE				00.000000000000000000000000000000000000			E STANSON AND STAN		er managar makangar men	Could Not Duplicate			Per Ilion, replace TPA, clean
8256	700	27476	270 WIN	31-Mar-03	N	S	3-Dec-12	3-Dec-12	Fired on Safe Release	Concern	291014	F	and test at 1/2 normal cost
													Per Ilion, replace TPA, clean
especial contraction			2744000000	100070-360			605.500		nem annemos	Altered Adjustments or			and test at BLSM program
8257	700	20000	243 WIN	1-Apr-68	N	S	3-Dec-12	3-Dec-12	Fired on Bolt Closing	Components	291072	F	price
			7MM REM				_ =		day come	Altered Adjustments or			Per Ilion, replace TPA, clean
8259	700	25803	MA	1-Aug-85	N	S	3-Dec-12	3-Dec-12	Fired on Bolt Closing	Components	291092	F	test at 1/2 normal cost
									Barrel Burst/Split				
		25.225						***	(Other than	Was a state to the state of the			
8260	1100	25328	12 GA	1-Mar-75	N	PD/S	3-Dec-12	10-Jan-13	Chamber)	Fired While Obstructed	292656	A	
0251	700	-1-	2005 5005	25 8400 20		nn ir	2.044.53	24 ton 42	Fired on Coto Bot	Could Not Duplicate	205577	F	Bolt Lock Modification at n/o
8261	/00	n/a	3006 SPRG	25-May-79	N	PD/S	3-Dec-12	21-Jan-13	Fired on Safe Release	Concern	296677	F	goodwill gesture
			7MM REM										Berlien contact TDA start
8207	710	27412	MA	28-Nov-06	N	s	4-Dec-12	4-Dec-12	Fired on Bolt Closing	Broken or Missing Parts	291130	F	Per Ilion, replace TPA, check over and test at no charge
0207	/10	2/412	IVIA	28-WUV-06	14	3	4-Dec-12	4-Dec-12	Fired on Boil Closing	broken or ivissing Parts	531120	- 1	over and test at no charge
			7MM REM							Altered Adjustments or			Per Ilion, replace TPA, clean
8266	700	n/a	EX EX	27-Apr-79	N	s	4-Dec-12	4-Dec-13	Fired on Safe Release	Components	291206		test at BLSM program price
0200	700	iiya	EA	E/-Apr-/9	14.	3	4-Dec-12	4-Dec-12	rii ed on sale nelease	Components	291200	- +	test at bestyr program price
													Per Ilion, offer to remove,
													tear down and clean TPA an
8267	788	n/a	222 REM	1-May-74	Y	s	4-Dec-12	4-Dec-12	Fired on Safe Release	Improper Maintenance	291241	E	test firear at 1/2 normal cost
				- 111111		-			Tree-of all marie tree-pages				

8268	660	n/a	243 WIN	1-Apr-68	Y	5	4-Dec-12	4-Dec-12	Fired on Safe Release	As received Follows Down	291253	F	Per Ilion, replace TPA, clean and test at no charge under recall
8269	742	n/a	3006 SPRG	1-Aug-72	Y	PD/S	4-Dec-12	18-Jan-13	Fired on Bolt Closing	Sent in for Evaluation	292652	F	Per Release - replace
8273	660	n/a	308 WIN	1-Aug-69	N	5	5-Dec-12	5-Dec-12	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	289613	F	Replace TPA, clean and test
8274	597	26562	22 LR	22-Jul-02	N	s	5-Dec-12	5-Dec-12	Jamming/Feeding issues	Could Not Duplicate Concern	291320	F	Per Ilion, check over completely, repair as needed at no charge
8275	700	20000	308 WIN	1-Jan-72	N	s	5-Dec-12	5-Dec-12	Fired on Bolt Closing	Could Not Duplicate Concern	291311	F	Per Ilion, replace TPA, clean, test at BLSM program price
8276	700	84078	7MM REM MA	13-May-11	N	S	5-Dec-12	5-Dec-12	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	291342	F	Check over completely and safety check and test fire at no charge as goodwill
8279	700	n/a	3006 SPRG	1-Apr-72	N	s	5-Dec-12	5-Dec-12	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	291485	F	Per Ilion, replace TPA, clean, test at BLSM program price
8280	700	n/a	243 WIN	1-Oct-77	N	s	5-Dec-12	5-Dec-12	Fired on Safe Release	Altered Adjustments or Components	291459	F	Replace TPA, clean, test at BLSM program price
8281	700	n/a	270 WIN	22-Aug-77	N	s	5-Dec-12	5-Dec-12	Fired on Safe Release	Altered Adjustments or Components	291484	F	Per Ilion, replace TPA, clean, test at 1/2 normal cost
8282	700	n/a	6MM REM	10-Nov-76	N	s	5-Dec-12	5-Dec-12	Fired on Safe Release	Altered Adjustments or Components	291487	F	Per Ilion, replace TPA, clean, test at BLSM program price
8288		n/a	38 SPC		N	s	6-Dec-12	6-Mar-13	Bullet Lodged in Barrel	Other - Unexamined	n/a	А	Lonoke resolved
8291	700	25771	270 WIN	24-Jul-86	N	s	7-Dec-12	7-Dec-12	Safety not working properly	Could Not Duplicate Concern	290933	F	Per Ilion, replace TPA, clean, test at 1/2 normal cost
8292	700	n/a	308 WIN	1-Jul-73	N	S	7-Dec-12	7-Dec-12	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	290913	F	Replace TPA, clean and test at BLSM program price
8293	700	25807	300 WIN	23-May-06	N	5	7-Dec-12	7-Dec-12	Fired on Bolt Closing	Could Not Duplicate Concern	290922	F	Can offer to replace TPA, clean, test fire at 1/2 normal cost
8294	700	n/a	3006 SPRG	1-Jul-74	N	s	7-Dec-12	7-Dec-12	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	291800	F	Per Ilion, replace TPA, clean and test fire at BLSM program price
8299	700	27357	7MM08 REM	18-Mar-09	N	s	10-Dec-12	10-Dec-12	Fired on Safe Release	Could Not Duplicate Concern	292050	F	To restore confidence in rifle will replace TPA, clean and test at no charge
8300	700	n/a	35 WHELEN	26-Jul-88	N	S	10-Dec-12	10-Dec-12	Fired on Safe Release	Could Not Duplicate Concern	292016	F	Per Ilion, can offer to replace TPA, clean, test at 1/2 norma cost
8301	700	27478	3006 SPRG	27-Aug-98	N	5	10-Dec-12	10-Dec-12	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	291936	F	Per Ilion, replace TPA, clean and test at 1/2 normal cost
8303	700	n/a	8MM REM MA	31-Mar-77	N	S	10-Dec-12	10-Dec-12	Fired on Bolt Opening	Could Not Duplicate Concern	291930	F	Per Ilion, replace TPA, clean, test at BLSM program price

8304	700	27013	280 REM	18-Aug-04	N.	s	10-Dec-12	10-Dec-12	Fired on Bolt Closing	Altered Adjustments or Components	291953	F	Per Ilion, replace TPA, clean, test at 1/2 normal cost
V11.5 (V)										CHARLES CHARLES A STATE AND COMPANIES.			Per Ilion, repair as needed a
8305	770	85630	243 WIN	12-Jan-12	N	S	10-Dec-12	10-Dec-12	Defective Parts	Broken or Missing Parts	291846	F	no charge
			7MM REM						Unexplained Discharge - No Mention of Safety	Could Not Duplicate			Per Ilion, as a gesture of goodwill, replace TPA, check
8306	770	85635	MA	3-Feb-09	N	S	10-Dec-12	10-Dec-12	Position	Concern	291892	F	
-						_				Could Not Duplicate		-	Replace TPA, clean and test
8309	700	25793	3006 SPRG	3-Jun-96	N	S	10-Dec-12	4-Feb-13	Fired on Safe Release	Concern	299070	F	
8312	597	26550	22 LR	26-Oct-00	N	PD/S	10-Dec-12	9-Jan-13	Ammunition Exploded	Other - Unspecified or Undetermined - Firearms	294697	A	Replace rifle w/26550 in exchange
8314	700	n/a	270 WIN		N	PD/S	10-Dec-12	7-Jun-13	Fired on Safe Release	Not Examined by Product Service		F	Gun not returned to Ilion fo exam
									Development of the second	Altered Adjustments or		10	Per Ilion - Quote to repair @
8315	700	25632	280 REM	21-Mar-86	N	S	11-Dec-12	11-Dec-12	Fired on Safe Release	Components	292145	F	1/2 normal cost
8316	700	n/a	243 WIN	1-Dec-74	N	s	11-Dec-12	11-Dec-12	Fired on Safe Release	Altered Adjustments or Components	292079	F	Per Ilion - Quote to repair under BLM
			22-250							Altered Adjustments or			Per Ilion - Quote to repair
8317	700	n/a	REM	12-Dec-77	N	S	11-Dec-12	11-Dec-12	Fired on Safe Release	Components	291992	F	under BLM
535500			201000000000	7000,000,000		4.5				Could Not Duplicate			Per Ilion - Quote to repair
8318	700	n/a	270 WIN	8-Jan-80	N	S	11-Dec-12	11-Dec-12	Fired on Bolt Closing	Concern	292047	F	200000000000000000000000000000000000000
0310	700		200.14/81	4:30E94			11 0 13	11.013	Florida on Bulk Planta	Could Not Duplicate	201005		Per Ilion - Quote to repair
8319	700	n/a	308 WIN	1-Jul-74	N	S	11-Dec-12	11-Dec-12	Fired on Bolt Closing	Concern	291886	F	under BLM
			78.45.400							Could Net Duelloots			Desilies officers contact TO
0270	7	24786	7MM08 WIN	4.755.644					First on Foto Balance	Could Not Duplicate	201022		Per Ilion, offer to replace TPA clean, test at 1/2 normal cos
8320	1:	24/86	7MM REM	1-Jul-84	N	S	11-Dec-12	11-Dec-12	Fired on Safe Release	Concern	291922	- 1	Per Ilion - Quote to repair
8321	700	n/a	MA	1 6 77	N	S	11 0 12	11 Dec 13	Fired on Safe Release	Altered Adjustments or Components	291956	F	
8321	700	nya	IVIA	1-Sep-77	N	3	11-Dec-12	11-000-12	Fired on Sale Release	Components	291936	- 1	Per Ilion - Quote to repair
8322	700	n/a	243 WIN	1-Apr-64	N	s	11-Dec-12	11-Dec-12	Fired on Safe Release	Improper Maintenance	292094	F	
8323	700ML	27572	50 CAL	15-Sep-97	Υ	s	11-Dec-12	11-Dec-12	Fired on Safe Release	Broken or Missing Parts	292133	F	Per Ilion - Repair at n/c
					177								Per Ilion - Quote to repair @
8325	700	29712	3006 SPRG	14-Jul-92	N	S	11-Dec-12	11-Dec-12	Fired on Bolt Closing	Improper Maintenance	292144	F	1/2 normal cost
										Altered Adjustments or			Per Ilion - Quote to repair
8326	721	n/a	270 WIN	1-Apr-52	Y	S	11-Dec-12	11-Dec-12	Fired on Bolt Closing	Components	292135	F	under BLM
										Altered Adjustments or			Per Ilion - Repair under recal
8327	600	n/a	308 WIN	1-Mar-73	Y	S	11-Dec-12	11-Dec-12	Fired on Bolt Closing	Components	292148	F	@ n/c
0.000			200200000000000000000000000000000000000	1000000000		1 55	*C355: *C5		25 St. 180 St. 5	540 2003			Per Ilion - Repair under reca
8328	600	n/a	308 WIN	1-0ct-73	Υ	S	11-Dec-12	11-Dec-12	Fired on Bolt Closing	Improper Maintenance	292187	F	@ n/c
	2000	100	7MM REM							Could Not Duplicate	10000000		Per Ilion - Quote to repair
8329	700	n/a	MA	1-Feb-72	N	S	11-Dec-12	11-Dec-12	Fired on Safe Release	Concern	292178	F	
8332	600	n/a	222 REM	1-Apr-65	Y	s	11-Dec-12	11-Dec-17	Fired on Safe Release	Improper Maintenance	292217	F	Per Ilion - Repair under recal @ n/c
OJJE	000	1.90	EEE NEW	A repriou	•		II Dec II	11 000 12	Theo on bare receive	Could Not Duplicate	EJEEL/	٠,	6.1/4
8336	1187	25339	12 GA	20-Apr-00	N	s	11-Dec-12	28-Dec-12	Fired Out of Battery	Concern	293814	E	Replace w/83620 in exchang
0000	MAN.	KODOO	20.001	LO PIPI CO			AT DCC IL	LO DEC 12	The batter battery	Altered Adjustments or	1.55024	-	Replace TA, clean & test @
8333	700	n/a	243 WIN		N	PD/S	11-Dec-12	8-Jan-13	Fired on Safe Release	Components	293967	F	
						-					3000000	7	To restore confidence -
8334	700	85361	3006 SPRG	8-Nov-07	N	PD/S	11-Dec-12	11-Jan-13	Fired With Safe ON	Could Not Duplicate Concern	294889	F	replace TA, clean & test at n/c
					100000								Per Ilion, replace TPA, clean
			7MM REM							Could Not Duplicate			and test at BLSM program
8337	700	n/a	MA	1-Jun-75	N	5	12-Dec-12	12-Dec-12	Fired on Safe Release	Concern	292301	F	price
	20000	LOS WAY	1505000			3.1			er on the service		325077418		Replace TPA, clean and chec
8339	700	27572	50 CAL	1-Nov-96	Υ	S	12-Dec-12	12-Dec-12	Fired on Safe Release	Broken or Missing Parts	292327	F	over at no charge
		1											

8341	597	26550	22 LR	4-May-98	N	S	12-Dec-12	12-Dec-12	Fired Out of Battery	Other - Unspecified or Undetermined - Firearms	292409	F	Per Ilion, check over completely, repair as needed at no charge
8342	660	n/a	6.5MM REM	1-Feb-68	Y	5		12-Dec-12		Could Not Duplicate Concern	292420	F	Per Ilion, replace TPA, clear and test under recall at no
8392	660	nya	KEIVI	1-1-60-68	1	3	12-060-12	12-060-12	Unexplained	Concern	292420	F	charge.
8343	600	n/a	243 WIN	1-Jun-67	v	s	12 000 12	12-Dec-12	Discharge - No Mention of Safety Position	Transport Majorten and	202423	F	Per Ilion, replace TPA, clean and test at no charge under recall
8343	600	n/a	243 WIN	1-Jun-6/	Υ	2	12-Dec-12	12-Dec-12	Position	Improper Maintenance	292422	- 1	Per Ilion, can offer to replace
8345	700	29709	270 WIN	19-Aug-96	N	s	12-Dec-12	12-Dec-12	Delayed Firing - Firearms	Improper Maintenance	292423	F	TPA, clean and test at 1/2 normal cost
	CONTRACTOR SECURITION OF SECUR	100	20200000	45485×27547		100				Could Not Duplicate			Replace TPA, clean, test at
8347	Mohawk 600	n/a	243 WIN	10-Jan-78	Υ	S	12-Dec-12	11-Feb-13	Fired on Safe Release	Concern	300135	F	
8349	700	n/a	243 WIN	1-Aug-74	N	5	13-Dec-12	13-Dec-12	Fired on Bolt Closing	Improper Maintenance	292572	F	Per Ilion, replace TPA, clean and test at BLSM program price
8350	700ML	27580	50 CAL	11-Apr-97	Υ	s	13-Dec-12	13-Dec-12	Fired on Safe Release	Broken or Missing Parts	292597	F	Per Ilion - Repair @ n/c
0000	70000	27500	300 WIN	22 1401 21	_	-	45 500 46	20.000.20	The on some mercuse	Altered Adjustments or	202007	-11	Per Ilion - Quote to repair @
8352	700	25807	MA	1-Mar-85	N	5	13-Dec-12	13-Dec-12	Fired on Safe Release	Components	292527	F	1/2 normal cost
	27.00									Altered Adjustments or			Per Ilion - Quote to repair
8353	700	n/a	3006 SPRG	1-Aug-71	N	S	13-Dec-12	13-Dec-12	Fired on Safe Release	Components	292619	F	under BLM
8348	700	n/a	3006 SPRG	22-Jun-78	N	PD/S	13-Dec-12	6-Jan-13	Fired on Bolt Opening	Could Not Duplicate Concern	292660	F	Replace TA, clean & test fire
						1375				Altered Adjustments or		7	Per Ilion - Quote to repair @
8355	700	n/a	3006 SPRG	1-May-06	N	S	13-Dec-12	9-Jan-13	Fired on Safe Release	Components	295454	F	1/2 normal cost
	20.000							SUCCESSION STATE		Could Not Duplicate		-10	Per Ilion - Quote to repair
8356	700	n/a	3006 SPRG	1-Dec-74	N	5	14-Dec-12	14-Dec-12	Fired on Safe Release	Concern	292748	F	under BLM
8357	597	26513	22 LR	11-Sep-12	N	S	14-Dec-12	14-Dec-12	Unexplained Discharge - No Mention of Safety Position	Broken or Missing Parts	292733	F	Per Ilion - Check over completely, repair as neede under warranty
													Per Ilion, replace TPA, clean
		592	********	-2-22-0-22-	2400	12				Altered Adjustments or	2242427	12	and test fire at BLSM
8362	700	n/a	243 WIN	1-May-73	N	S	17-Dec-12	17-Dec-12	Fired on Bolt Closing	Components Could Not Duplicate	292958	F	program price Per Ilion - check over & repai
8363	770	85632	270 WIN	25-May-11	N	S	17-Dec-12	17-Dec-12	Fired on Bolt Closing	Concern	292384	F	- warranty
			7MM REM		-	-				Could Not Duplicate		1	Per Ilion - Replace TA to
8365	700	84016	MA	3-Apr-12	N	S	17-Dec-12	17-Dec-12	Fired on Safe Release	Concern	292261	F	restore confidence @ n/c
8366	700	26263	7MM REM MA	26-Feb-98	N	s	17-Dec-12	17-Dec-12	Fired on Safe Release	Could Not Duplicate Concern	292403	F	Per Ilion, can offer to replace TPA, clean, test at 1/2 charg to restore confidence
8367	700	84207	308 WIN	29-Jun-12	N	5	17-Dec-12	17-Dec-12	Fired on Safe Release	Could Not Duplicate Concern	292947	F	Per Ilion, will replace TPA, check over and test at no charge
8368	700	25773	3006 SPRG	16-Oct-87	N	s		17-Dec-12	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	292922		Per Ilion, can offer to replac TPA, clean and test at 1/2 charge to restore confidence
8369	600	n/a	243 WIN	1-Aug-74	Y	s	17-Dec-12	17-Dec-12	Fired on Safe Release	Altered Adjustments or Components	292924	F	Per Ilion, replace TPA, clean and test under recall at no charge
8370	700	84170	243 WIN	24-Jan-07	N	s	17-Dec-12	17-Dec-12	Safety not working properly	Altered Adjustments or Components	292979	0	Per Ilion, replace TPA, clear and test at 1/2 normal cost

8371	700	25773	3006 SPRG	16-Nov-89	N	s	17-Dec-12	17-Dec-12	Fired on Safe Release	Could Not Duplicate Concern	292992	F	Per Ilion, offer to replace TP/ clean, test at 1/2 charge
8372	700	n/a	3006 SPRG	25-Jan-78	N	5			Fired on Safe Release	Could Not Duplicate Concern	293067	F	Per Ilion, replace TPA, clear and test at BLSM program
-					-	-			Delayed Firing -		71000000	Ť	Per Ilion - Quote to repair @
8373	700	27476	270 WIN	24-Jan-00	N	s	18-Dec-12	18-Dec-12	Firearms	Improper Maintenance	292508	F	1/2 normal charge
8375	700	25777	7MM REM MA	19-May-89	N	s		18-Dec-12	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	293178	F	Per Ilion, offer to replace TP clean and test at 1/2 norma charge
10000	777070	(0)	2000000000	3500000			20727 222-	22222	3111111 3533030000	P. D. C. S.	-11500001101		Per Ilion - Quote to repair
8376	700	n/a	308 WIN	1-Jul-68	N	S	18-Dec-12	18-Dec-12	Fired on Safe Release	Improper Maintenance	293229	F	
8377	700	25771	270 WIN	21-Oct-96	N	s	18-Dec-12	18-Dec-12	Fired on Safe Release	Could Not Duplicate Concern	293346	F	
	1222.67		2020000	200000		- 2		0.000		Could Not Duplicate			Per Ilion - Repair @ n/c -
8382	770	85637	243 WIN	14-Aug-09	N	S	19-Dec-12	19-Dec-12	Fired on Safe Release	Concern	293417	F	
8383	7	24743	308 WIN 7MM	14-Oct-96	N	s	19-Dec-12	19-Dec-12	Fired on Safe Release	Improper Maintenance Altered Adjustments or	293495	F	Per Ilion - Quote to repair @ 1/2 normal cost Per Ilion - Quote to repair @
8384	700	26434	SAUM	10-Jul-02	N	s	19-Dec-12	19-Dec-12	Fired on Safe Release	Components	293381	F	1/2 normal cost
	7.55				-					Worn parts or		Ť	
8385	700	27580	50 CAL	4-Apr-97	N	S	19-Dec-12	19-Dec-12	Fired on Bolt Closing	components	293457	F	Per Ilion - Repair at n/c
										Could Not Duplicate			Per Ilion - Quote to repair @
8389	700	26259	3006 SPRG	24-Oct-01	N	S	20-Dec-12	20-Dec-12	Fired on Safe Release	Concern	293611	F	1/2 normal cost
8391	700	25713	308 WIN	18-Feb-99	N	s	20-Dec-12	20-Dec-12	Fired on Safe Release	Altered Adjustments or Components	293664	F	Return as received
8392	597	26516	17 HMR	20-Mar-03	N	s	20-Dec-12	2-May-13	Other - Firearms	Other - Unspecified or Undetermined - Firearms	295181	F	Quote for 60001
8394	700	n/a	270 WIN	1-Aug-74	N	5	21-Dec-12	21-Dec-12	Fired on Safe Release	Could Not Duplicate Concern	293695	F	Per Ilion, replace TPA, clear and test at BLSM program price
0324	700	nya	270 4414	1-W08-14		,	ZI Dec 12	21-000-12	Filed off Sale Nelease	Altered Adjustments or	233033	1	Per Ilion, replace TPA, clear and test at BLSM program
8395	700	n/a	270 WIN	22-Jul-79	N	s	21-Dec-17	21-Dec-17	Fired on Safe Release	Components	293754	F	
8396	700	n/a	3006 SPRG	23-Sep-75	N	s			Fired on Safe Release	Could Not Duplicate Concern	293798	F	Per Ilion, replace TPA, clear and test at BLSM program
8397	700	25771	270 WIN	1-Jan-89	N	s	21-Dec-12	21-Dec-12	Fired on Safe Release	Improper Maintenance	293785	F	Return as received
													Per Ilion, offer to remove, disassemble and clean TPA
8398	788	29813	243 WIN	1-Jun-82	Υ	S	21-Dec-12	21-Dec-12	Fired on Safe Release	Improper Maintenance	293806	F	and test at 1/2 charges
7127	New England Single Shot	n/a	12 GA		N	s	21-Dec-12		Delayed Firing - Ammunition	Other - Unexamined		A	
													Per Ilion, replace TPA, clear and test fire at BLSM
8406	700	n/a	270 WIN	1-Mar-70	N	S	2-Jan-13	2-Jan-13	Fired on Bolt Closing	Improper Maintenance	293577	F	program price.
8407	600	n/a	308 WIN	1-Apr-67	N	s	2-Jan-13	2-Jan-13	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	294045	F	Per Ilion, replace TPA, clear and test under recall
8409	700	27518	243 WIN	3-May-02	N	s	2-Jan-13	2-Jan-13	Fired on Safe Release	Could Not Duplicate Concern	293956	E	Per Ilion, offer to replace TP clean, test at 1/2 normal co
COPO	700	2/310	7MM REM	3-IVISY-UZ	TW	3	2-Jan-15	27011-13	rifed on sale nelease	CORCELL	293930	-	crean, tescaca/a normal cos
	700	n/a	MA				1		Fired on Safe Release	Improper Maintenance			

8411	7600	25152	3006 SPRG	22 Inn 02		nn/c	2 top 12	30 Jan 12	Fired With Safe ON	Altered Adjustments or	202021	F	Repair @ n/c - goodwill
8411	7600	25153	7MM REM	23-Jan-03	N	PD/S	2-Jan-13	30-Jan-13	Fired With Safe ON	Components	293971	- 1	gesture Replace TPA, clean, test at
3412	700	n/a	MA	1-May-77	N	S	2-Jan-13	2-Jan-13	Fired on Safe Release	Improper Maintenance	293946	F	BLSM program price
8413	700	n/a	243 WIN	1-Dec-71	N	s	2-Jan-13	2-Jan-13	Fired on Safe Release	Could Not Duplicate Concern	294124	F	Per Ilion, replace TPA, clear and test at BLSM program price
8414	700	n/a	7MM REM MA	1-Oct-68	N	s	2-Jan-13	2-Jan-13	Fired on Safe Release	Altered Adjustments or Components	294132	F	Per Ilion, replace TPA, clean and test at BLSM program price
0414	700	11/4	19164	1-001-08	34	3	2-1411-12	2-7411-13	Fired on sale nelease	components	294132		price
8417	742	n/a	3006 SPRG	27-Jun-79	Υ	PD/S	2-Jan-13	9-Jan-13	Fired on Bolt Closing	Sent in for Evaluation	294342	F	Return as received
8421	700	n/a	2506 REM	1-Jul-84	N	PD/S	3-Jan-13	3-Jan-13	Fired on Bolt Closing	Altered Adjustments or Components	294739	F	Per Ilion, offer to replace TP/ clean, test at 1/2 normal cos
8422	700	25771	270 WIN	2-Aug-88	N	s	3-jan-13	3-Jan-13	Fired on Safe Release	Improper Maintenance	294743	F	Per Ilion - Quote to repair @ 1/2 normal cost
8423	700	n/a	270 WIN	1-Aug-67	N	S	3-Jan-13	3-Jan-13	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	294253	F	Per Ilion - Quote to repair under BLM
8424	700	n/a	270 WIN	28-Apr-76	N	s	3-Jan-13	3-Jan-13	Fired on Safe Release	Improper Maintenance	294368	F	Per Ilion - Quote to repair under BLM
8425	700	26099	300 RUM	25-Jul-99	N	s	3-Jan-13	3-Jan-13	Fired on Safe Release	Could Not Duplicate Concern	294575	F	Per Ilion - Quote to repair @ 1/2 normal cost
8425	700	20099	300 KOIVI	25-Jul-99	N	3	3-14H-13	3-Jan-13	Fired on sale Kelease	Altered Adjustments or	2943/3		Per Ilion - Quote to repair
8426	700	n/a	3006 SPRG	30-Mar-76	N	5	3-Jan-13	3-Jan-13	Fired on Safe Release	Components	294585	F	under BLM
8427	597	26516	17 HMR	24-Oct-04	N	s	3-Jan-13	22-Jan-13	Other - Firearms	Other - Unspecified or Undetermined - Firearms	296803	F	Replace with #70724
8432	700	n/a	3006 SPRG	1-Sep-71	N	s	4-Jan-13	4-Jan-13	Fired on Safe Release	Could Not Duplicate Concern	294785	F	Per Ilion - Quote to repair under BLM
8434	700	n/a	3006 SPRG	19-Sep-78	N	5	4-Jan-13	4-Jan-13	Fired on Safe Release	Could Not Duplicate Concern	294791	F	Per Ilion - Quote to repair under BLM
8436	660	n/a	243 WIN	1-Feb-68	Y	s	4-Jan-13	21-Jan-13	Other - Does not trust firearm	Returned due to Recall	297128	F	Per Ilion - Replace TA @ n/c recall
8438	700	n/a	270 WIN	6-Oct-75	N	s	7-Jan-13	7-Jan-13	Fired on Bolt Closing	Altered Adjustments or Components	294509	F	Per Ilion, replace TPA, clean and test fire at BLSM
2224		292	7MM REM		440	10	2000000	74W7092		Could Not Duplicate	(22/2022)		Per Ilion - Quote to repair
8439	700	n/a	MA	3-May-77	N	5	7-Jan-13	7-Jan-13	Fired on Safe Release	Concern	294952	F	under BLM Per Ilion, can offer to replace
8440	700	25797	280 REM	4-Nov-91	N	s	7-Jan-13	7-Jan-13	Fired on Bolt Closing	Altered Adjustments or Components	295098	F	TPA, clean and test at 1/2 normal cost
8441	700	n/a	270 WIN	1-Apr-77	N	s	7-Jan-13	22-Jan-13	Delayed Firing - Firearms	Improper Maintenance	297520	F	Per Ilion, replace TPA, clean, test at BLSM program price
8445	700	n/a	270 WIN	1-Jul-74	N	5	8-Jan-13	8-Jan-13	Fired on Safe Release	Could Not Duplicate Concern	294552	F	Replace TPA, clean and test fire at BLSM program price
8446	700	84600	223 REM	27-Feb-12	N	S	8-Jan-13	15-Jan-13	Fired on Safe Release	Could Not Duplicate Concern	295180	F	Replace TPA, clean, test at no charge to restore confidence in rifle
8448	700	26096	300 RUM	23-Oct-00	N	s	8-Jan-13	8-Jan-13	Fired on Safe Release	Improper Maintenance	295225	F	Per Ilion - Quote to repair @ 1/2 normal cost
8452	700	n/a	2506 REM	9-Apr-76	N	s	9-Jan-13	9-Jan-13	Fired on Safe Release	Altered Adjustments or Components	295455	F	
8453	700	25739	308 WIN	21-Mar-12	N	s	10-Jan-13	10-Jan-13	Fired on Bolt Closing	Improper Maintenance	295573	F	Per Ilion - Replace TA @ n/c goodwill gesture

8454	788	n/a	6MM REM	1-Nov-70	Y	s	10-Jan-13	10-Jan-13	Fired on Bolt Closing	Could Not Duplicate Concern	295502	F	Per Ilion, can offer to remove TPA, disassm and clean and remove bolt lock at 1/2 cost
8456	700	26973	338 WIN MA	4-May-95	N	s	10-Jan-13	10-Jan-13	Fired on Bolt Closing	Altered Adjustments or Components	295578	F	Replace TPA, clean and test at 1/2 normal cost
8460	600	n/a	308 WIN	1-Jan-66	Y	PD/S	10-Jan-13	12-Feb-13	Fired on Safe Release	Could Not Duplicate Concern	298058	F	Bolt lock modification - no charge
			7MM08							Could Not Duplicate			
8465	R25	60031	REM	25-Nov-09	N.	S	11-Jan-13	28-Jan-13	Fired on Bolt Closing	Concern	295350	F	RGA issued for the rifle
8466	CARBON 15	90689	223-5.56 N	13-Jun-12	N	s	11-Jan-13	21-Jan-13	Fired on Bolt Closing	Could Not Duplicate Concern	295804	F	Repair no charge under warranty
8467	600	n/a	243 WIN	14-Nov-77	Y	s	11-Jan-13	11-Jan-13	Fired on Bolt Closing	Could Not Duplicate Concern	295908	F	Per Ilion, replace TPA, clean, test fire at BLSM program price
8468	700	26107	300 RUM	25-Jan-01	N	S	11-Jan-13	29-Jan-13	Fired on Safe Release	Could Not Duplicate Concern	298263	F	Per Ilion - Quote to repair @ 1/2 normal cost
										Could Not Duplicate			Per Ilion - Quote to repair
8471	700	n/a	270 WIN	1-Aug-72	N	5	14-Jan-13	14-Jan-13	Fired on Safe Release	Concern	296328	F	under BLM
8472	700	n/a	3006 SPRG	1-Apr-72	N	S	14-Jan-13	14-Jan-13	Fired on Safe Release	Altered Adjustments or Components	296173	F	Per Ilion - Quote to repair under BLM
8474	700	n/a	22-250 REM	1-May-68	N	s	14-Jan-13	14-Jan-13	Fired on Bolt Closing	Altered Adjustments or Components	296348	F	Per Ilion, replace TPA, clean, test at BLSM program price
8476	700	n/a	270 WIN	5-Jan-81	N	s	14-Jan-13	14-Jan-13	Fired on Safe Release	Could Not Duplicate Concern	296345	F	Per Ilion, replace TPA, clean, test at BLSM program price
8477	700	85407	308 WIN	29-May-12	N	s	14-Jan-13	14-Jan-13	Fired on Safe Release	Could Not Duplicate Concern	296325	F	Per Ilion, will replace TPA, check over and test at no charge as goodwill
	200									Could Not Duplicate			Per Ilion, can offer to replace TPA, clean, test at 1/2 norma
8478	700	25709	308 WIN	1-Oct-08	N	S	14-Jan-13	14-Jan-13	Fired on Bolt Closing	Concern	296162	F	cost
8479	600	n/a	243 WIN	1-May-72	Y	s	15-Jan-13	15-Jan-13	Fired on Bolt Closing	Altered Adjustments or Components	296425	F	Per Ilion, replace TPA, clean, test at no charge under recal
8482	700	25793	3006 SPRG	18-Dec-86	N	s	16-Jan-13	16-Jan-13	Delayed Firing - Firearms	Improper Maintenance	295927	F	Per Ilion, can offer to replace TPA, clean, test fire at 1/2 normal cost
8494	870	27040	12 GA	24-Sep-12	N	s	18-Jan-13	18-Jan-13	Fired on Safe Release	Could Not Duplicate Concern	296953	F	Per D. Sykes, #26929 as replacement under warranty
8496	700	84272	2506 REM	24-Oct-12	N	s	18-Jan-13	18-Jan-13	Fired on Bolt Closing	Other - Unspecified or Undetermined - Firearms	296810	F	Per Ilion, will replace TPA, check over and test fire at no charge
92220	2000		22000000		1000	844		220	210000000000000000000000000000000000000	Other - Unspecified or		1023	
8499	597	26560	22 WMR	21-Sep-11	N	S	21-Jan-13	24-Jan-13	Blowback in Face	Undetermined - Firearms	297358	F	Replace w/70855 in exchange Per Ilion, can offer to replace
8500	700	25793	3006 SPRG	1-Nov-83	N	s	21-Jan-13	21-Jan-13	Delayed Firing - Firearms	Improper Maintenance	297149	F	TPA, clean, test at 1/2 norma cost
8501	700	29717	3006 SPRG	26-Oct-95	N	s	21-Jan-13	21-Jan-13	Fired on Safe Release	Altered Adjustments or Components	297410	F	Per Ilion - Quote to repair at 1/2 normal cost
8502	700	27572	50 CAL	15-Sep-97	N	5	21-Jan-13	21-Jan-13	Fired on Bolt Closing	Improper Maintenance	297380	F	Per Ilion - Quote to repair at 1/2 normal cost
8503	700	n/a	243 WIN	14-Nov-75	N	s	21-Jan-13	21-Jan-13	Fired on Safe Release	Altered Adjustments or Components	297400	F	Per Ilion - Quote to repair under BLM
8506	1911	96328	45 ACP	1-Dec-11	N	s	21-Jan-13	21-Jan-13	Fired With Safe ON	Sent in for Evaluation	297025	F	Per Ilion - Check over, repair as needed @ n/c

8507	700	85490	308 WIN	21-Oct-11	N	S	21-Jan-13	21-Jan-13	Fired on Safe Release	Could Not Duplicate Concern	297101	F	Per Ilion - Replace TA @ n/c to restore confidence - goodwill
										Altered Adjustments or			Per Ilion - Quote to repair
8508	700	n/a	3006 SPRG	1-Sep-71	N	S	21-Jan-13	21-Jan-13	Fired on Safe Release	Components	297268	F	
			2000000	200.20	220	12			200	Altered Adjustments or			Per Ilion - Quote to repair @
8509	700	25632	280 REM	9-May-91	N	S	21-Jan-13	21-Jan-13		Components	297271	F	1/2 normal cost
8510	700	25771	270 WIN	20-Aug-91	N	s	21-Jan-13	21-Jan-13	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	297203	F	Per Ilion, offer replace TPA, clean, test at 1/2 normal cos
neae .					1200					Could Not Duplicate	(404440)		Check over completely, repair as needed and test fire at no
8515	887	82502	12 GA	18-Jun-10	N	S	22-Jan-13	22-Jan-13	Fired on Bolt Closing	Concern	297550	F	The second secon
8519	700	27131	204 RUGER	5-Sep-08	N	S	23-Jan-13	23-Jan-13	Fired on Safe Release	Altered Adjustments or Components	297652	F	Per Ilion, can offer to replace TPA, clean and test at 1/2 normal cost
	10000	25000	7MM REM						Delayed Firing -	05 85 5			Per Ilion - Quote to repair @
8520	700	25803	MA	10-Jul-95	N	S	23-Jan-13	23-Jan-13	Firearms	Improper Maintenance	297617	F	1/2 normal cost
8522	700	25767	243 WIN	13-Sep-93	N	S	24-Jan-13	24-Jan-13	Defective Parts Fired on Bolt	Leaking Primers  Altered Adjustments or	296992	F	Per Ilion, repair 1/2 normal cost as a good will gesture Per Ilion, replace TPA, clean and test at BLSM program
8523	700	n/a	243 WIN	1-Dec-71	N	S	24-Jan-13	24-Jan-13	Opening	Components	297857	F	price
8525 8527	600 710	n/a 27408	222 REM	25-Feb-76 16-May-02	Y	S PI/PD/S	24-Jan-13 24-Jan-13	24-Jan-13 20-Feb-13	Fired on Bolt Closing	Could Not Duplicate Concern Altered Adjustments or Components	297906 300092	F	Per Ilion, replace TPA, clean, test under recall at no charge Replace with #85632, 770 .270
USE!	7.20	27 100	E CO TINE	as may sa		141015	E+ 3011 25	20100 25	Theo on sore necesse.	Altered Adjustments or	300032	Ť	Replace TPA no charge as
8528	700	25609	35 WHELEN	5-Oct-89	Υ	PI/S	28-Jan-13	26-Feb-13	Fired on Bolt Closing	Components Altered Adjustments or	301645/301709	F	goodwill 85633, 770 30-06 as
8532	710	27410	3006 SPRG	7-Jan-01	N	S	28-Jan-13	19-Feb-13	Fired on Bolt Closing	Components	298241	F	
8534	1187	29895	12 GA	11-May-10	N	s	29-Jan-13	29-Jan-13	Fired With Safe ON	Could Not Duplicate Concern	297973	F	
8535	700	84401	2506 REM	8-Jul-09	N	s	29-Jan-13	29-Jan-13	Fired on Safe Release Jamming/Feeding	Altered Adjustments or Components	298215	F	Per Ilion, offer to replace TPA check over and test at 1/2 normal cost Ordered #25594 as
8536	597	26560	22 WMR	1-Aug-11	N	s	29-Jan-13	18-Feb-13	issues	Sent in for Evaluation	298132	F	
8539	700	n/a	3006 SPRG	23-Sep-79	N	5	29-Jan-13	29-Jan-13	Fired on Bolt Opening	Improper Maintenance	298271	F	Per Ilion, replace TPA, clean and test at BLSM program
0333	700	11/4	3000 31110	23-3ep-/9	14	3	23-3011-13	23-7011-13	Opening	may oper maniferiance	2302/1	+	Per Ilion, offer to replace TPA
8543	700	25771	270 WIN	1-Oct-83	N	s	30-Jan-13	30-Jan-13	Fired on Safe Release	Improper Maintenance	298376	F	clean and test at 1/2 normal cost
8544	700	n/a	270 WIN	20-May-81	N	s	30-Jan-13	30-Jan-13	Fired on Safe Release	Altered Adjustments or Components	298379	F	Per Ilion, replace TPA, clean and test at BLSM program price
8547	700	n/a	308 WIN	16-Jul-79	N	s	30-Jan-13	30-Jan-13	Defective Parts	Altered Adjustments or Components	298400	F	Replace TPA, clean and test at BLSM program price
8548	700	n/a	6MM REM	1-May-69	N	S	30-Jan-13	30-Jan-13	Fired on Safe Release	Altered Adjustments or Components	298537	F	Replace TPA, clean and test at BLSM program price

8551	700	27009	2506 REM	21-Jan-10	N	s	31-Jan-13	31-Jan-13	Fired on Bolt Closing	Could Not Duplicate Concern	298782	F	To restore confidence, will replace TPA, recrown muzzle, check over and test no charge
8552	700	n/a	22-250 REM	1-Mar-69	N	s	31-Jan-13	31-Jan-13	Fired on Safe Release	Could Not Duplicate Concern	298815	F	Per Ilion - Quote to repair under BLM
8553	700	n/a	7MM REM MA	1-Oct-01	N	5	31-Jan-13	31-Jan-13	Delayed Firing - Firearms	Improper Maintenance	298775	F	Per Ilion - Quote to repair at 1/2 normal cost
										Could Not Duplicate			Per Ilion - Replace TA @ n/c
8554	700	27094	270 WIN	17-Jul-12	N.	S	31-Jan-13	31-Jan-13	Fired on Bolt Closing	Concern	298738	F	goodwill
8558	597	26562	22 LR	25-Mar-11	N	s	1-Feb-13	1-Feb-13	Unexplained Discharge Safe OFF	Could Not Duplicate Concern	298985	F	
8559	700	n/a	7MM REM MA	1-Sep-71	N	s	1-Feb-13	1-Feb-13	Fired on Safe Release	Altered Adjustments or Components	298948	F	Per Ilion, replace TPA, clean and test at BLSM program price
8560	700	n/a	243 WIN	12-Oct-77	N	s			Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	298856	F	Replace TPA, clean and test
8560	700	nya	245 WIN	12-Oct-//	N.	3	1-Feb-13	1-Feb-13	Position	Concern	298856	- 1	at BLSM program price
8562	700	27476	270 WIN	1-Jan-96	N	s	4-Feb-13	4-Feb-13	Fired on Safe Release	Improper Maintenance	299028	F	Offer to replace TPA, clean and test at 1/2 normal cost
8563	700	27017	3006 5PRG	24-Aug-09	N	s	4-Feb-13	4-Feb-13	Fired on Safe Release	Could Not Duplicate Concern	299026	F	To restore confidence in rifle we will replace TPA, clean and test at no charge
8564	700	25783	22-250 REM	6-Jan-03	N	s	4-Feb-13	4-Feb-13	Fired on Safe Release	Improper Maintenance	299055	F	
	0.000			Self-land Control		2.0	900-8410AV			Could Not Duplicate			Per Ilion - Quote to repair at
8565	700	27478	3006 SPRG	12-Mar-99	N	5	4-Feb-13	4-Feb-13	Fired on Bolt Closing	Concern	299029	F	
8567	CARBON 15	90689	223 REM	29-Oct-10	N	s	4-Feb-13	4-Feb-13	Fired With Safe ON	Could Not Duplicate Concern	299228	F	
8568	700	n/a	3006 SPRG	1-Aug-87	N	s	4-Feb-13	4-Feb-13	Fired on Safe Release	Improper Maintenance	299030	F	Per Ilion - Quote to repair @ 1/2 normal cost
8569	870	25568	12 GA	18-May-12	N	S	4-Feb-13	4-Feb-13	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate	299248	F	Check over completely. Repair as needed at no charge
8569	8/0	25568	12 GA	18-IVIAY-12	N	3	4-Feb-13	4-Feb-13	Position	Concern	299248	- 1	charge
8571	700	84644	3006 SPRG	10-Aug-12	N	s	5-Feb-13	5-Feb-13	Fired on Safe Release	Could Not Duplicate Concern	298477	F	
8572	700	25789	2506 REM	28-Jun-96	N	s	5-Feb-13	5-Feb-13	Fired on Safe Release	Altered Adjustments or Components	299304	F	Replace TPA, clean and test at 1/2 normal cost
8573	700	n/a	243 WIN	1-Apr-69	N	PD/S	5-Feb-13	5-Feb-13	Fired With Safe ON	Altered Adjustments or Components	299267	F	Per Ilion, replace TPA and test at BLSM program price
8574	600	n/a	308 WIN	1-Jul-65	Y	s	5-Feb-13	5-Feb-13	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	299305	F	Replace TPA, clean and test under recall at no charge
8575	700	84543	2506 REM	2-Apr-12	N	s	5-Feb-13	5-Feb-13	Fired on Bolt Closing	Could Not Duplicate Concern	298482	F	Per Ilion, replace TPA, check over and test at no charge
8577	700	27255	300 WSM	21-Aug-09	N	s	5-Feb-13		Fired on Safe Release	Could Not Duplicate Concern	303330	F	Per Ilion - Replace TA @ n/c - goodwill

8582	597	26515	22 LR	6-Sep-12	N	S	7-Feb-13	7-Feb-13	Went Automatic	Could Not Duplicate Concern	298883	F	Per Ilion, check over completely, repair as needed at no charge under warranty
8583	700	n/a	7MM REM MA	10-Jul-80	N	s	7-Feb-13	7-Feb-13	Safety not working properly	Altered Adjustments or Components	299656	F	Per Ilion, replace TPA, clean and test at BLSM program price
8584	887	82502	12 GA	8-Oct-10	N	S	7-Feb-13	21-Feb-13	Fired Out of Battery Unexplained	Sent in for Evaluation	299630	F	Replace w/82502 in exchange @ n/c
8585	770	85633	3006 SPRG	28-Dec-09	N	s	7-Feb-13	7-Feb-13	Discharge - No Mention of Safety Position	Could Not Duplicate Concern	299626	F	Per Ilion, offer to replace TPA clean and test at no charge
8586	700	n/a	270 WIN	1-Mar-70	N	s	7-Feb-13	7-Feb-13	Fired on Bolt Closing	Improper Maintenance	299658	F	Per Ilion, replace TPA, clean, test at BLSM program price
	122227		222227	120000000000000000000000000000000000000	-	102	200000	200000		Could Not Duplicate	12.202225	1/2	Per Ilion, could not duplicate
8587	700	84206	223 REM	8-May-09	N	S	7-Feb-13	7-Feb-13	Fired on Bolt Closing	Concern	299659	F	Concern  Por Illon, will replace TRA
8589	700	25709	308 WIN	27-Apr-09	N	s	8-Feb-13	8-Feb-13	Fired on Bolt Closing	Could Not Duplicate Concern	299018	F	Per Ilion, will replace TPA, check over and test at no charge as goodwill
8591	700	n/a	3006 SPRG	1-Sep-71	N	5	8-Feb-13	8-Feb-13	Fired on Safe Release	Improper Maintenance	299808	F	- Interest the section of the sectio
8592	887	82500	12 GA	22-Jul-09	N	s	8-Feb-13	8-Feb-13	Fired on Bolt Closing	Sent in for Evaluation	299790	F	Per Ilion, check over completely, replace bolt assm, clean and test at no charge
8593	7	24788	308 WIN	21-Jun-96	N	S	8-Feb-13	8-Feb-13	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	299770	F	Per Ilion - Quote to repair @ 1/2 normal cost
tures.	724555	1-90	32233869	59/00/1789/9	225	93	255740000	880-990-98		Altered Adjustments or		100	
8594	700	n/a	308 WIN	1-Nov-77	N	S	8-Feb-13	8-Feb-13	Fired on Safe Release	Components	299837	F	Per Ilion - Quote to repair
8595	BACR	90704	5.56 NATO	30-Jul-10	N	S	8-Feb-13	8-Feb-13	Went Automatic	Sent in for Evaluation	299849	F	Per Illon - Repair @ n/c
8596	700	26285	7MM08 REM	17-Sep-09	N	s	8-Feb-13	8-Feb-13	Fired on Safe Release	Could Not Duplicate Concern	299832	F	Per Ilion - Replace TA, check over, test @ n/c - goodwill Per Ilion - Repair @ n/c -
8599	870	25100	12 GA	25-Jan-12	N	s	11-Feb-13	11-Feb-13	Fired Out of Battery	Sent in for Evaluation	299169	F	warranty
8601	700	n/a	7MM REM MA	23-Sep-77	N	PD/S	11-Feb-13	22-Feb-13	Fired on Safe Release	Could Not Duplicate Concern	300101	F	Quoted 1/2 normal price for stock and BLSM program price for trigger
8602	700	84207	308 WIN	10-Jun-09	N	5	11-Feb-13		Fired on Safe Release	Could Not Duplicate Concern	299947	F	Per Ilion, will replace TPA, clean and test as goodwill gesture
8603	700	27533	7MM REM M	19-May-98	N	s	11-Feb-13		Fired on Bolt Closing	Improper Maintenance	299952	F	Can offer to replace TPA, clean and test at 1/2 normal cost
8604	700	27489	22-250 REM	23-Feb-00	N	s	11-Feb-13		Fired on Safe Release	Altered Adjustments or Components	299999	F	Replace TPA, clean and test at 1/2 normal cost
5504		27403	22-250	23-160-00	14	,		11-1-0-13	rinca on pale nelease	Altered Adjustments or	23333	-	Per Ilion - Reset TA & test @
8607	7	85953	REM	15-Apr-08	N	S	12-Feb-13	12-Feb-13	Fired on Safe Release	Components	300196	F	n/c - goodwill gesture
8608	770	85654	7MM REM MA	13-Jul-11	N	S	12-Feb-13	12-Feb-13	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	300190	F	
8609	600	n/a	350 REM MA	1-Mar-65	Y	s	12-Feb-13	12-Feb-13	Fired on Safe Release	Could Not Duplicate Concern	300256	F	Per Ilion - Replace TA under recall
8610	1911	96323	45 ACP	19-Jan-12	N	s	12-Feb-13	12-Feb-13	Safety not working properly	Sent in for Evaluation	300287	F	Per Ilion - Replace in exchange @ n/c

						1				Could Not Duplicate	0.000.0000.000	-10	LA MALI PROMOCIO INVARIANTA MANUELA
8614	770	85653	3006 SPRG	23-Mar-11	N	S	14-Feb-13	14-Feb-13	Fired on Safe Release	Concern	299884	F	Per Ilion - Repair @ n/c
8615	700	n/a	7MM REM MA	1-Jul-74	N	s	14-Feb-13	14-Feb-13	Delayed Firing - Firearms	Improper Maintenance	299863	F	Per Ilion - Quote to repair under BLM
	0.54.5	74.00	7 MM REM		-			211111111	15000000000	Could Not Duplicate		-11	Per Ilion - Quote to repair é
8620	700	26933	M	9-Jan-95	N	s	18-Feb-13	18-Feb-13	Fired on Safe Release	Concern	300780	F	1/2 normal cost
-		-			100	-	170-170-110-0					- 10	Can offer to replace TPA,
			7 MM REM							Could Not Duplicate			clean and test fire at 1/2
8626	710	27412	M	15-Feb-06	N	s	19-Feb-13	19-Feb-13	Fired With Safe ON	Concern	300316	F	
	- 140	27 1,44	1	25.05.00		-	20,140,00	20 1 1 1 2 1	17700 177117 2072 077			-1	
										Altered Adjustments or			Replace TPA, clean and tes
8628	700	n/a	223 REM	31-Dec-75	N	s	19-Feb-13	19-Feb-13	Fired on Safe Release	Components	300941	F	
						_	20.110.20	45 130 30		Could Not Duplicate		Ť	Replace TA, clean & test @
8630	700	27017	3006 SPRG	10-Mar-05	N	s	20-Feb-13	25-Feb-13	Fired on Safe Release	Concern	301122	F	n/c - goodwill gesture
			7 MM REM						D30000-03800-039	Could Not Duplicate			Per Ilion - Quote to repair
8632	700	n/a	Α	13-Jun-80	N	s	20-Feb-13	20-Feb-13	Fired on Safe Release	Concern	301212	F	under BLM
		7		20 3000	-	-	20.100.20	20110				1	Per Ilion - Quote to repair
8633	721	n/a	270 WIN	1-Dec-52	Y	s	20-Feb-13	20-Feb-13	Fired on Bolt Closing	AFT MKT STOCK ASSM	301243	F	under BLM
	1.07	74.5			_	_						Ť	Per Ilion, check over
													completely, repair as neede
8638	XM15-E2S	90641	223 - 5.56	16-Aug-11	N	S	21-Feb-13	21-Feb-13	Went Automatic	Sent in for Evaluation	301327	F	at no charge
						_				Altered Adjustments or		1	Repair @ n/c - goodwill
8642	600	n/a	243 WIN	4-Dec-77	Y	s	21-Feb-13	12-Apr-13	Fired on Safe Release	Components	307383	F	gesture
													Per Ilion - Quote to repair
8643	700	n/a	3006 SPRG	1-Mar-75	N	S	22-Feb-13	22-Feb-13	Fired on Bolt Closing	Improper Maintenance	301531	F	under BLM
							***************************************			,		-	20.700.200
													Per Ilion, check over
										Could Not Duplicate			completely, repair/adjust a
8644	1911 R1	96324	45 ACP	21-Jan-13	N.	s	22-Feb-13	22-Feb-13	Fired Out of Battery	Concern	301474	F	needed, test fire at no charg
			22-250	22.5020		-			Action Opened on	MIN LOCK UP ON BBL		-	Per Ilion - Repair as needed
8646	SB2 ULTRA	72744	REM	9-Mar-06	N	S	25-Feb-13	25-Feb-13	Firing	CATCH	301811	F	n/c
			10000			_						1	Per Ilion, offer to replace TP
			300										clean and test fire at 1/2
8647	700	25869	SAVAGE	3-Apr-03	N	5	25-Feb-13	25-Feb-13	Fired on Safe Release	Improper Maintenance	301084	F	normal cost
			7MM REM									-	Per customer request -
8648	700	n/a	MA	1-Dec-74	N	s	25-Feb-13	25-Feb-13	Fired on Safe Release	Improper Maintenance	301078	F	returned as received
		.,,				-						Ť	Replacing with a 597 .22LR
										Could Not Duplicate			#26550 as a gesture of
8649	522	29792	22 LR	23-Jul-96	Y	PD/S	25-Feb-13	25-Feb-13	Went Automatic	Concern	301706	F	
0045	366	23132	EE CIT	25 741 70	÷	10/5	25 100 25	2510015	- West Platemane	- Conton	501700	Ť	Replace TPA, check over and
8650	700	25739	308 WIN	19-Dec-12	N	5	25-Feb-13	25-Feb-13	Fired on Bolt Closing	As received Follows Down	301809	F	test fire at no charge
0020			500 1111	17 000 10		-	23,100,25	20120 20	The on our closing.	Altered Adjustments or	301003	-	Per Ilion - Repair @ n/c -
8651	700	84207	308 WIN	14-Feb-12	N	s	25-Feb-13	25-Feb-13	Fired on Bolt Closing	Components	301642	F	goodwill
OUDA	7.00	51207	500 1111	27100.20		-	25.140.20	20.100.20	Unexplained	- Secondarion	202012	Ť	Beautin
									Discharge - No				
									Mention of Safety	Altered Adjustments or			
8652	700	26107	300 RUM	31-Jan-00	N	5	25-Feb-13	25-Feb-13	Position	Components	301658	F	Return as received
	7.44		20011010		1.5	-			Unexplained			1	
									Discharge - No				Per Ilion, replace TPA, clear
									Mention of Safety	Could Not Duplicate			and test at BLSM program
8653	700	n/a	3006 SPRG	1-Oct-69	N	s	25-Feb-13	25-Feb-13	Position	Concern	301671	F	price
	-7/7/7//		1		- 0.0					92232201		1	- F0/300
										Other - Unspecified or			
8656	597	26516	17 HMR	21-Jul-05	N	s	26-Feb-13	1-Mar-13	Fired Out of Battery	Undetermined - Firearms	301973	F	Replace with #70721
						-						Ť	
										Altered Adjustments or			Replace TPA, clean and tes
8657	700	n/a	6MM REM	1-May-70	N	s	26-Feb-13	26-Feb-13	Fired on Safe Release	Components	301855	F	
	77.33	.,,-				-						7	Per Ilion, replace TPA, clear
			7MM REM							Altered Adjustments or			and test fire at BLSM
200000	52227	1.00	MA		100	10		22 5 4 42	Fired on Safe Release			1/2	
8660	700	n/a		1-Apr-83	N	S				Components	301577	F	program price

8661	700	27363	3006 SPRG	9-Mar-11	N	s	27-Feb-13	27-Feb-13	Fired on Bolt Closing	Could Not Duplicate Concern	302049	F	Per Ilion, will replace TPA, check over and test at no charge
8663	700	n/a	6MM REM	8-Dec-75	N	S		28-Feb-13	Delayed Firing - Firearms	Altered Adjustments or Components	302176	F	Per Ilion, replace TPA, clean and test at BLSM program
8664	770	85633	3006 SPRG	29-Aug-12	N	s	28-Feb-13	28-Feb-13	Delayed Firing - Firearms	Improper Maintenance	302186	F	Per Ilion, replace TPA, clean and test at no charge
8665	887	82502	12 GA	28-Jan-10	N	s	28-Feb-13	28-Feb-13	Fired With Safe ON	Could Not Duplicate Concern	302181	F	Per Ilion, check over completely, replace TPA, repair, test no charge
8666	700	n/a	270 WIN	9-Oct-75	N	s		28-Feb-13	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	302279	F	Replace TPA, clean and test
8668	1187	83609	12GA	5-May-11	N	s	1-Mar-13	1-Mar-13	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	301791	F	Per Ilion, check over completely, replace TPA and test fire at no charge
8669	887	82500	12 GA	22-Jun-12	N	s	1-Mar-13	1-Mar-13	Fired With Safe ON	Could Not Duplicate Concern	302519	F	Replace TPA, check over completely and test fire at no charge
8670	700	n/a	7MM REM MA	1-Oct-71	N	s	1-Mar-13	1-Mar-13	Fired on Bolt	Could Not Duplicate Concern	302537	F	Per Ilion - Quote to repair under BLM
8743	700	n/a	270 WIN	1-May-72	N	5	1-Mar-13		Opening  Fired on Safe Release	Altered Adjustments or Components	305981	F	Per Ilion, replace TPA, clean and test at BLSM program price
8673	700	n/a	22-250 REM	1-Feb-71	N	s	4-Mar-13	4-Mar-13	Fired on Bolt Closing	Improper Maintenance	302131	F	Per Ilion, replace TPA, clean and test at BLSM program price
8674	700	27271	7MM REM MA	27-Aug-12	N	s	4-Mar-13	4-Mar-13	Fired on Bolt Closing	Could Not Duplicate Concern	302715	F	Per Ilion, replace TPA, check over and test at no charge as goodwill
8677	600	n/a	308 WIN	1-May-71	Y	s	5-Mar-13	5-Mar-13	Fired on Bolt Closing	Improper Maintenance	302076	F	Per Ilion, replace TPA, clean, test at no charge
Section			53.92.0		200		Orania de la composição d	Separation 10	Ammunition		55/32 S.W		No product returned for
8682		N/A	N/A		N	5	7-Mar-13	22-May-13	Exploded Fired on Bolt	Other - Unexamined Could Not Duplicate	n/a	A	inspection Replace TPA, clean, test at
8683	700	n/a	270 WIN 300 WIN	19-Sep-75	N	S	8-Mar-13	8-Mar-13	Opening	Concern Could Not Duplicate	302723	F	BLSM program price
8684	700	85623	MA	2-Aug-12	N	S	8-Mar-13	8-Mar-13	Fired on Safe Release	Concern	303851	F	Per Ilion - Replace TA at n/c
8685	770	85632	270 WIN	17-Nov-08	N	5	8-Mar-13	8-Mar-13	Delayed Firing - Firearms	Could Not Duplicate Concern	303887	F	As a gesture of goodwill, replace TPA, clean and test at no charge
8687	XM15E2S	n/a	223-5.56 N	14-Jan-09	N	S	8-Mar-13	8-Mar-13	Went Automatic	Broken or Missing Parts	303908	F	Repair as needed and test fin
8688	710	27408	270 WIN	26-Apr-02	N	s	8-Mar-13	27-Mar-13	Fired on Bolt Closing	Could Not Duplicate Concern	305661	F	Check over, repair, adjust, clean and test as needed at no charge
8689	700	27097	7MM REM MA	12-Apr-12	N	s	11-Mar-13	11-Mar-13	Fired on Bolt Closing	Could Not Duplicate Concern	303290	F	Per Ilion, replace TPA, check over, test fire at no charge as a gesture of goodwill. Per Ilion, offer to replace TPA
8690	700	27317	270 WIN	13-Jun-03	N	5	11-Mar-13	11-Mar-13	Fired on Safe Release	Could Not Duplicate Concern	304047	F	clean and test fire at \$20 + shipping
8693	887	82502	12 GA	6-Aug-12	N	s	12-Mar-13	12-Mar-13	Fired on Safe Release	Could Not Duplicate Concern	304183	F	Per Ilion - Repair at n/c
8694	700	n/a	3006 SPRG	15-Feb-77	N	s	12-Mar-13	12-Mar-13	Delayed Firing - Firearms	Improper Maintenance	304143	F	Per Ilion - Quote to repair under BLM

8695	700	n/a	3006 SPRG	7-Feb-77	N	s	12-Mar-13	12-Mar-13	Fired on Safe Release	Improper Maintenance	304144	F	Per Ilion - Quote to repair under BLM
0022		.,,,,,		710077			AL HAI AS	AL IVIGIT ALS	Unexplained Discharge - No	and a second	307477	Ť	0,100,100
			7MM08						Mention of Safety				Per Ilion - Quote to repair @
8696	700	25799	REM	31-Jan-90	N	s	12-Mar-13	12-Mar-13	Position	Improper Maintenance	304152	F	
0000		20100	300 H&H		-		30,000,30	20 1101 20		Could Not Duplicate		Ť	Per Ilion - Quote to repair
8698	721	n/a	MA	1-Apr-60	Y	5	13-Mar-13	13-Mar-13	Fired on Safe Release	Concern	304241	F	
									Fired on Bolt	Could Not Duplicate			Per Ilion - Quote to repair
8699	700	n/a	3006 SPRG	1-Jul-76	N.	S	13-Mar-13	13-Mar-13	Opening	Concern	304307	F	
									67 50 -	Altered Adjustments or			Per Ilion - Quote to repair @
8701	722	n/a	n/a		Υ	S	14-Mar-13	14-Mar-13	Fired on Safe Release	Components	304374	F	1/2 normal cost
													Per Ilion - Replace TA, clean
8702	660	n/a	6MM REM	1-May-69	Υ	S	14-Mar-13	14-Mar-13	Fired on Safe Release	Improper Maintenance	304443	F	test under recall at n/c Per Ilion - Quote to repair
6170	700	n/a	3006 SPRG	1-Sep-74	N	s	15-Mar-13	15-Mar-13	Fired on Safe Release	Improper Maintenance	304601	F	
			7MM REM										
8704	710	27412	MA	13-Jun-05	Y	5	15-Mar-13	15-Mar-13	Fired on Safe Release		304251	F	Per Ilion - Repair @ n/c
000000	0.0000000000000000000000000000000000000			RECELOROSIO		110	NUMBER		F. 220 20 Film (842) - 400 F	Could Not Duplicate			Transaction and transactions
8705	XM15-E2S	90629	223 - 5.56	27-Sep-11	N	S	15-Mar-13	15-Mar-13	Defective Parts	Concern	304615	F	
0705	700	25201	22014/81	31.04.01			45 14 43	45.1443	Delayed Firing -	Income to the later of the late	204524	F	Per Ilion - Quote to repair @
8706	700	25791	270 WIN	31-Oct-91	N	S	15-Mar-13	15-Mar-13	Firearms	Improper Maintenance Could Not Duplicate	304621	- 1	1/2 normal cost  Per Ilion - Quote to repair @
8707	700	25793	3006 SPRG	19-Apr-89	N	s	15-Mar-13	15-Mar-13	Fired on Bolt Closing	Concern	304568	F	1/2 normal cost
0/0/	700	23732	3000 31110	15 Apr 05			45 19101 45	15 (4)(11-15	Thea off boil closing.	Altered Adjustments or	304300	-	Per Ilion - Quote to repair
8708	700	n/a	222 REM	1-Dec-71	N	s	15-Mar-13	15-Mar-13	Fired on Bolt Closing	Components	304566	F	
										Could Not Duplicate			Per Ilion - Replace TA @ n/c
8711	700	27094	270 WIN	19-Jun-12	N	s	18-Mar-13	18-Mar-13	Fired on Safe Release	Concern	304577	F	goodwill gesture
			22-250							Could Not Duplicate			Per Ilion - Replace TA, check
8713	700	85565	REM	3-Feb-12	N	S	18-Mar-13	18-Mar-13	Fired on Safe Release	Concern	304866	F	over & test at n/c
8714	710	27410	3006 SPRG	22-May-03	γ	s	18-Mar-13	20-Mar-13	Fired With Safe ON	Broken or Missing Parts	304831	F	Replace w/85633 in exchang @ n/c
										Could Not Duplicate			Replace TPA, clean and tes
8717	600	n/a	6MM REM	19-Oct-77	Υ	S	19-Mar-13	19-Mar-13	Fired on Safe Release	Concern	305039	F	
										***************************************			Per Ilion, check over
	507	20000	22.10						First Constitution	Other - Unspecified or			completely, repair as neede
8720	597	26550	22 LR	28-Jul-08	N	S	20-Mar-13	20-Mar-13	Fired Out of Battery	Undetermined - Firearms  Could Not Duplicate	305282	F	at no charge Per Ilion - Quote to repair
8721	700	n/a	6MM REM	1-Aug-69	N	s	20-Mar-13	22-Mar-13	Fired on Safe Release	Concern	305249	F	under BLM
0/21	700	100	OWNER REIN	I-Mug-05	-14	-	ZO-IVIGIT-ZO	CT.IMM. TO	Firing Pin Follows	Concern	303243	-	Per Ilion - Repair @ n/c -
8726	1911	96343	45 AUTO	18-May-12	N	s	21-Mar-13	21-Mar-13	Down	Sent in for Evaluation	305447	F	
													Per Ilion, replace TPA, clear
			0.000-0.000						4 - 5 - 5 - 6 - 5				and test under recall at no
8732	660	n/a	222 REM	1-Jan-68	Υ	S	25-Mar-13	25-Mar-13	Fired on Safe Release	Improper Maintenance	305766	F	charge
									Delayed Firing -			-1	Per Ilion - Quote to repair
8736	600	n/a	243 WIN	1-Feb-77	Y	S	25-Mar-13	25-Mar-13	Firearms	Improper Maintenance	305726	F	under BLM
	020	26927	12 GA	20.1107	N	s	20.14			Defective Trigger		F	
8742	870	26927	12 GA	29-Mar-07	N	5	26-Mar-13	26-Mar-13	Defective Parts	Assembly Not Examined by Product	305982	- 1	Per Ilion - Repair @ n/c Gun not returned to Ilion fo
8740	700	n/a	7MM MAG	21-Mar-79	N	PD/S	26-Mar-13	14-Feb-14	Fired on Bolt Closing	Service	n/a	F	exam
07.10	700	190	711111111111111111111111111111111111111	EZ IIIII I I		10/0	EO IVIII ZO	2110021	Theo on boil closing	Service.	.,, .	-	Check over completely, repa
										Could Not Duplicate			as needed and test fire at n
8744	XM15-E2S	n/a	223/5.56	26-Nov-08	N	s	27-Mar-13	27-Mar-13	Went Automatic	Concern	306033	F	
			12771007723		100					Could Not Duplicate		10	Per Ilion - Replace TA & tes
8745	40X	27225	308 WIN	30-Nov-11	N	5	27-Mar-13	27-Mar-13	Fired on Safe Release	Concern	306070	F	fire @ n/c
Carr	521850		264 WIN	500 500		-81		22-12		Could Not Duplicate	ACCURACIO		Per Ilion - Quote to repair
8747	700	n/a	MA	1-Apr-63	N.	S	28-Mar-13	28-Mar-13	Fired on Bolt Closing	Concern	306184	F	
										Not Examined by Product	count		Gun not returned to Ilion fo
8749	700	27480	7MM MAG	3-May-00	N	S	1 28-Mar-13	14-Feb-14	Fired on Safe Release	Service	n/a	F	exam

													Per Release - 90289 is
8752	Carbon 15 Pistol	n/a	223/5.56		Υ	PI/S	1-Apr-13	4-Jun-13	Defective Parts	Broken or Missing Parts	304640	F	
8753	700	27580	50 CAL	8-Aug-97	Υ	s		16-Apr-13	Fired on Bolt Closing	Design and Missian Basto	306299	F	Ordering #84275 as
8/53	700	2/580	50 CAL	8-Aug-97	1	- 2	1-Apr-13	16-Apr-13	Fired on Bolt Closing	Broken or Missing Parts	306299	- 1	replacement Per Ilion, can offer to replace
8754	700	25630	270 WIN	26-Jul-87	N	s	1-Apr-13	1-Apr-13	Safety not working properly	Altered Adjustments or Components	306306	F	TPA, clean and test at 1/2
8755	700	n/a	7MM REM MA	1-Sep-72	N	S	1-Apr-13	1-Apr-13	Fired on Safe Release	Altered Adjustments or Components	306303	F	Per Ilion, replace TPA, clear and test at BLSM program price
			101000000000	Activess:	Vo. 1. 1				Delayed Firing -	W.C.C. (1900)			Per Ilion, replace TPA, clear and test at BLSM program
8759	700	n/a	3006 SPRG	9-Jul-76	N	S	2-Apr-13	2-Apr-13	Firearms	Improper Maintenance	306443	F	price
8760	660	n/a	308 WIN	1-Feb-69	Y	s	2-Apr-13	2-Apr-13	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	306490	F	Per Ilion, check over completely, replace TPA, clean, test at no charge
								-					Replace TPA, clean and test
8761	700	25614	243 WIN	10-Apr-89	N	S	2-Apr-13	2-Apr-13	Fired on Bolt Closing	Improper Maintenance	306504	F	at 1/2 normal cost
8765	700	85479	308 WIN	16-Dec-11	N	5	3-Apr-13	3-Apr-13	Fired on Bolt Closing	Could Not Duplicate Concern	306089	F	Per Ilion: Replace TA @ n/c goodwill gesture
0/00	700	034/3	200 4484	10-060-11	14	3	2.wbi-12	2-whi-12	Fired on Boil Closing	Concern	300003	- 1	Roomin Restate.
8768	600	n/a	308 WIN	1-Feb-66	Y	s	4-Apr-13	4-Apr-13	Fired on Safe Release	Improper Maintenance	306770	F	Per Ilion: Replace TA, clean & test under recall @ n/c
									Unexplained Discharge - No Mention of Safety				Per Ilion, offer to replace TPA
8770	700	29675	2506 REM	11-Sep-00	N	S	4-Apr-13	4-Apr-13	Position	Improper Maintenance	306895	F	clean, test at 1/2 normal cos
									Unexplained Discharge - No Mention of Safety				Per Ilion, replace TPA, clean and test under recall at no
8771	660	n/a	243 WIN	1-Jan-68	Y	S	4-Apr-13	4-Apr-13	Position	Improper Maintenance	306812	F	charge
8772	887	82500	12 GA	14-Dec-11	N	PD/S	4-Apr-13	4-Apr-13	Fired Out of Battery	Broken or Missing Parts	306723	F	Per Ilion, check over completely, repair, update, test at no charge
	477.5045.00		22-250				777		17	Could Not Duplicate			Per Ilion - Quote to repair
8773	700	n/a	REM	1-Dec-77	N	S	4-Apr-13	4-Apr-13	Fired on Bolt Closing	Concern	306776	F	under BLM
8775	700	27363	3006 SPRG	6-Dec-04	N	PI/S	4-Apr-13	17-Jun-13	Fired on Safe Release	Improper Maintenance	311757	F	Replace TA, clean, test @ n/e goodwill gesture
8779	700	n/a	270 WIN	1-Jan-65	N	s	5-Apr-13	5-Apr-13	Fired on Bolt Closing	Could Not Duplicate Concern	306971		Per Ilion, replace TPA, clean test at BLSM program price
011.5	1,00	.,,	27.0 11.11	2 3011 05		-	3 Fipt 23	5 Apr 25	The on both diesing	Could Not Duplicate	500571	Ť	Per Ilion - Quote to repair @
8780	700	26404	243 WIN	24-May-00	N	5	8-Apr-13	8-Apr-13	Fired on Bolt Closing	Concern	307197	F	1/2 normal cost
Charles	120000	= pr			223	75	12912700	120 C - 120		Could Not Duplicate	2244070250	16	Per Ilion - Quote to repair
8781	700	n/a	2506 REM	31-Mar-78	N	S	8-Apr-13	8-Apr-13	Fired on Safe Release	Concern	307165	F	THE RESERVE OF THE PERSON NAMED IN COLUMN 2 IS NOT THE PERSON NAME
8782	870	25077	12 GA	24-Sep-09	N	s	8-Apr-13	8-Apr-13	Action Opened on Firing	Could Not Duplicate Concern	307184	F	Per Ilion - Check over competely, test fire @ n/c- goodwill
8785	700	25739	308 WIN	4-Aug-10	N	s	8-Apr-13	1-May-13	Fired on Safe Release	Could Not Duplicate Concern	309552	F	Per Ilion - Replace TA, clean test - goodwill gesture
8786	700	n/a	22-250 REM	1-Jun-77	N	PD/S	8-Apr-13	24-Apr-13	Fired on Bolt Closing	Altered Adjustments or Components	308903	F	Per Ilion, replace TPA, clear and test under BLSM program price
8787	700	n/a	243 WIN	1-Sep-81	N	S	9-Apr-13	9-Apr-13	Fired on Bolt Closing	Could Not Duplicate Concern	306521	F	Per Ilion, replace TPA, clean and test fire at BLSM program price

8789	700	27111	300 RUM	3-Sep-05	N.	s	9-Apr-13	9-Apr-13	Fired on Bolt Closing	Altered Adjustments or Components	307298	F	Offer to replace TPA, clean and test at 1/2 normal cost
			300 WIN							Could Not Duplicate			Per Ilion, replace in exchange
8790	700	27387	MA	8-Apr-13	N	S	9-Apr-13	9-Apr-13	Fired on Safe Release	Concern	307417	F	ramac# 27387
8791	700	26096	300 RUM	24-Feb-00	N	s	10-Apr-13	10-Apr-13	Fired on Safe Release	Improper Maintenance	307385	F	Per Ilion, can offer to replace TPA, clean and test at 1/2 normal cost
			7MM08							Could Not Duplicate			Per Ilion - Replace TA, clean &
8795	7	24741	REM	16-Oct-95	N	S	11-Apr-13	11-Apr-13	Fired on Safe Release	Concern	306878	F	test @ n/c
8796	700	27527	204 RUG	15-Sep-04	N	s	11-Apr-13	11-Apr-13	Safety not working properly	Altered Adjustments or Components	306656	F	
2222	22227	1010000	12233323	C220100000000	9250	122	222.000000	42-20-02			020000	12	Replace with a new rifle of
8799	700	84218	308 WIN	27-Jun-08	N	S	12-Apr-13	15-Apr-13	Fired on Safe Release	As received Follows Down	307049	F	
8801	870	25561	20 GA		100				Other - Firearms	Could Not Duplicate	207770	F	Replace with new 85561 to
9901	8/0	25561	20 GA	14-Aug-12	N	S	15-Apr-13	15-Apr-13	Other - Firearms	Concern	307778	- 1	restore confidence Quote to repair at 50%
8802	700	25813	3006 SPRG	23-Jan-01	N	5	15-Apr-13	15-Apr-13	Fired on Safe Release	Improper Maintenance	307837	F	
8805	CARBON 15	90689	223/5.56	30-Dec-10	N	S	16-Apr-13	16-Apr-13	Went Automatic	Broken or Missing Parts	307881	F	
0003	Criticol 1 43	50005	220/5:50	DO DEC XO	0.54	-	20 rpi 23	2079123	Trens Platoritatio	Altered Adjustments or	307002	-11	Per Ilion - Quote to repair
8807	700	n/a	6MM REM	1-May-74	N	s	17-Apr-13	17-Apr-13	Fired on Safe Release	Components	307957	F	
8808	XP100	25387	260 REM	18-Nov-97	Y	s		17-Apr-13	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	308113	F	Per Ilion - Quote to repair @ 1/2 normal cost
										1000			Per Ilion, quote to repair,
8809	788	n/a	22-250 REM	10-Mar-65	Y	s	17-Apr-13	17-Apr-13	Fired on Bolt Closing	Improper Assembly by Customer	308101	F	1402
			essumment.	222222		dec	CONTRACTOR		Fired on Bolt	and the state of t			Replacing with new 85651 on
8810	770	85651	243 WIN	30-Oct-12	N	S	17-Apr-13	18-Apr-13	Opening	Fired on Bolt Opening	308112	F	
8811	700	n/a	6MM REM	17-Sep-78	N	s	17-Apr-13	23-Apr-13	Fired on Safe Release	Could Not Duplicate Concern	308687	F	
			22-250										Repair @ n/c - goodwill
8814	700	n/a	REM	1-Jan-72	N	PD/S	17-Apr-13	2-May-13	Fired on Bolt Closing	Improper Maintenance	309376	F	gesture
8816	770	85633	3006 SPRG	15-Apr-11	N	s/c	18-Apr-13	18-Apr-13	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	308283	F	Per Ilion, replace TPA and bolt assm, test fire at no charge as goodwill
									Delayed Firing -				Quote to repair @ 1/2
8820	700	25793	3006 SPRG	1-Oct-85	N	S	18-Apr-13	18-Apr-13	Firearms	Improper Maintenance	308217	F	normal cost
8825	40X	87920	308 WIN	14-Apr-10	N	s	22-Apr-13	22-Apr-13	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	308507	F	Per Ilion - Repair as needed at n/c
			22-250	117		1	1.5	- 25		Altered Adjustments or			Per Ilion - Quote to repair
8827	700	n/a	REM	1-Feb-75	N	S	22-Apr-13	22-Apr-13	Fired on Safe Release	Components	308665	F	under BLM
estatue.			7MM REM	H-1850 7953		- 000	5-3900 1530			escapeo e estropologico.			Per Release: Replace gun
8829	710	27412	MA	10-Jun-05	Υ	5	22-Apr-13	25-Oct-13	Fired on Safe Release	Broken or Missing Parts	324000	F	w/Item# 85635
8833	721	n/a	3006 SPRG	1-Aug-49	Y	s	23-Apr-13	23-Apr-13	Fired on Bolt Closing	Could Not Duplicate Concern	308739	F	Replace TPA, clean and test at BLSM program price
8834	700	n/a	270 WIN	1-May-62	N	s	23-Apr-13	23-Apr-13	Fired on Safe Release	Could Not Duplicate Concern	308740	F	Replace TPA, clean and test at BLSM program price
							11-			Altered Adjustments or		100	Per Ilion - Quote to repair
8836	721	n/a	3006 SPRG	1-May-56	Y	S	23-Apr-13	23-Apr-13	Fired on Safe Release	Components	308770	F	under BLM

8838	700	n/a	223 REM	1-Jan-98	N	S	23-Apr-13	10-May-13	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	310406	F	Per Ilion, can offer to replace TPA, clean, test at 1/2 norma cost
8840	870	24952	12 GA	26-Oct-00	N	s	24-Apr-13	24-Apr-13	Fired With Safe ON	Aft Mkt Safety	308771	F	Per Ilion, offer to replace TPA at 1/2 normal cost
8841	597	26513	22 LR	9-Feb-13	N	5	24-Apr-13	24-Apr-13	Went Automatic	Could Not Duplicate Concern	308830	F	Per Ilion - Repair as needed - warranty
8842	700	n/a	3006 SPR	26-Feb-80	N	S	24-Apr-13	24-Apr-13	Fired on Bolt Closing	Improper Maintenance	308788	F	Per Ilion, replace trigger assembly, clean and test fire at BLSM price
8845	700	n/a	243 WIN	1-Sep-68	N	5	24-Apr-13	24-Apr-13	Fired on Safe Release	Improper Maintenance	308789	F	Replace TPA, clean and test at BLSM program price
8846	700	n/a	7MM REM MA	1-Jun-75	N	s	24-Apr-13	24-Apr-13	Fired on Safe Release	Could Not Duplicate Concern	308787	F	Per Ilion, replace TPA, clean, test at BLSM program price
8851	700	n/a	7MM REM MA	4-Jun-75	N	S	26-Apr-13	26-Apr-13	Fired on Safe Release	Could Not Duplicate Concern	309019	F	Per Ilion, replace TPA, clean and test at BLSM program price
8855	XM15E2S	n/a	223/5.56	21-Jul-06	N	s	26-Apr-13	26-Apr-13	Other - Firearms	Could Not Duplicate Concern	309014	F	Per Ilion, check over completely, repair as needed at no charge
8857	770	n/a	243 WIN		N	PI/S	26-Apr-13	9-May-13	Unexplained Discharge - No Mention of Safety Position	No Fault Found	n/a	F	Per Derek Watkins - No Fault Found
8861	700	85541	300 WIN	6-Feb-13	N	s	29-Apr-13	29-Apr-13	Fired on Bolt Closing	Could Not Duplicate Concern	309191	F	
8864	700	26133	7MM REM MA	24-Jun-00	N	s	30-Apr-13	30-Apr-13	Fired on Bolt Closing	Could Not Duplicate Concern	309377	F	Per Ilion, can offer to replace TPA, clean and test at 1/2 normal cost
8866	CARBON 15	90689	223/5.56	5-Mar-13	N	s	30-Apr-13	30-Apr-13	Fired With Safe ON	Fired on safe	309271	F	Per Ilion, repair/adjust as needed, test fire at no charge under warranty
													Per Ilion, offer to replace TPA clean and test at 1/2 normal
8868	700	27518	243 WIN	9-Jun-00	N	S	30-Apr-13		Fired on Bolt Closing	Improper Maintenance Not Examined by Product	309324	F	cost Gun not returned to Ilion for
8869	700	n/a	3006 SPRG		N	PD/S	30-Apr-13	18-Feb-14	Fired on Safe Release	Service Could Not Duplicate	n/a	F	exam Replace TPA, clean, test at
8875	700	n/a	270 WIN	2-Jun-81	N	S	2-May-13		Fired on Safe Release	Concern Altered Adjustments or	309422	F	BLSM program price Replace TPA, clean and test
8876	700	n/a	3006 SPRG	1-Jun-83	N	5	2-May-13	2-May-13	Fired on Safe Release	Components	309155	F	Can offer to replace TPA,
8881	700	27477	308 WIN	22-Feb-06	N	S	6-May-13	6-May-13	Fired on Safe Release	Could Not Duplicate Concern	309919	F	clean and test at 1/2 normal cost
		0.40							Unexplained Discharge - No Mention of Safety				Per Ilion, replace TPA, clean and test at BLSM program
8882	700 597	n/a 26562	3006 SPRG	1-Jul-63 12-May-05	N	5	6-May-13 7-May-13	6-May-13 7-May-13	Position Fired Out of Battery	Other - Unspecified or Undetermined - Firearms	309962	F	price Per Ilion, check over completely, repair as needed at no charge
8885	CARBON 15	90689	223/5.56	10-Nov-12	N	s	7-May-13		Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	310020	F	Check over completely, repair as needed at no charge under warranty
8887	700	n/a	3006 SPRG	1-Jun-69	N	PD/S	7-May-13	4-Jun-13	Fired on Safe Release	Could Not Duplicate Concern	311839	F	BLM @ n/c - goodwill gesture

			7MM REM							Could Not Duplicate			Per Ilion, will replace TPA, check over and test fire at no
8890	770	85657	MA	27-Jun-11	N	S	8-May-13	8-May-13	Fired With Safe ON	Concern	310186	F	charge
8892	710	27410	3006 SPRG	15-Sep-05	N	S	8-May-13	8-May-13	Fired on Safe Release	Altered Adjustments or Components	310218	F	Per Ilion, offer to replace TPA clean and test at 1/2 normal cost
													Per Ilion, replace TPA, clean and test under recall at no
8895	600	n/a	308 WIN	1-Jan-66	Υ	S	9-May-13	9-May-13	Fired on Bolt Closing	Improper Maintenance	310260	F	
8896	700	n/a	308 WIN	1-Sep-71	N	s	9-May-13	9-May-13	Fired on Bolt Opening	Altered Adjustments or Components	310358	F	Per Ilion, replace TPA, clean and test at BLSM program price
8900	597	26516	17 HMR	11-Nov-04	N	S	10-May-13	15-May-13	Fired Out of Battery	Other - Unspecified or Undetermined - Firearms	310440	F	
8902	710	27418	243 WIN	18-Jul-06	N	S	10-May-13	10-May-13	Fired on Bolt Closing	Could Not Duplicate Concern	309547	F	Per Ilion, offer to repair/adjust/clean as needed and test fire at 1/2 normal cost
8905	700	25709	308 WIN	25-Feb-02	N	s	10-May-13	10-May-13	Fired on Safe Release	Improper Maintenance	310378	F	Per Ilion, offer to replace TPA clean and test at 1/2 cost
0000	700	25793	3006 SPRG			S			Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate	210500	F	Per Ilion, offer to replace TPA clean and test at 1/2 normal cost
8909	700	25/93	3000 SPRG	4-Jan-90	N	3	13-IVI0Y-13	13-May-13	Fired on Bolt	Concern	310609		Replace TPA, clean and test
8913	700	n/a	MA	1-Dec-69	N	S	14-May-13	14-May-13	Opening	Improper Maintenance	310632	F	
8914	700	n/a	270 WIN	17-Jun-81	N	s	15-May-13	15-May-13	Fired on Safe Release	Could Not Duplicate Concern	310762	F	Per Ilion, replace TPA, clean and test at BLSM program price
8915	600	n/a	308 WIN	1-Sep-66	Y	S	15-May-13	15-May-13	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	310865	F	Replace TPA, clean and test under recall at no charge Per Ilion - Clean & Adjust at
8916	742	n/a	3006 SPRG	27-Apr-79	Y	S	15-May-13	15-May-13	Fired With Safe ON	Improper Maintenance	310872	F	
8922	700	n/a	308 WIN	1-Aug-66	N	s	17-May-13	17-May-13	Fired on Bolt Closing	Improper Maintenance	310996	F	Per Ilion - Quote to repair under BLM
8925	1100	n/a	12 GA	1-Nov-94	N	s	17-May-13	17-May-13	Fired on Bolt Closing	Could Not Duplicate Concern	311099	F	Per Ilion, repair as needed at 1/2 normal cost as goodwill gesture
8928	700	n/a	3006 SPR	1-Apr-67	N	s	17 14 17	15 (-) 13	Fired on Safe Release	Sent in for Evaluation	314735	F	Per Ilion - Quote to repair under BLM
8928	H&R Handi- Rifle SB2	72582	45/70 GOV	4-Mar-11	N	5		15-Jul-13 21-May-13	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	311248	F	Per Ilion, check over completely, repair as needed at 1/2 normal cost
0022	870	26960	12 GA		N	nu (c	21 14	39 to 44	Fired With Safe ON	Not Examined by Product		F	Gun not returned to Ilion for exam
8933	8/0	20900	12 04		1.A	PI/S	£1-Way-13	28-Jan-14	riidd with said ON	Service	n/a	-	Per Ilion - Repair & clean @
8934	700ML	27572	50 CAL	30-Jan-98	Υ	S	22-May-13	12-Jun-13	Fired on Safe Release		313119	F	n/c
8938	700	n/a	243 WIN	1-May-69	N	s	29-May-13	29-May-13	Fired on Bolt Closing	Altered Adjustments or Components	311860	F	
8939	1911 R1	96323	45 ACP	27-Mar-12	N	s	29-May-13	29-May-13	Defective Parts	Sent in for Evaluation	311742	F	Per Ilion, repair/adjust as needed at no charge
8942	700	n/a	7MM REM MA	1-May-67	N	s			Fired on Safe Release		311662	F	Per Ilion - Quote to repair under BLM
8943	700	n/a	3006 SPRG	1-May-69	N	5	29-May-13	29-May-13	Fired With Safe ON	Improper Maintenance	311976	F	Per Ilion - Quote to repair under BLM

					-				Unexplained				Per Ilion, to restore
									Discharge - No				confidence, replace trigger
	500000		W77770	47.45	10334	- 65	POWER CO.		Mention of Safety	Could Not Duplicate			assembly, check over and te
8947	M 24	25705	7.62	20-Jan-06	N	S	30-May-13	30-May-13	Position	Concern	312023	F	fire
	H&R Handi-								Action Opened on				
8953	Rifle	72790	17 HMR	3-Mar-10	N	PI/5	3-Jun-13	24-Jun-13	Firing	Sent in for Evaluation	311787	F	Repair as needed @ n/c
										Altered Adjustments or			Replace TPA, clean and test
8954	721	n/a	3006 SPRG	1-Jun-51	Υ	5	3-Jun-13	3-Jun-13	Fired on Bolt Closing	Components	312249	F	at BLSM program price
			5233757						12000000000000000000000000000000000000	W			Per Ilion, replace barrel,
	********		300	22 123 123 12 134					Bullet Lodged in	Inadequate or Lack of			receiver assm and test at ne
8958	700	84205	BLACKO	29-Nov-12	N	S	4-Jun-13	4-Jun-13	Barrel	Powder	312298	F	charge
													Per Ilion, replace TPA, clear
	12.000	2.40			1007	10	8109798201	F4777755		0.0000000000000000000000000000000000000		1.0	and test at BLSM program
8963	700	n/a	6MM REM	1-Nov-67	N	S	5-Jun-13	5-Jun-13	Fired on Bolt Closing	Improper Maintenance	312514	F	price
													Per Ilion, offer to replace TPA
0057	700	2.6	3000 5000	74.0-4.00				61 - 12	Florida - Bolk Classes		242550		clean and test at 1/2 norma
8967	700	n/a	3006 SPRG	24-Oct-88	N	S	6-Jun-13	6-Jun-13	Fired on Bolt Closing	Improper Maintenance	312560	F	cost Per Ilion, replace TPA, clean
										Altered Adjustments or			and test at BLSM program
8969	721	n/a	3006 SPRG	1-May-52	Y	S	6-Jun-13	6-Jun-13	Fired on Safe Release	Components	312527	F	-1055
0303	722	7,044	3000 31110	A-IVIUY-DE	·	-	0.3011-23	0-7011-23	Fired Oil Saile Release	components	SAEJEI	-	price
										Altered Adjustments or			Per Ilion, replace TPA, clean
8970	722	n/a	222 REM	1-Mar-51	Y	5	7-Jun-13	7-Jun-13	Fired on Bolt Closing	Components	312814	F	test at BLSM program price.
							1.3.00.00					1	Per Ilion, offer to replace TPA
										Altered Adjustments or			clean and test at 1/2 norma
8973	700	27518	243 WIN	10-Dec-98	N	S	10-Jun-13	10-Jun-13	Fired on Safe Release	Components	312965	F	cost
													Per Ilion, offer to replace TPA
										Could Not Duplicate			clean and test at 1/2 normal
8981	700	25791	270 WIN	1-Mar-84	N	S	11-Jun-13	11-Jun-13	Fired on Safe Release	Concern	313109	F	cost
									Jamming/Feeding	Other - Unspecified or			
8982	597	80877	22 LR	28-Jun-12	N	5	11-Jun-13	13-Jun-13	issues	Undetermined - Firearms	313019	F	
	700	25.202	2005 500	value orașe	9860	122				Not Examined by Product	2000	F	Gun not returned to Ilion fo
8983	700	25793	3006 SPR	6-Jun-96	N	S	11-Jun-13	14-Apr-15	Fired on Safe Release	Not Examined by Product	n/a	F	exam Gun not returned to Ilion fo
8985	700	25801	17 REM	6-Dec-02	N	s	11-jun-13	14 Apr 15	Fired on Bolt Closing	Service	n/a	F	exam
0202	700	23801	17 NEIVI	0°D00°02	14	3	11-1011-15	14-Mp1-13	Fired on boil closing	Service	nya	- F	Per Ilion, replace TPA, clean
										Could Not Duplicate			and test at BLSM program
8987	700	n/a	243 WIN	1-Apr-64	N	S	13-Jun-13	13-Jun-13	Fired on Bolt Closing	Concern	313301	F	
		7.9.4	350 REM				20,301.00	20.7017,00	Theo on continuing	Altered Adjustments or		-	Per Ilion - Replace TA, clean 8
8991	660	n/a	MA	1-Mar-69	Y	s	18-Jun-13	18-Jun-13	Fired on Bolt Closing	Components	313573	F	
		100000											7011000000000
										Other - Unspecified or			Per Release: Replace gun
8992	597	26560	22 WMR	6-Sep-07	N	PI/S	18-Jun-13	20-Aug-13	Fired Out of Battery	Undetermined - Firearms	313622	F	w/Item# 84370
	800000		1997/8/2/2001/0	terminaer	2513	- 22	enance con-		ali no se casa se como e	12230 1222-1223-1223-123		100	Per Ilion - Quote to repair
8994	722	n/a	222 REM	1-Feb-53	Υ	S	19-Jun-13	19-Jun-13	Fired on Safe Release	Improper Maintenance	313688	F	under BLM
											The street of the		Per Iloin - Quote to repair @
8995	700	25795	308 WIN	1-Nov-85	N	S	19-Jun-13	21-Jun-13	Fired on Bolt Closing	Improper Maintenance	313717	F	1/2 normal cost
													Replace TA, clean & test to
										Could Not Duplicate			restore confidence in rifle a
8996	700	86447	7.62 NATO	14-Feb-13	N	S	19-Jun-13	21-Jun-13	Fired on Safe Release	Concern	313739	E	no charge - goodwill gesture
	7700	Martine .		21100.13	***	-	20 7411-23	24.700.40	The state of the state of		- Walter Colors	- 1	Becaum Besture
													Replace TA, clean & test to
										Could Not Duplicate			restore confidence in rifle at
8999	700	86447	7.62 NATO	14-Feb-13	N	5	19-Jun-13	21-Jun-13	Fired on Safe Release		313751	F	no charge - goodwill gesture
												10	Per Derek Watkins - Rifle is
9004	700	84203	308 WIN	29-Jan-13	N	S	24-Jun-13	23-Jul-13	Fired on Bolt Closing	No Fault Found	n/a	F	not malfunctioning
										Could Not Duplicate	Later Date of the Control of the Con		Per Ilion - Replace TA @ n/c
9006	710	27410	3006 SPRG	20.0	Y	5	20.00		Fired on Safe Release	Concern	314131	F	goodwill gesture

0000	700	25807	300 WIN	43.405		-	25 1 - 12	25 1 12	Fired Make Feder Obj	Could Not Duplicate	214172		Per Ilion - Quote to repair @
9009	/00	25807	MA	12-Apr-95	N	S	26-Jun-13	26-Jun-13	Fired With Safe ON	Concern	314172	F	
9010	700	n/a	270 WIN	1-Nov-71	N	s	26-Jun-13	26-Jun-13	Fired on Safe Release	Could Not Duplicate Concern	314224	F	Per Ilion - Quote to repair under BLM
9016	700	n/a	270 WIN	1-Jun-78	N	S	28-Jun-13	28-Jun-13	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	314410	F	Per Ilion, quote to repair BLN
										Could Not Duplicate			Replace TPA, check over and
9017	700	84017	300 WSM	5-Feb-10	N:	S	28-Jun-13	28-Jun-13	Fired on Bolt Closing	Concern	314308	F	test at no charge
									725	Could Not Duplicate			=======================================
9028	XM15-E2S	N/A	223/5.56	26-Nov-08	N	5	12-Jul-13	25-Jul-13	Went Automatic	Concern	316150	F	Replacing trigger at no charg
9030	700	25793	3006 SPRG	1-Apr-84	N	s	15-Jul-13	15-Jul-13	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	314864	F	Offer to replace trigger assembly, clean, and test at 50% discount
	770	05530	24214004	2.11		- 2			5	F	*****		Barrier and the state of the state of
9032	770	85630	243 WIN 7MM REM	14-Mar-07	N	S	15-Jul-13	15-Jul-13	Fired on Safe Release	Sent in for Evaluation	315163	F	Per Ilion, repair at no charge
9033	700	nla	MA	20.0-4.25			10 (4) 12	15 14 12	Fired on Safe Release	Altered Adjustments or Components	315000		Day Ilian musta to service DIS
9033	/00	n/a	IVIA	20-Oct-76	N	S	15-Jul-13	15-Jul-13	Fired on Sare Kelease	Components  Could Not Duplicate	315099	F	Per Ilion, quote to repair BLN
9035	700	n/a	6MM REM	1.5 70	N	s	15-Jul-13	15-Jul-13	Fired on Safe Release	Concern	314607		Per Ilion, quote to repair BLN
9035	700	n/a	DIVITAL KEIAI	1-Sep-78	N	3	15-Jul-13	15-Jul-13	Unexplained	Concern	314607	- 1	Per Illon, quote to repair BLIV
9036	XM15-E2S	90391	223/5.56	25-Mar-13	N	s	15-Jul-13	15-Jul-13	Discharge - No Mention of Safety Position	Could Not Duplicate Concern	314816	F	Per Ilion - Quote to repair @ 50% discount
										Altered Adjustments or			
9039	600	n/a	243 WIN		Υ	S	16-Jul-13	16-Jul-13	Fired on Safe Release	Components	315470	F	Per Ilion, repair at no charge
1.0000-0			2013300000000	0.0000000000000000000000000000000000000			THE STATE OF		CATTRIL TO USARDA	Could Not Duplicate			
9044	700	n/a	3006 SPRG	1-Oct-72	N	S	17-Jul-13	17-Jul-13	Fired on Safe Release	Concern	315522	F	Per Ilion, quote to repair BLN
										Altered Adjustments or			
9045	700	n/a	270 WIN	1-Jan-67	N	S	18-Jul-13	18-Jul-13	Fired on Safe Release	Components	314861	F	Per Ilion, quote to repair BLN
9046	7	29539	223 REM	26-Apr-04	N	s	18-Jul-13	18-Jul-13	Fired on Bolt Closing	Altered Adjustments or Components	315248	F	Offer to replace trigger assembly, clean, and test at 50% discount
			375 H&H						Fired on Bolt	Could Not Duplicate		-10	
9047	700	n/a	MA	1-Jun-77	N	S	18-Jul-13	18-Jul-13	Opening	Concern	315257	F	Per Ilion, quote to repair BLN
										Other - Unspecified or			Repair as needed at no
9049	597	26550	22 LR	10-Aug-10	N	S	18-Jul-13	18-Jul-13	Fired Out of Battery	Undetermined - Firearms	315601	F	charge
9050	514	80808	22 RF	21-Sep-11	N	S	18-Jul-13	18-Jul-13	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	315151	F	Check over completely and repair as needed at no charge
9053	700	n/a	3006 SPRG	1-Sep-73	N	5	19-Jul-13	19-Jul-13	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	314364	F	
9054	700	n/a	3006 SPRG	1-Nov-83	N	s	19-Jul-13	19-Jul-13	Safety not working properly	Improper Maintenance	315709	F	Replace trigger assembly, clean, and test fire at 1/2 normal cost
										Could Not Duplicate			Replace trigger assembly, clean and test fire under bolt
9055	700	n/a	3006 SPRG	1-Feb-79	N	S	22-Jul-13	22-Jul-13	Fired on Safe Release	Concern	315566	F	lock program
9057	700	25803	7MM REM MA	14-Oct-86	N	s	23-Jul-13	23-Jul-13	Fired Out of Battery	Improper Maintenance	315924	F	Per Ilion - Quote to repair @ 1/2 normal cost for trigger, clean & test
9058	700	27476	270 WIN	4-Apr-03	N	PD/S	23-Jul-13	25-Sep-13	Fired on Bolt Closing	Altered Adjustments or Components	321344	F	Offer to replace trigger assembly and check over at 50% discount

						-				Not Examined by Product			Gun not returned to Ilion for
9060	700	29663	308 WIN	13-Dec-07	N	S	23-Jul-13	15-Apr-15	Fired on Safe Release	Service	n/a	F	exam
									Unexplained Discharge - No Mention of Safety		100-31-1		Replace trigger assembly, clean, and test fire under bo lock program for \$20.00 +
9062	700	n/a	308 WIN	16-Mar-78	N	S	24-Jul-13	24-Jul-13	Position	Improper Maintenance	316104	F	shipping,
9063	7	24741	7MM08 REM	14-Mar-01	N	5	25-Jul-13	25-Jul-13	Fired on Safe Release	Could Not Duplicate Concern	316153	F	Replace TPA, check over and test at no charge
9068	600	n/a	308 WIN	10-Oct-75	N	s	26-Jul-13	26-Jul-13	Fired on Safe Release	Improper Maintenance	316313	F	Replace trigger assembly, clean, and test fire under bo lock program for \$20.00 + shipping.
9074	700	25771	270 WIN	1-Aug-85	N	s	29-Jul-13	29-Jul-13	Fired on Safe Release	Improper Maintenance	316457	F	Per Ilion - Quote to repair
9078	700	n/a	3006 SPRG	1-Jul-74	N	s	31-Jul-13	31-Jul-13	Fired on Bolt Closing	Could Not Duplicate Concern	316637/316638	F	Per Ilion, quote to repair BLN
9079	710	27408	270 WIN	5-Mar-03	N	5	31-Jul-13	31-Jul-13	Fired on Bolt Closing	Improper Maintenance	316658	F	Offer to remove trigger assembly, clean, and test at 50% discount
	27007			and the contract of the	100					Could Not Duplicate			
9081	XM15-E2S	90289	223/5.56	28-Jun-13	N	S	1-Aug-13	1-Aug-13	Went Automatic	Concern	316760	F	Per Ilion, repair at no charge Offer to replace trigger
9085	700	25829	243 WIN	16-Mar-89	N	s	5-Aug-13	5-Aug-13	Fired on Safe Release	Altered Adjustments or Components	316908	F	assembly, clean, and test at
9086	700	N/A	7MM REM MA	1.10	N	s	F A 12	E Aug 12	Fired on Bolt Opening	January Maintenance	216022		Decilies and to see a PLA
				1-Nov-62			5-Aug-13	5-Aug-13	Safety not working	Improper Maintenance	316832		Per Ilion, quote to repair BLN
9087	700	27582	54 CAL	31-Jul-97	N	S	5-Aug-13	5-Aug-13	properly	Broken or Missing Parts	316907	F	Per Ilion, repair at no charge
9093	700	25771	270 WIN	8-Nov-90	N	s	6-Aug-13	6-Aug-13	Delayed Firing - Firearms	Improper Maintenance	316964	F	Replace trigger assembly, clean, and test at 50% discount
2023	700	23//1	270 99119	81107130	14	- 3	0-Muli-13	D-MUK-13	Filedille	improper maintenance	310304		discount
9094	700	27491	223 REM	5-Feb-03	N	s	6-Aug-13	6-Aug-13	Fired on Bolt Opening	Other - Unspecified or Undetermined - Firearms	316966	F	Per Ilion - Repair @ n/c Repair as needed at no
9095	CARBON 15	90689	223/5.56	9-Dec-10	N	s	6-Aug-13	6-Aug-13	Went Automatic	Broken or Missing Parts	317006	F	charge
9098	CARBON 15	90689	223/5.56	19-Jul-12	N	s	7-Aug-13	7-Aug-13	Went Automatic	Sent in for Evaluation	317051	F	
9099	1911 R1	96324	45 ACP	11-Feb-13	N	s	7-Aug-13	7-Aug-13	Fired With Safe ON	Broken or Missing Parts	317105	F	Repair as needed at no charge
9102	700	84019	257 WBY MA	8-Jun-10	N	s	8-Aug-13	16-Apr-15	Fired on Safe Release	Not Examined by Product Service		F	Gun not returned to Ilion for exam
9104	VERSA-MAX	81048	12 GA	5-May-11	N	s	9-Aug-13	9-Aug-13	Fired on Bolt Closing	Broken or Missing Parts	317273	F	Repair as needed at no charge
9105	660	N/A	243 WIN	1-May-68	Y	s	9-Aug-13	9-Aug-13	Fired on Bolt Closing	Improper Maintenance	317317	F	Replace TPA, check over and test at no charge
9106	700	84370	223 REM	21-Jan-08	N	s	9-Aug-13	1 1	Fired on Safe Release	Could Not Duplicate Concern	318743	F	Replace TPA, check over and
9109	700	N/A	7MM REM MA	20-Sep-76	N	5			Fired on Safe Release	Altered Adjustments or Components	317958	F	Replace trigger assembly, clean, and test fire under bo lock program for \$20.00 + shipping.
													Offer to replace trigger assembly, clean, and test at
9114	700	27518	243 WIN	30-May-03	N	S	15-Aug-13	15-Aug-13	Fired on Bolt Closing	Improper Maintenance	318086	F	50% discount
9117	600	n/a	243 WIN	1-Jun-77	Y	s	19-Aug-13	19-Aug-13	Fired on Safe Release	Altered Adjustments or Components	318354	F	Replace TPA, clean, and test under recall at no charge
9123	700	84203	308 WIN	19-Jul-13	N	s	19-Aug-13	6-Sep-13	Fired on Safe Release	Other - Unspecified or Undetermined - Firearms	320305	F	Per Ilion - Replace in exchange, ramac 84203

9121	770	85633	3006 SPRG	8-Feb-13	N	PD/S	19-Aug-13	15-Apr-15	Fired on Bolt Closing	No Fault Found	n/a	F	Gun not returned to Ilion
9124	887	82502	12 GA	3-Jun-10	N	s	20 Aug 12	20-Aug-13	Fail to Fire	Could Not Duplicate Concern	318571	F	Replace TPA, check over and test at no charge
3124	007	02302	12.04	3-7011-10	14	3	20-A0K-13	20-MUE-13	Pali to Fire	Could Not Duplicate	3103/1	- 1	Replace TPA, check over and
9125	700	27363	3006 SPRG	8-Aug-11	N	S	20-Aug-13	20-Aug-13	Fired on Bolt Closing	Concern	318559	F	test at no charge
9126	700	n/a	3006 SPRG	7-Feb-79	N	S	20-Aug-13	20-Aug-13	Fired on Safe Release	Altered Adjustments or Components	318542	F	Replace trigger assembly, clean, and test fire under bol lock program for \$20.00 + shipping.
9127	700	n/a	2506 REM	1-Nov-70	N	5	20 Aug 12	30 Aug 13	Fired on Safe Release	Improper Maintenance	318503	F	Replace trigger assembly under BLP for \$20.00 + shipping and replace bolt at 25% discount
9127	700	nya	2506 REIVI	1-1404-70	N	3	20-Aug-13	20-Aug-13	Fired on Sale Release	improper iviaintenance	318303	- 1	Replace trigger assembly,
9129	700	n/a	7MM REM MA	1-0ct-71	N	s	20-Aug-13	20-Aug-13	Fired on Safe Release	Improper Maintenance	318410	F	clean, and test fire under bolt lock program for \$20.00 +
	2000								Unexplained Discharge - No Mention of Safety				Quote to clean TA & ck function only, Customer said
9135	742	n/a	3006 SPRG	1-Apr-74	Υ	5	23-Aug-13	23-Aug-13	Position Unexplained	Improper Maintenance	318925	F	Return as Received
9136	700	n/a	243 WIN	3-Jun-76	N	S	26-Aug-13	26-Aug-13	Discharge - No Mention of Safety Position Unexplained	Improper Maintenance	318973	F	Quote to repair under BLM
9139	600	n/a	6MM REM	1-Jul-73	Y	S	27-Aug-13	27-Aug-13	Discharge - No Mention of Safety Position	Improper Maintenance	319127	F	
	700	27004	22011111							Could Not Duplicate	*****		Per Ilion - Replace TA @ n/c
9140	700	27094	270 WIN	18-Jul-12	N	S	27-Aug-13	27-Aug-13	Fired on Safe Release	Concern	319065	F	to restore confidence Offer to replace trigger
9142	722	N/A	300 SAV	1-Nov-48	Y	S	28-Aug-13	28-Aug-13	Fired With Safe ON	Improper Maintenance	319199	F	assembly, clean, and test at 50% discount
9162	700	20000	223 REM		N	s	28-Aug-13	14-Apr-15	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
9059	710	27410	3006 SPRG	17-Jan-03	Y	PD/S		10-Sep-13	Unexplained Discharge Safe ON	Could Not Duplicate Concern	319385	F	Replace rifle w/85633 in
9145	700	27333	300 WSM	28-Aug-10	N	S		29-Aug-13	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	319028	F	Repair as needed at no charge and test fire
9149	700	N/A	270 WIN	10-Sep-79	N	S	29-Aug-13	29-Aug-13	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	319399	F	Replace trigger assembly, clean, and test fire under boll lock program for \$20.00 + shipping.
9152	700	N/A	7MM REM MA	1-Apr-71	N	S	30-Aug-13	30-Aug-13	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	319507	F	
9154	700	85335	270 WIN	26-Jun-12	N	s	20. Δυσ. 12	17-Sep-13	Ammunition Exploded	Sent in for Evaluation	319491	A	Repair as needed at no charge and test fire
A. J. WOOD	TORINA	ecus.	20000000				200.00 70000			Altered Adjustments or	escentrono I		Replace trigger assembly under BLP for \$20.00 + shipping and repair magazine
9158	700	N/A 25773	222 REM 3006 SPRG	1-Jan-75 9-Oct-97	N	5	4-Sep-13 4-Sep-13	4-Sep-13	Fired on Bolt Closing Fired on Safe Release	Components  Could Not Duplicate Concern	319582 319617	F	at 50% discount  Offer to replace trigger assembly, clean, and test at 50% discount

9160	700	N/A	270 WIN	13-Jan-81	N	S	4-Sep-13	4-Sep-13	Fired on Safe Release	Could Not Duplicate Concern	319629	F	Replace trigger assembly, clean, and test fire under bolt lock program for \$20.00 + shipping.
9161	700	N/A	3006 SPRG	11-Jun-80	N	S	4-Sep-13	4-Sep-13	Fail to Fire	Could Not Duplicate Concern	319647	F	Replace trigger assembly, clean, and test fire under bol lock program for \$20.00 + shipping.
9166	7	N/A	7MM-08 REM	28-Oct-02	N	s	5-Sep-13	5-Sep-13	Fired on Safe Release	Altered Adjustments or Components	319768	F	Offer to replace trigger assembly, check over, and test at 50% discount
9169	750	27057	308 WIN	6-Mar-09	N	s	6-Sep-13	6-Sep-13	Went Automatic	Could Not Duplicate Concern	320086	F	Replace TPA, check over and test at no charge
9170	721	N/A	3006 SPRG	1-Feb-53	Y	s	6-Sep-13	6-Sep-13	Fired With Safe ON	Altered Adjustments or Components Could Not Duplicate	320303	F	Replace trigger assembly, check over, and test fire under bolt lock program for \$20.00 + shipping. Replace TPA, check over and
9176	700	29663	308 WIN	6-Mar-13	N	S	9-Sep-13	23-Sep-13	Fired on Bolt Closing	Concern	321706	F	test at no charge
9183	700	27580	50 CAL	6-Aug-96	N	s	11-Sep-13	11-Sep-13	Fired on Safe Release	Sent in for Evaluation	320590/320575	F	Replace trigger and check over at no charge
9185	700	N/A	338 WIN	1-Jul-62	N	S	11-Sep-13	11-5ep-13	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	320685	F	Replace trigger assembly under BLP for \$20.00 + shipping and replace bolt at 50% discount
9187	597	26536	17 HMR	3-Jun-03	N	S	13-Sep-13	17-Sep-13	Fired With Safe ON	Other - Unspecified or Undetermined - Firearms	320921	F	Converting to 22 WMR as requested by customer, repair and check over completely at no charge.
9192	597	26513	22 LR	1-Jul-13	N	s	16-Sep-13	16-Sep-13	Went Automatic	Other - Unspecified or Undetermined - Firearms	321037/325496	F	Replace TPA, check over and test at no charge / Replace with Ramac 26513 in exchange
9193	700	N/A	308 WIN	14-Mar-77	N	5	16-Sep-13	16-Sep-13	Fired on Safe Release	Improper Maintenance	321052	F	Replace trigger assembly, check over, and test fire under bolt lock program for \$20.00 + shipping.
9156	700	n/a	3006 SPRG	1-Sep-76	N	s	17.5 17	17.5 17	Fired on Safe Release	Altered Adjustments or Components	321167	F	Per Ilion - Quote to repair under BLM
9195	7	24782	243 WIN	25-May-90		s			Fired on Bolt Closing	Could Not Duplicate Concern	321159	F	Offer to replace trigger assembly, check over, and
9200	700	not avail.	243 WIN	16-Oct-08	N	5	18-Sep-13	18-Sep-13	Fired on Safe Release	Altered Adjustments or Components	321356	F	Offer to replace trigger assembly, check over, and test at 50% discount
9201	700	84173	3006 SPRG	29-Apr-09	N	5	18-Sep-13	18.5cn.13	Fired on Safe Release	Could Not Duplicate Concern	321319	F	Replace TPA, check over and test at no charge
5201	700	01275	3000 37 110	25 Apr 05		-	10-3ср-13	10 3cp 13	THEO OF SINC NECOSC	Concern	321313		Check over completely, and
9205	CARBON 15	90863	223/5.56	19-Dec-12	N	s	20-Sep-13	20-Sep-13	Went Automatic	Sent in for Evaluation	321662	F	repair as needed at no charge Replace trigger assembly,
9206	700	N/A	3006 SPRG	12-Oct-78	N	PI/S	20-Sep-13	20-Sep-13	Fired on Bolt Closing	Improper Maintenance	321608	F	clean, and test fire under bolt lock program for \$20.00 + shipping.
9214	597M	26536	17 HMR	27-Jun-03	N	s	23-Sep-13	4-Oct-13	Other - Firearms	Other - Unspecified or Undetermined - Firearms	323075	F	
9215	700	n/a	243 WIN	11-Nov-80	N	s	24-Sep-13	24-Sep-13	Fired on Safe Release	Altered Adjustments or Components	321905	F	Replace trigger assembly, clean, and test fire under bolt lock program for \$20.00 + shipping.

9217	700	N/A	7MM REM MA 3006 SPRG	1-Oct-71 27-Sep-79	N	s	24-Sep-13 24-Sep-13	24-Sep-13 8-Oct-13	Fired on Bolt Closing	Altered Adjustments or Components Altered Adjustments or Components	321933 323224	F	Replace trigger assembly, clean, and test fire under boll lock program for \$20.00 + shipping. Per Ilion - Quote to repair under BLM
5222				Li scp is						Altered Adjustments or	JEJET	Ť	Offer to replace trigger assembly, check over, and
9235	7	24781	260 REM	7-Mar-03	N	S	27-Sep-13	27-Sep-13	Fired on Safe Release	Components	322326	F	test at 50% discount
9237	700	25793	3006 SPRG	1-Oct-84	N	s	27-Sep-13	27-Sep-13	Fired on Bolt Closing	Improper Maintenance	322345	F	Offer to replace trigger assembly, check over, and test at 50% discount
9243	597M	26514	17 HMR	29-Jan-04	N	s	30-Sep-13	11-Oct-13	Other - Firearms	Other - Unspecified or Undetermined - Firearms	323630	F	
9245	887	82500	12 GA	11-Jun-13	N	5	30 Can 13	22-Oct-13	Delayed Firing - Firearms	Could Not Duplicate Concern	324796	F	Replace TPA, check over and test at no charge
3243	007	82300	12 GA	11-3011-13	14	3	20-26h-12	22.001.13	Filedillo	Concern	324730	- 10	test at no charge
9207	700ML	27580	50 CAL	11-Sep-96	Υ	s	1-Oct-13	1-Oct-13	Fired on Safe Release	Other - Unspecified or Undetermined - Firearms	322598	F	Replace trigger and check over at no charge
9247	700	N/A	7MM REM MA	1-May-74	N	s	1-Oct-13	1-0ct-13	Fired on Safe Release	Altered Adjustments or Components	322572	F	Replace trigger assembly under BLP for \$20.00 + shipping and replace trigger guard at 50% discount
	700	27077	300 WIN						First or Cata Balanca	Altered Adjustments or	222525		Burther Burth to see to
9249	700	27037	MA 300 WIN	6-Nov-06	N	S	1-Oct-13	1-Oct-13	Fired on Safe Release	Components Altered Adjustments or	322575	F	Per Ilion - Quote to repair Per Ilion - Quote to repair @
9251	700	27339	MA	22-Jul-05	N	S	1-Oct-13	21-Oct-13	Fired on Bolt Closing	Components	324650	F	a discount
9254	597M	26536	17 HMR	30-Jun-05	N	s	1-Oct-13	16-Oct-13	Other - Firearms	Other - Unspecified or Undetermined - Firearms	324090	F	Converting to 22 WMR as requested by customer
9255	700	n/a	243 WIN	1-Jun-70	N	s	1-Oct-13	15-Oct-13	Delayed Firing - Firearms	Improper Maintenance	323840	F	Per Ilion - Quote to repair under BLM
9259	887	82500	12 GA	7-Mar-13	N	S	3-Oct-13	3-Oct-13	Fired on Bolt Closing	Could Not Duplicate Concern	322897		Check over completely, and repair as needed at no charge
9262	700	25803	7MM REM MA	20-Apr-91	N	5	4-Oct-13	4-Oct-13	Delayed Firing - Firearms	Improper Maintenance	322987	F	Offer to replace trigger assembly, check over, and test at 50% discount
9263	700	27452	25-06 REM	23-Jun-00	N	s	4-Oct-13	14-Oct-13	Fired on Bolt Closing	Improper Maintenance	323730	F	Replace trigger, check over and test fire at 50% discount
9264	700	N/A	243 WIN	12-Sep-72	N	PI/S	4-Oct-13	22-Oct-13	Fired on Safe Release	Improper Maintenance	324296	F	Replace TPA, check over and test at no charge
9280	700	25803	7MM REM MA	2-Nov-89	N	s	4-Oct-13		Fired on Safe Release	Improper Maintenance	324587	F	Per Ilion - Quote to repair @ a discount
9270	700	27165	270 WIN	18-Nov-05	N	s	7-Oct-13	7-Oct-13	Fired on Safe Release	Could Not Duplicate Concern	323178	F	Replace TPA, check over and test at no charge
22.70	,,,,,	27200	27.0 11.01	23-1107-03	.,,	-	7-041-23	, -Oct-43	Action Opened on	Could Not Duplicate	JEJETO	- 1	Replacing with Ramac 85632
9271	710	27408	270 WIN	28-Apr-05	Y	S	7-Oct-13	11-Oct-13	Firing	Concern	323183	F	in exchange
9273	710	27408	270 WIN	11-Mar-03	Y	s	8-Oct-13	8-Oct-13	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	323345	F	
9274	700	N/A	270 WIN	1-Aug-68	N	5	8-Oct-13	8-Oct-13	Fired on Safe Release	Altered Adjustments or Components	323213	F	Replace trigger assembly, check over, and test fire under bolt lock program for \$20.00 + shipping.

													Offer to replace trigger
			7MM REM							Could Not Duplicate			assembly, check over, and
9275	700	25815	MA	6-Dec-89	N	S	8-Oct-13	8-Oct-13	Fired With Safe ON	Concern	323243	F	The state of the s
	700	22125	22011111	44.4						1.4000000044444400000000000000000000000	225024		Per Ilion - Quote to repair
9293	700	27476	270 WIN	26-Sep-97	N	S	8-Oct-13	1-Nov-13	Fired on Bolt Closing	Improper Maintenance	326021	F	a discount
									Unexplained Discharge - No				
			300 WIN						Mention of Safety	Altered Adjustments or			Replace trigger, check over
9285	700	27480	MA	4-Nov-96	N	S	10-Oct-13	10-Oct-13	Position	Components	323518	E	and test fire at 50% discour
2203		27 100		41101 30		-	20 001 25	20.001.23		- congenius	565510	T.	One rest in car serie discour
			300 WIN							Altered Adjustments or			Replace trigger, check over
9287	700	29694	MA	28-Jul-93	N	S	10-Oct-13	10-Oct-13	Fired on Safe Release	Components	323442	F	and test fire at 50% discour
	vovo.		2000000	150 mm - 0150		V-10-7-11	a-100 and a 100 miles	20000000000	Action Opened on	10-10-00-00-00-00-00-00-00-00-00-00-00-0		-10	No fault found, returning gu
9288	870	81112	12 GA	1-May-13	N	PI/S	10-Oct-13	17-Oct-13	Firing	Sent in for Evaluation	323527	0	The second secon
			7mm-08		and the								Per Ilion - Quote to repair @
9292	700	25799	REM	15-Aug-02	N	S	10-Oct-13	31-Oct-13		Improper Maintenance	325961	F	a discount
									Unexplained				
									Discharge - No Mention of Safety	Could Not Duplicate			
9296	582	n/a	22 RF	1-Apr-69	Υ	s	14-Oct-13	14-Oct-13	Position	Concern	323747	E	Per Ilion - Quote to repair
2220		0.9.10		27.01.00		_	27.000.20	27 001 22	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		5657 17	1	Offer to replace trigger
	78									Could Not Duplicate			assembly, check over, and
9297	SPORTSMAN	N/A	3006 SPRG	18-Dec-87	Y.	S	14-Oct-13	14-Oct-13	Fired on Safe Release	Concern	323732	F	test at 50% discount
													Offer to replace trigger
										Could Not Duplicate			assembly and check over a
9301	700	26905	243 WIN	11-Jun-96	N	S	15-Oct-13	15-Oct-13	Fired on Safe Release	Concern	323925	F	
													Offer to replace trigger
9302	700	26123	270 WIN	8-Jun-04	N	s	15 Oct 13	15-Oct-13	Fired on Bolt Closing	Altered Adjustments or Components	323841	F	assembly, check over, and test at 50% discount
9302	700	26123	270 WIN	8-Jun-04	IN	3	15-Oct-13	15-001-13	Fired on Boit Closing	Components	323841	F	Check over completely, repa
													as needed, and test fire at n
9303	CARBON 15	90689	223 REM/5.	31-Aug-13	N	S	15-Oct-13	15-Oct-13	Fired With Safe ON	Sent in for Evaluation	323919	F	
2000			THE STREET WAS	52 1106 25			15.001.15	15 001 15			200243	Ť	Per Ilion - Quote to repair @
										Altered Adjustments or			1/2 normal cost for trigger
9304	700	29698	220 SWIFT	15-Mar-93	N	S	15-Oct-13	15-Oct-13	Fired on Bolt Closing	Components	323955	F	clean & test
										9076 81 770 41		-10	
	1200000		10.000000000000000000000000000000000000				0.0000000000000000000000000000000000000		David Contact this own	Other - Unspecified or		-	Replacing with Ramac 7072
9310	597M	26514	17 HMR	9-Nov-04	N	S	16-Oct-13	31-Oct-13	Other - Firearms	Undetermined - Firearms	325959	F	
0211	700	n la	308 WIN	1 tun 11		-	17.0-12	17.0-113	Fired on Cole Belones	Could Not Duplicate Concern	224425	F	Replace TPA, check over and
9311	700	n/a	SUO VVIIV	1-Jun-11	N	S	17-001-13	17-001-13	Fired on Safe Release	Concern	324125	- 1	test at no charge Converting to 22 WMR as
													requested by customer,
										Other - Unspecified or			repair and check over
9312	597	26536	17 HMR	20-May-03	N	PD/S	17-Oct-13	17-Oct-13	Other - Firearms	Undetermined - Firearms	324153	F	
													Converting to 22 WMR as
										MARKET SAFETY OF SPECIAL SPECI			requested by customer,
									5.15410000000000000000000000000000000000	Other - Unspecified or			repair and check over
9314	597	26536	17 HMR	21-May-03	N	PD/S	17-Oct-13	17-Oct-13	Other - Firearms	Undetermined - Firearms	324263	F	completely at no charge.
													Devices TDA help devices
9317	770	85637	243 WIN	29-Nov-07	N	PD/S	21-04-12	21-Oct-13	Fired on Bolt Closing	Broken or Missing Parts	324642		Replace TPA, bolt, check over, and test at no charge
231/	770	0303/	243 99119	23-1404-07	1.4	10/3	21-00-13	21-04-13	Unexplained	District of tensoring parts	324042	- 1	over, and test at no charge
									Discharge - No				
			300 WBY						Mention of Safety	Could Not Duplicate			Replace trigger, check over
9324	700	n/a	MA	16-Dec-99	N	5	22-Oct-13	22-Oct-13	Position	Concern	324731	F	and test fire at 50% discoun
													Replace trigger assembly,
													check over, and test fire
													under bolt lock program fo
9326	700	N/A	270 WIN	1-Sep-69	N	S	22-Oct-13	6-Nov-13	-	Improper Maintenance	326510	F	\$20.00 + shipping.
-	700		2000 000					42.11	Delayed Firing -	40.000.000.440.000.000	227442	1.2	
9327	700	N/A	3006 SPR	1-Oct-72	N	S	22-Oct-13	13-Nov-13	Firearms	Improper Maintenance	327419	I.F	Per Ilion, quote to repair BL

-91.000	1055,554	Temes de co	N. CA. H. S.	000070-0000	223					Other - Unspecified or	Factor IV		Converting to 22 WMR as requested by customer, repair and check over
9322	597	26516	17 HMR	11-Nov-04	N	S	22-Oct-13	3-Mar-14	Fired Out of Battery	Undetermined - Firearms	324787	F	
9325	700	N/A	243 WIN		N	s	22-Oct-13	16-Apr-15	Fired on Bolt Closing	Not Examined by Product Service		F	Gun not returned to Ilion fo exam
9330	700	27494	243 WIN	20-Mar-95	N	s	23.0±.13	33.0d.13	Fired on Safe Release	Altered Adjustments or Components	324841	F	Replace trigger, check over, and test at no charge
9330	700	2/434	243 44114	20-19/81-33	14	3	23-001-13	23-001-13	Fired oil sale nesease	Components	324041		and test at no charge
9331	700	25971	300 RUM	19-Jul-01	N	s	23-Oct-13	23-Oct-13	Fired on Bolt Closing	Improper Maintenance	324898	F	replace trigger, check over, and test fire at 50% discoun
20000		- 20	20200000		2.7	- 2	-122	22.22	Delayed Firing -	Not Examined by Product	2	12	Gun not returned to Ilion fo
9335	700	n/a	243 WIN		N	S	23-Oct-13	15-Apr-15	Firearms	Service Not Examined by Product	n/a	F	exam Gun not returned to Ilion fo
9336	700	N/A	243 WIN		N	PD/S	23-Oct-13	16-Apr-15	Fired on Safe Release	Service	n/a	F	exam
		190	0,0,1101		-		20.011.20	20.4.20		Not Examined by Product		1	Gun not returned to Ilion fo
9345	700	N/A	3006 SPR	12-Jun-78	N	S	23-Oct-13	13-Apr-15	Fired on Safe Release	Service	n/a	F	exam
													Replace trigger assembly,
		1090							Fired on Bolt	Could Not Duplicate			check over, and test fire under bolt lock program for
9339	700	N/A	270 WIN	26-Jul-78	N	5	24-Oct-13	24-Oct-13	Opening	Concern	325070	F	\$20.00 + shipping.
9340	700	84216	22-250 REM	11-Dec-06	N	s	24-Oct-13	24-Oct-13	Fired on Safe Release	Altered Adjustments or Components	324990	F	The state of the s
2000 Per		200,000,000	20000000	STORY SEE		28	-100mm		Action Opened on	Not Examined by Product			Gun not returned to Ilion for
9346	870	81112	12 GA	1-May-13	N	5	24-Oct-13	13-Apr-15	Firing	Service	n/a	F	exam
9354	700	25771	270 WIN	29-Apr-94	N	s	24-Oct-13	15-Apr-15	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
9347	700	84022	6MM REM	9-Dec-11	N	s	25-Oct-13	25-Oct-13	Fail to Fire	Could Not Duplicate Concern	325130	F	Replace TPA, bolt, check over, and test at no charge
	7.00		-200702000						330000000000000000000000000000000000000	Could Not Duplicate			Per Ilion - Quote to repair
9355	700	n/a	270 WIN	1-May-75	N	S	25-Oct-13	20-Nov-13	Fired on Safe Release	Concern	328044	F	under BLM
9351	700	N/A	243 WIN	1-May-78	N	s	28-Oct-13	28-Oct-13	Fired on Bolt Closing	Improper Maintenance	325210	F	
	122201	72.240.27	25200000							Other - Unspecified or		1/2	Check over completely, repair as needed, and test fire at no
9352	750	27059	270 WIN	21-Apr-10	N	S	28-Oct-13	28-Oct-13	Case Separation	Undetermined - Firearms	325390	F	
9353	788	n/a	243 WIN	26-Aug-81	Y	s	28-Oct-13	28-Oct-12	Fired on Safe Release	Improper Maintenance	325333	F	Per Ilion - Quote to repair @ a discount
9359	700	N/A	7MM REM	1-Nov-73	N	s	28-Oct-13	6-Dec-13	Unexplained Discharge Safe OFF	Could Not Duplicate Concern	329684	F	Replace trigger assembly, check over, and test fire under bolt lock program for
													Replacing with Ramac 84371
		20070500	200220004	0.00000 0000		50000	NO. 1470 DESCRIPTION			Altered Adjustments or			in exchange at a 50%
9362	770	85633	3006 SPRG	19-Jun-07	N	PI/S	29-Oct-13	29-Oct-13	Fired on Safe Release	Components	325595	F	
9365	710	27408	270 WIN	25-Oct-05	Y	s	29-Oct-13	13.Nov.13	Fired on Safe Release	Could Not Duplicate Concern	327156	F	Per Ilion, replace trigger assembly and repair as needed at 50% discount
2303	7.40	27400	270 11111	23-001-03			23-001-13	23 1404 13	i i i su di suite nereuse	Could Not Duplicate	367 230	- 1	Replacing with Ramac 85633
9368	710	27410	3006 SPR	30-Apr-01	γ	PD/S	30-Oct-13	18-Nov-13	Fired on Bolt Closing	Concern	325693	F	
9369	700	25971	300 RUM	8-Nov-01	N	s	30-Oct-13	30-Oct-13	Fired on Safe Release		325685	F	Replace trigger, check over and test fire at 50% discoun
12222	80000	040,73796 III	SAMPLETON	1010-000 NORTH	550	1814	T-0500-075T	microsocial.		Altered Adjustments or	1979/2002/001		Per Ilion - Quote to repair @
9372	700	27361	270 WIN	16-Jan-06	N	5	30-Oct-13	9-Dec-13	Fired on Safe Release	Components	329862	F	a discount

													Offer to replace bolt assembly, trigger assembly,
9374	722	N/A	257 ROBTS	1-Feb-50	Y	S	30-Oct-13	7-Nov-13	Fired With Safe ON	AFT MKT TRIGGER ASSM	326769	F	check over, and test at 50%
9371	700	N/A	243 WIN	28-Aug-01	N	s	30-Oct-13	3-Jan-14	Fired on Bolt Closing	Could Not Duplicate Concern	332493	F	
	0.000	T							Action Opened on	Could Not Duplicate			Replacing with Ramac 72582
9375	H&R	N/A	45-70 GOV	28-Sep-11	N	PI/S	30-Oct-13	2-Jan-14	Firing	Concern	328173	F	
0275	770	85634	200111111	*****	220	- 2	34.0.43	74.0.4.7	Flord on Balk Classes	Could Not Duplicate	225020	2	Replace TPA, check over and
9376	770	85634	308 WIN	19-Jul-12	N	S	31-Oct-13	31-Oct-13	Fired on Bolt Closing	Concern	325820	F	test at no charge
9377	700	26308	7MM RUM	3-Apr-03	N	s	31-Oct-13	31-Oct-13	Fired on Safe Release	Could Not Duplicate Concern	325831	F	Replace trigger, check over, and test at no charge
9378	700	29705	308 WIN	2-Mar-01	N	s	31-Oct-13	31-Oct-13	Fired on Bolt Closing	Altered Adjustments or Components	325853	F	Replace trigger, check over and test fire at 50% discount
9379	58	N/A	12 GA	1-Apr-56	Y	s	31-Oct-13	31-Oct-13	Fired on Bolt Closing	Broken or Missing Parts	325838	F	Offer to check over completely and repair at 50% discount
		1.4								Could Not Duplicate		1	Replace TPA, check over and
9381	770	85633	3006 SPR	10-Jun-13	N	5	31-Oct-13	31-Oct-13	Fired on Bolt Closing	Concern	325901	F	
9382	700	N/A	270 WIN	24-Jan-05	N	S	31-Oct-13	20-Nov-13	Fired on Bolt Closing	Could Not Duplicate Concern	327952	F	
9385	700ML	27572	50 CAL	22 1.4 02	Y	s	31 04 13	2-Dec-13	Fired on Safe Release	Broken or Missing Parts	328551	F	Per Ilion, replace trigger,
9400	700ML	25971	300 RUM	22-Jul-97 27-Oct-00	N	5	31-Oct-13	20-Nov-13	Aug Comment	Altered Adjustments or Components	327936	F	10 M 40 40 40 40 40
										Not Examined by Product			Ammo not returned to
9383		n/a	45 ACP		N	PI/S	31-Oct-13	17-Apr-14	Other - Ammunition	Service	n/a	A	Lonoke for exam
Silbolen		2754	Cardinate Season		320	757	-3350 0000	Water State	5/6/1905-05/WWW.Upges.06/59/	Not Examined by Product	94501		Gun not returned to Ilion for
9384	700	N/A	25-06 REM		N	S	31-Oct-13	16-Apr-15	Fired on Bolt Closing	Service	n/a	F	exam
9386	700	n/a	243 WIN	29-Sep-81	N	PD/S	31.0-13	14 400 15	Fired on Safe Release	Not Examined by Product Service		F	Gun not returned to Ilion for
9386	/00	n/a	300 WIN	29-3ep-81	.14	PU/S	31-Oct-13	14-Apr-15	Fired on Bolt	Service	n/a	- 1	exam Repair @ n/c - goodwill
9282	770	85636	MA	16-Nov-07	N	PD/S	1-Nov-13	6-Nov-13	Opening	Broken or Missing Parts	326008	F	
9390	7	24786	7MM 08 REM	14-Sep-93	N	5	1-Nov-13	1-Nov-13	Fired on Safe Release	Altered Adjustments or Components	326064	F	Replace trigger, check over and test fire at 50% discount
										Altered Adjustments or	700123.000		Replace trigger assembly, check over, and test fire under bolt lock program for
9391	700	N/A	270 WIN	1-Oct-70	N	5	1-Nov-13	1-Nov-13	Fired on Safe Release	Components	326068	F	7.7.2
9392	700	27490	223 REM	1-Feb-96	N	s	1-Nov-13	1-Nov-13	Fired on Safe Release	Altered Adjustments or Components	326011	F	Offer to replace trigger assembly, check over, and test at 50% discount
ecaper	25000-0	2555	22-250	0.0000000000000000000000000000000000000	2000	95	10000-220	100000 000		Altered Adjustments or	68 GTX 150 FT	J.	
9394	700	N/A	REM	18-Dec-76	N	5	1-Nov-13	14-Nov-13	Fired on Safe Release	Components	327471	F	Per Ilion, quote to repair BLN
9396	597M	26514	17 HMR	9-Dec-03	N	s	1-Nov-13	3-Dec-13	Other - Firearms	Other - Unspecified or Undetermined - Firearms	327656	F	Replacing with Ramac 70743 in exchange
9398	700	N/A	7MM REM MA	1-Dec-72	N	S	1-Nov-13	4-Dec-13	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	329415	F	Per Ilion, quote to repair BLN
9406	700	84174	7MM REM MA	27-Oct-06	N	5	4-Nov-13	20-Nov-13	Fired on Safe Release	Altered Adjustments or Components	327800	F	Replace trigger, check over and test fire at 50% discount

9410	700	N/A	7MM REM MA	1-Apr-80	N	s	5-Nov-13	5-Nov-13	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	326244	F	Replace trigger assembly, check over, and test fire under bolt lock program for \$20.00 + shipping.
9412	710	27408	270 WIN	6-Feb-06	Y	s	5-Nov-13	5-Nov-13	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	326324	F	Replace trigger, check over and test fire at 50% discount
9414	700	25636	7MM STW	31-Oct-86	N	S	5-Nov-13	20-Nov-13	Fired on Safe Release	Altered Adjustments or Components	328096	F	Offer to replace trigger assembly, check over, and test at 50% discount
9424	700	n/a	3006 SPRG	2-Feb-81	N	s	5-Nov-13	20-Nov-13	Fired on Bolt Opening	Improper Maintenance	328069	F	Per Ilion - Quote to repair under BLM
9418	700	N/A	270 WIN	1-Sep-84	N	s	6-Nov-13	6-Nov-13	Fired on Bolt Closing	Altered Adjustments or Components	326391	F	Per Ilion, replace trigger assembly and repair as needed at 50% discount
9419	CARBON 15	90689	223/5.56	10-Nov-12	N	s	6-Nov-13	6-Nov-13	Went Automatic	Sent in for Evaluation	326454	F	Check over completely, and repair as needed at no charge
9422	722	N/A	222 REM	1-Jan-59	Υ	s	6-Nov-13	6-Nov-13	Fired With Safe ON	Altered Adjustments or Components	325900	F	Per Ilion, quote to repair BLM
9434	Mohawk 600	n/a	243 WIN	1-May-74	Y	PD/S	6-Nov-13	2-Dec-13	Fired on Safe Release	Altered Adjustments or Components	328960	F	Per Ilion - Repair @ n/c - goodwill
9435	700	n/a	3006 SPRG	5-May-88	N	s	6-Nov-13	21-Nov-13	Fired on Safe Release	HARD OFF SAFE	328371	F	Per Ilion - Repair @ n/c
9425	700	N/A	25-06 REM	19-Oct-77	N	s	6-Nov-13	31-Jan-14		Altered Adjustments or Components	336054	F	Per Ilion, quote to repair BLN
9432	700	27265	7mm-08	3-Mar-06	N	S	6-Nov-13	16-Apr-15	Delayed Firing - Firearms	Not Examined by Product Service Altered Adjustments or	n/a	F	Gun not returned to Ilion for exam Per Ilion - Quote to repair @
9427	700	n/a	243 WIN 7MM REM	1-Jan-68	N	S	7-Nov-13	7-Nov-13	Fired on Safe Release Unexplained	Components	326599	F	a discount  Per Ilion, replace trigger assembly and repair as
9430	700	25803	MA	11-Jun-91	N	S	7-Nov-13	3-Dec-13	Discharge Safe OFF	Improper Maintenance	328851	F	needed at 50% discount
9431	700ML	27572	50 CAL	30-Apr-97	Y	s	7-Nov-13	2-Dec-13	Unexplained Discharge Safe OFF	Could Not Duplicate Concern	328920	F	
9440	700	26033	270 WIN	6-Sep-00	N	S	8-Nov-13	15-Nov-13	Unexplained Discharge Safe OFF	Improper Maintenance	327756	F	Per Ilion, replace trigger assembly and repair as needed at 50% discount
9441	700	25791	270 WIN	14-Feb-90	N	s	8-Nov-13	3-Dec-13	Fired on Safe Release	Altered Adjustments or Components	328975	F	Replace trigger, check over and test fire at 50% discount Paralegal from Canada.
9442	700	n/a			N	s	8-Nov-13	8-Nov-13	Fired on Safe Release	Not Examined by Product Service	n/a	F	Referred them to Gravel Agency
9443	700	25803	7MM REM MA	8-Nov-91	N	s	8-Nov-13	2-Dec-13	Fired on Safe Release	Could Not Duplicate Concern	328841	F	
9449	700	25909	7MM WBY MA	10-May-91	N	s	11-Nov-13	10-Dec-13	Fired on Bolt Closing	Could Not Duplicate Concern	330172	F	Per Ilion, replace trigger, check over, and test at 50% discount
9451	700	27121	270 WIN	18-Sep-06	N	s	11-Nov-13	2-Dec-13	Fired on Safe Release	Sent in for Evaluation	328579	F	Per Ilion, replace trigger, check over and test fire at no charge
9456	700	25771	270 WIN	1-May-85	N	s	11-Nov-13	17-Dec-13	Fired on Safe Release	Could Not Duplicate Concern Could Not Duplicate	331119	F	Per Ilion - Quote to repair Per Ilion - Repair @ n/c -
9457	700	85435	308 WIN	9-May-12	N	s	11-Nov-13	5-Dec-13	Fired on Safe Release	Concern	329532	F	

9463	700ML	27572	50 CAL	21-Oct-97	Y	s	11-Nov-13	6-Dec-13	Fired on Safe Release	Other - Unspecified or Undetermined - Firearms	329683	F	Per Ilion - Repair @ n/c
9450	742	N/A	308 WIN 7mm-08	1-Jul-78	N	S	11-Nov-13	8-Jan-14	Fired on Bolt Closing	Sent in for Evaluation Could Not Duplicate	332891	F	Per Ilion, repair at no charge
9460	700	85591	REM	24-Jun-11	N	S	11-Nov-13	28-Jan-14	Fired on Safe Release	Concern	335507	F	Per Ilion - Repair at n/c
		25220								Other - Unspecified or			Per Ilion, replace trigger, check over and test fire at no
9452	700	25739	308 WIN 300 WIN	5-Mar-13	N	S	12-Nov-13	12-Nov-13	Fired on Safe Release	Undetermined - Firearms Altered Adjustments or	327039	F	charge
9453	700	N/A	MA	1-Sep-73	N	S	12-Nov-13	12-Nov-13	Fired on Bolt Closing	Components Altered Adjustments or	327006	F	Per Ilion, quote to repair BLN
9469	Mohawk 600	n/a	308 WIN	1-Jul-71	Y	s	12-Nov-13	2-Dec-13	Fired on Bolt Closing	Components	328954	F	Per Ilion - Repair @ n/c
9454	742	n/a	308 WIN	1-Feb-74	Y	s		31-Jan-14	Fired With Safe ON	Could Not Duplicate Concern	336104	F	Per Ilion - Quote to repair @
	970000		CHC0000 THE SEASON		0035		DAMPER DES			Could Not Duplicate			Per Ilion - Repair at n/c -
9480	700	27337	3006 SPRG	2-Sep-09	N	S	12-Nov-13	14-Mar-14	Fired on Safe Release	Concern Other - Unspecified or	340523	F	goodwill  Converting to 22 WMR as requested by customer, repair and check over
9464	597	N/A	17 HMR	10-Dec-03	N	S	13-Nov-13	23-Dec-13	Other - Firearms	Undetermined - Firearms	331782	F	completely at no charge.
9483	700	25805	338 WIN MA	1-Dec-89	N	s	13-Nov-13	2-Dec-13	Delayed Firing - Firearms	Improper Maintenance	328723	F	Per Ilion - Quote to repair @ a discount
9473	700	25793	3006 SPR	30-May-96	N	s	13-Nov-13	16-Apr-15	Unexplained Discharge Safe OFF	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
9475	597	26536	17 HMR	20-Jun-03	N	s	13-Nov-13	15-Apr-15	Other - Firearms	Not Examined by Product Service	328633	F	Gun not examined by Product Service in Ilion
9467	597	26516	17 HMR	5-May-04	N	s	13-Nov-13	26-Dec-13	Other - Firearms	Other - Unspecified or Undetermined - Firearms	330312	F	Replacing with Ramac 85836 in exchange
	7005	05.400	7MM REM							Could Not Duplicate			Per Ilion, replace trigger, check over and test fire at no
9474	7005	85422	MA	16-Sep-09	N	S	14-Nov-13	3-Dec-13	Fired on Safe Release	Concern Altered Adjustments or	329185	F	charge Repair @ n/c - goodwill
9477	700	27474	243 WIN 7MM REM	1-Aug-96	N	PI/S	14-Nov-13	4-Dec-13	Fired on Bolt Closing	Components	329417	F	
9478	700	n/a	MA	17-Sep-76	N	s	15-Nov-13	15-Nov-13	Fired on Safe Release	Improper Maintenance	327745	0	
9484	700	N/A	3006 SPR	4-Jun-80	N	PD/S	15-Nov-13	14-Apr-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
9489	597M	26516	17 HMR	25-Mar-04	N	s	18-Nov-13	11-Dec-13	Other - Firearms	Other - Unspecified or Undetermined - Firearms	330282	F	Replacing with Ramac 70733 in exchange
9491	700	n/a	3006 SPRG	1-May-74	N	s	18-Nov-13	4-Dec-13	Fired on Bolt Opening	Improper Maintenance	329387	F	
9503	700	27359	308 WIN	28-Jan-12	N	S	18-Nov-13	12-Dec-13	Fired on Safe Release	Could Not Duplicate Concern	330554	F	Replace TPA, check over and test at no charge
9517	770	85634	308 WIN	8-Mar-13	N	s	18-Nov-13	11-Dec-13	Fired on Bolt Closing	Could Not Duplicate Concern	330361	F	
9490	700	25773	3006 SPRG	15-Oct-87	N	s	18-Nov-13	26-Mar-14	Fired on Safe Release	Altered Adjustments or Components	341502	F	
9492	700	n/a	270 WIN	19-Jan-79	N	PI/S	18-Nov-13	2-Jan-14	Fired on Safe Release	Could Not Duplicate Concern	330314	F	Repair @ n/c - goodwill gesture Converting to 22 WMR as
9509	597	N/A	17 HMR	25-Jun-03	N	s	18-Nov-13	12-Feb-14	Other - Firearms	Other - Unspecified or Undetermined - Firearms	335856	F	requested by customer, repair and check over
	700	n/a	270 WIN	28-Apr-76	N	PD/S	19 Nov. 12	9. Jan. 14	Fired on Bolt Closing	Improper Maintenance	331122		Quote to repair under BLM

0407	710	27404	270 WIN	27 41 04		nn ir	10 No. 17		Fired on Cafe Balance	Not Examined by Product		F	Gun not returned to Ilion for
9493	/10	2/404	270 WIN	27-Nov-01	Υ	PD/S	18-Nov-13	14-Apr-15	Fired on Safe Release	Service	n/a	- 1	exam
9506	700	N/A	300 RUM		N	s	18-Nov-13	15-Apr-15	Fired on Bolt Closing	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
9524	700	n/a	n/a		N	s	18-Nov-13	15-Apr-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
		10 -1-									2.7871.	100	
										Other - Unspecified or			Converting to 22 WMR as
9518	597M	26514	17 HMR	29-Jan-04	N	S	19-Nov-13	6-Dec-13	Other - Firearms	Undetermined - Firearms	329754	F	requested by customer
9527	597M	26516	17 HMR	14-Oct-03	N	s	19-Nov-13	13-Dec-13	Other - Firearms	Other - Unspecified or Undetermined - Firearms	330587	F	Converting to 22 WMR as requested by customer
19565	96000	2255	58177500000	15259 350			07300 800			Altered Adjustments or			
9533	700	N/A	243 WIN	1-Mar-72	N	S	19-Nov-13	18-Dec-13	Fired on Safe Release	Components	331227	F	Per Ilion, quote to repair BLM
									Fired on Bolt	Could Not Duplicate			Per customer request
9529	700	N/A	3006 SPR	1-Sep-71	N	S	19-Nov-13	13-Jan-14	Opening	Concern	333271	F	Returning as Received.
9526	700	20000	3006 SPRG		N	s	19-Nov-13	13-Apr-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
		10	-populario			- 22	20,000 1,000		error asvesor	Not Examined by Product			Gun not returned to Ilion for
9528	700	not avail.	223 REM		N	S	19-Nov-13	16-Apr-15	Fired on Safe Release	Service	n/a	F	exam
02123	-								Unexplained Discharge - No Mention of Safety		2313420		Per Ilion, replace trigger,
9494	700	27586	50 CAL	28-Jan-97	N	S	20-Nov-13	20-Nov-13	Position	Broken or Missing Parts	327796	F	check over at no charge
9495	700	27452	2506 REM	22-Sep-04	N	s	20-Nov-13	20-Nov-13	Fired on Safe Release	Could Not Duplicate Concern	327956	F	Per Ilion - Repair @ n/c - goodwill
9496	700	25767	243 WIN	10-Jun-93	N.	s	20-Nov-13	20-Nov-13	Fired on Bolt Closing	Improper Maintenance	327879	F	Offer to replace trigger assembly, check over, and test at 50% discount
			7MM REM			77			200	Altered Adjustments or	777		Per Ilion - Quote to repair
9498	700	n/a	MA	2-Apr-80	N	S	20-Nov-13	20-Nov-13	Fired on Safe Release	Components	327997	F	under BLM
9499	700	25773	3006 SPRG	7-May-03	N	5	20-Nov-13	20-Nov-13	Fired on Safe Release	Improper Maintenance	327790	F	Per Ilion, replace trigger assembly and repair as needed at 50% discount
9500	700	25793	3006 SPRG	1-Jun-84	N	s	20-Nov-13	20-Nov-13	Fired on Safe Release	Altered Adjustments or Components	327996	F	Per Ilion, replace trigger, check over and test fire at no charge
									Delayed Firing -				
9505	600	n/a	243 WIN	1-Sep-66	Υ	S	20-Nov-13	20-Nov-13	Firearms	Improper Maintenance	327963	F	Per Ilion - Repair @ n/c
	700	290	7MM REM		1200				First - Baladania	Could Not Duplicate	222224	12	Per Ilion - Quote to repair
9507	700	n/a	MA	25-Mar-79	N	S	20-Nov-13	20-Nov-13	Fired on Bolt Closing	Concern	327964	F	under BLM
9508	700	25771	270 WIN	22-Oct-99	N	s	20 Nov. 12	20-Nov-13	Delayed Firing - Firearms	Could Not Duplicate Concern	328072	F	Per Ilion - Quote to repair @ a discount
9508	700	23//1	270 99119	22-OCI-99	. FV	3	20-NOV-13	20-1404-13	Fireditio	Concern	328072	- 1	a discount
9534	597M	26514	17 HMR	9-Nov-04	N	s	20-Nov-13	12-Dec-13	Other - Firearms	Other - Unspecified or Undetermined - Firearms	330514	F	Replacing with Ramac 70723 in exchange
9513	600	N/A	6MM REM	1-May-64	Y	5	21-Nov-13	21-Nov-13	Fired on Bolt Closing	Improper Maintenance	328293	F	Per Ilion, replace trigger, check over and test fire at no charge
9514	700	n/a	270 WIN	24.Son. 92	N	s	21-Nov.13	21. Nov. 12	Fired on Safe Release	Improper Maintenance	328256	F	Per Ilion - Quote to repair @ a discount
3514	700	nya	556555	24-Sep-82	N	3	21-NOV-13	21-NOV-13	riied on sale kelease	improper iviaintenance	328230	+	Per Ilion, replace trigger
9515	700	25855	7MM08 REM	7-Mar-03	N	S	21-Nov-13	21-Nov-13	Fired on Safe Release	Improper Maintenance	328294	F	assembly and repair as needed at 50% discount
										Sould Net Doublant			Per Ilion, replace trigger,
	700	05335	24214051		1200	2			Floridan Bolt Cl	Could Not Duplicate	******		check over and test fire at no
9516	700	85339	243 WIN	16-Aug-11	N	S	21-Nov-13	21-Nov-13	Fired on Bolt Closing	Concern	328292	F	charge Partition Custo to consis
0521	700	n/n	270 WIN	1.101.72	M		21 Nov. 22	11 Dec 13	Fired on Safe Relates	Altered Adjustments or	270252	F	Per Ilion - Quote to repair
9531	700	n/a	270 WIN	1-Jul-73	N	S	21-NOV-13	11-Dec-13	Fired on Safe Release	Components	330352	1.6	under BLM

9532	H&R Slug Hunter	72200	12 GA	24-Apr-13	N	s	21-Nov-13	9-Dec-13	Unexplained Discharge Safe OFF	Broken or Missing Parts	329433	F	Refund - \$250.04 - custome request
										Not Examined by Product			Gun not returned to Ilion fo
9530	770	85633	3006 SPRG	4-Feb-13	N	S	21-Nov-13	14-Apr-15	Fired on Safe Release	Service	n/a	F	exam
9521	700	27580	50 CAL	11-Apr-97	N	S	22-Nov-13	22-Nov-13	Fired on Safe Release	Broken or Missing Parts	328419	F	Per Ilion, replace trigger, check over at no charge
9545	700	N/A	300 SAUM	25-Sep-02	N	s	22-Nov-13	11-Aug-14	Fired on Safe Release	Could Not Duplicate Concern	453864	F	Per Ilion, replace trigger, check over and test fire at no charge
										Could Not Duplicate			Replace trigger, check over,
9553	700	25773	3006 SPR	21-May-86	N	PI/S	22-Nov-13	16-Jul-14	Fired on Safe Release	Concern	446647	F	
9542	700	85478	270 WIN	18-May-10	N	S	25-Nov-13	18-Dec-13	Fired on Safe Release	Altered Adjustments or Components	331256	F	and the state of t
9560	700	26129	3006 SPR	24-Feb-00	N	S	25-Nov-13	77-Dec-13	Fired on Safe Release	Improper Maintenance	332066	F	Per Ilion, replace trigger, check over, and test at 50% discount
2300	740		40000111	E4160 00	- 15	-	25 1107 25	Er bee 15	THE OTTOWN THE THE OWNER	Could Not Duplicate	552000	٠,	Per Ilion - Quote to repair @
9543	700	27476	270 WIN	5-Feb-04	N	S	25-Nov-13	27-Feb-14	Fired on Safe Release		338920	F	
9556	597M	26516	17 HMR	10-Jul-05	N	s	25-Nov-13	3-Jan-14	Other - Firearms	Other - Unspecified or Undetermined - Firearms	332497	F	
course 1	100001	1000001	-22-03-00-00-02-1			19		2200000		Not Examined by Product	200000		Gun not returned to Ilion for
9544	700	25803	7MM MAG	16-Apr-91	N	S	25-Nov-13	16-Apr-15	Fired With Safe ON	Service	n/a	F	
9548	700	25793	3006 5PRG	23-Oct-02	N	5	25-Nov-13	16-Apr-15	Fired With Safe ON	Not Examined by Product Service	n/a	F	
										Not Examined by Product			Gun not returned to Ilion for
9564	710	27410	3006 SPR	15-Jul-02	Υ	S	26-Nov-13	15-Apr-15	Fired on Bolt Closing	Service	n/a	F	exam
9565	700	N/A	3006 SPR	1-Feb-70	N	S	27-Nov-13	18-Dec-13	Fired on Bolt Closing	Improper Maintenance	331235	F	Per Ilion, quote to repair BLN
		-21-033								Not Examined by Product			Gun not returned to Ilion for
9552	710	27416	243 WIN	20-Mar-06	N	5	27-Nov-13	14-Apr-15	Fired on Safe Release	Service	n/a	F	exam
9568	788	n/a	308 WIN	25-Sep-75	Y	s	2-Dec-13	2-Dec-13	Fired With Safe ON	Improper Maintenance	328695	F	Per Ilion - Quote to repair @ a discount
					1000								Per Ilion - Quote to repair @
9569	700	n/a	3006 SPRG	17-Mar-82	N	S	2-Dec-13	2-Dec-13	Fired on Bolt Closing	Improper Maintenance	328850	F	a discount
9570	700	n/a	243 WIN	1-Mar-67	N	s	2-Dec-13	2-Dec-13	Fired With Safe ON	Altered Adjustments or Components	328687	F	Per Ilion - Quote to repair under BLM
										1,500			Per Ilion - Quote to repair
9574	700	n/a	270 WIN	17-Aug-79	N	S	2-Dec-13	2-Dec-13	Fail to Fire	Improper Maintenance	329100	F	under BLM
9582	700	N/A	3006 SPR	1-Apr-67	N	s	2-Dec-13	27-Dec-13	Fired on Safe Release	Altered Adjustments or Components	332065	F	Per Ilion, quote to repair BLN
			7MM REM							Could Not Duplicate			
9603	700	27385	MA	10-Aug-09	N	S	2-Dec-13	17-Dec-13	Fired on Safe Release	Concern	331121	F	Per Ilion - Repair @ n/c
9606	700	29705	308 WIN	1-Jan-96	N	PI/S	2-Dec-13	20-Jan-14	Fired on Safe Release	Altered Adjustments or Components	332195	F	
50893			7mm-08	VV.4339335554	980		1204570600			Could Not Duplicate			Repair @ n/c - goodwill
9607	700	27453	REM	28-Mar-02	N	PD/S	2-Dec-13		Fired on Safe Release		339870	F	gesture Repair @ n/c - goodwill
9608	700	n/a	3006 SPRG	24-Feb-77	N	PD/S	2-Dec-13	22-Jan-14	Fired on Safe Release	Improper Maintenance Not Examined by Product	333110	F	gesture Gun not returned to Ilion for
9576	700	N/A		17-Aug-77	N	S	2-Dec-13	14-Apr-15	Fired on Safe Release	Service	n/a	F	exam
0570	700	22252	270 W/IF	12 1/107	N.		2 Dec 12	14 400 15	Fired on Sale Release	Not Examined by Product		-	Gun not examined by Produc
9579	700	27253	270 WIN 7MM REM	12-Jul-07	N	S	2-Dec-13	14-Apr-15	Fired on Safe Release		n/a	F	
9581	700	n/a	MA	1-May-73	N	s	3-Dec-13	3-Dec-13	Fired on Bolt Closing	Could Not Duplicate Concern	329039	F	Per Ilion - Quote to repair under BLM
9584	870	24407	12 GA	9-Jan-12	N	s	3-Dec-13	3-Dec-13	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	329283	F	Per Ilion - Repair @ n/c - warranty

9586	700	N/A	7MM REM MA	1-Oct-83	N	PI/PD/S	3-Dec-13	17-Dec-13	Fired on Safe Release	Could Not Duplicate Concern	330339	F	Replace trigger, check over, and test at no charge
										Could Not Duplicate		Ť	Per Ilion - Repair @ n/c -
9623	700	84207	308 WIN	13-Feb-12	N	S	3-Dec-13	20-Dec-13	Fired on Safe Release	Concern	331598	F	warranty
	1000000									Could Not Duplicate		П	Repair @ n/c - goodwill
9599	700	85569	308 WIN	12-Jun-09	N	PD/S	3-Dec-13	7-Feb-14	Fired on Safe Release	Concern	332864	F	gesture
9609	700	n/a	3006 SPRG	1-Sep-68	N	PD/S	3-Dec-13	14-Jan-14	Fired on Bolt Closing	Improper Maintenance	333717	F	Replace TA, clean & test fire @ n/c - goodwill gesture
9593	700ML	N/A	50 CAL		Υ	s	3-Dec-13	15-Apr-15	Fired on Bolt Opening	Not Examined by Product Service	n/a	F	Gun not returned to Ilion fo exam
9624	700	n/a	3006 SPRG	20-Aug-75	N	s	4-Dec-13	19-Dec-13	Fired on Bolt Closing	Altered Adjustments or Components	331479	F	Per Ilion - Quote to repair under BLM
2027	,,,,,	1.70	300031110	ao nug 15	.,	-	4 000 25	15 000 13	Theo on boil closing	Could Not Duplicate	331473	Ť	Per Ilion - Repair at n/c -
9626	700	84600	223 REM	13-Jul-11	N	s	4-Dec-13	12-Feb-14	Fired on Safe Release	Concern	337484	F	goodwill
										Not Examined by Product			Gun not returned to Ilion fo
9625	700	27476	270 WIN	22-Jan-99	N	S	4-Dec-13	14-Apr-15	Fired on Safe Release	Service	n/a	F	exam
2000		935945554	Section 1	5553 1 - 044		- 25		25-24	Section Contraction	Altered Adjustments or			
9598	770	85633	3006 SPRG	25-Jan-08	N	S	5-Dec-13	5-Dec-13	Fired on Bolt Closing	Components	329543	F	Quote to repair at a discoun
9604	700	25709	308 WIN	26-Dec-12	N	s	5-Dec-13	29-Jan-14	Fired on Safe Release	Could Not Duplicate Concern	335752	F	Per Ilion, replace TPA, check over and test at no charge
9619	700	N/A	270 WIN	1-Sep-83	N	s	5-Dec-13	3-Jan-14	Fired on Bolt Closing	Altered Adjustments or Components	332498	F	Per Ilion, replace trigger, check over, and test at 50% discount
									77.2	Could Not Duplicate		П	Per Ilion - Quote to repair @
9643	700	29708	270 WIN	16-Jul-92	N	S	5-Dec-13	3-Jan-14	Fired on Safe Release	Concern	332499	F	a discount
	No. Time								A con communica	Not Examined by Product	101		Gun not returned to Ilion fo
9630	700	N/A	3006 SPR		N	S	5-Dec-13	14-Apr-15	Fired on Safe Release	Service	n/a	F	exam
9612	700	n/a	243 WIN	1-Dec-70	N	PD/S	6-Dec-13	6-Dec-13	Fired on Safe Release	Broken or Missing Parts	329125	F	Per Ilion - Repair @ n/c
9614	660	n/a	308 WIN	1-Aug-68	Y	s	6-Dec-13	6-Dec-13	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	329692	F	Per Ilion - Repair @ n/c
9616	700	N/A	243 WIN	1-Dec-73	N	PD/S	6-Dec-13	30-Dec-13	Fired on Safe Release	Could Not Duplicate Concern	329295	F	quote to repair BLM
9617	700	26035	3006 SPRG	23-Mar-98	N	s	6-Dec-13	6-Dec-13	Fired on Safe Release	Improper Maintenance	329703	F	Per Ilion - Quote to repair @ a discount
3017	700	20033	3000 SFNG	23-IVId1-30	14	3	0-000-13	0-000-13	Fired Oil Sale Nesease		329703	ŕ	a discount
9644	597	26560	22 WMR	22-Oct-12	N	s	6-Dec-13	16-Jan-14	Blowback in Face	Other - Unspecified or Undetermined - Firearms	332264	F	Replace w/26560 in exchang
			20.75.100	20 01120	-			40.10.14.7		Altered Adjustments or		Ť	Per Ilion - Quote to repair @
9634	700	26909	270 WIN	12-May-03	N	s	9-Dec-13	9-Dec-13	Fired on Safe Release	Components	330046	F	a discount
									Unexplained Discharge - No Mention of Safety	Could Not Duplicate			
9635	Versa Max	81059	12 GA	14-Aug-13	N	s	9-Dec-13	9-Dec-13	Position	Concern	329888	F	Per Ilion - Repair @ n/c
9636	721	n/a	3006 SPRG	1-Feb-56	Y	PD/S	9-Dec-13	9-Dec-13	Fired on Safe Release	Could Not Duplicate Concern	330026	F	Per Ilion - Quote to repair under BLM
										Could Not Duplicate	USDRIVETS ST		Per Ilion - Quoted to repair consumer refused, rifle
9637	700	27093	243 WIN	16-Aug-06	N	PD/S	9-Dec-13	9-Dec-13	Fired on Bolt Closing	Concern Could Not Duplicate	330006	F	returned to dealer
9642	700	25793	3006 SPRG	10-May-12	N	PD/S	9-Dec-13	2-Jan-14	Fired on Safe Release	Concern	331923/364482	F	Repair @ n/c - warranty
9674	700	n/a	3006 SPRG	29-Oct-81	N	PD/S	9-Dec-13	13-Jan-14	Fired on Safe Release	Altered Adjustments or Components	332868	F	Repair @ n/c - goodwill gesture
9647	700	84456	308 WIN	28-May-09	N	PI/S	10-Dec-13	30-Dec-13	Blowback in Face	Sent in for Evaluation	330173	F	Quote to repair at a discour

9650	700	84406	300 WIN MA	23-Sep-09	N	s	10-Dec-13	10-Dec-13	Fired on Safe Release	Could Not Duplicate Concern	330139	F	Per Ilion - Quote to repair @ a discount
			7MM REM						Delayed Firing -				Replace trigger assembly under BLP for \$20.00 + shipping and replace bolt at
9654	700	N/A	MA	1-Oct-70	N	S	10-Dec-13	19-Dec-13	Firearms	Improper Maintenance	331374	F	50% discount
9668	700	n/a	270 WIN	16-Nov-78	N	5	10-Dec-13	8-Jan-14	Fired on Bolt Closing	Could Not Duplicate Concern	332852	F	Per Ilion - Quote to repair under BLM
										Not Examined by Product			Gun not returned to Ilion fo
9653	700	n/a	270 WIN	11-Jun-92	N.	S	10-Dec-13	15-Apr-15	Fired on Safe Release	Service	n/a	F	exam
9656	1187	25277	12 GA 7MM REM	29-Aug-92	N	s	11-Dec-13	11-Dec-13	Fired on Bolt Closing	Could Not Duplicate Concern Could Not Duplicate	330341	F	Per Ilion, check over, repair a needed, and test at 50% discount
9657	700	N/A	MA	1-Feb-70	N	S	11-Dec-13	11-Dec-13	Opening	Concern	330402	F	Per Ilion, quote to repair BLM
	1500000							270 AAURES		Could Not Duplicate			Per Ilion, replace trigger, check over and test fire at no
9659	700	27255	300 WSM	20-Aug-09	N	S	11-Dec-13	11-Dec-13	Fired on Safe Release	Concern	330323	F	charge
9663	700	N/A	22-250 REM	1-Jan-73	N	s	11-Dec-13	27-Dec-13	Fired on Safe Release	Improper Maintenance	332064	F	Per Ilion, quote to repair BLM
9666	700	84178	3006 SPRG	25-Mar-09	N	s	12 Dec 12	12-Dec-13	Fired on Bolt Closing	Improper Maintenance	330531	F	Returning as received
9666	700	841/8	3006 SPKG	25-War-09	N	3	12-Dec-13	12-Dec-13	Fired on Boit Closing	Could Not Duplicate	330531	- 1	Replace TPA, check over and
9669	SPT-78	26164	3006 SPRG	6-Jan-89	N	PI/S	12-Dec-13	14-Jan-14	Fired on Safe Release	Concern	332496	F	
2002						1.90						-11	test acree charge
9672	700	84642	243 WIN	7-Aug-12	N	Š	12-Dec-13	2-Jan-14	Fired on Safe Release	Could Not Duplicate Concern	332222	F	Per Ilion, replace TPA, check over and test at no charge
			300 WIN							Altered Adjustments or		10	Per Ilion - Quote to repair
9681	700	n/a	MA	13-Apr-81	N	S	12-Dec-13	17-Jan-14	Fired on Safe Release	Components	334245	F	under BLM
		200								Not Examined by Product			Gun not returned to Ilion for
9671	700	n/a	7MM MAG		N	PD/S	12-Dec-13	15-Apr-15	Fired on Bolt Closing	Service	n/a	F	exam
9676	700	N/A	270 WIN	10-Sep-82	N	S	13-Dec-13	13-Dec-13	Fired on Bolt Opening	Improper Maintenance	330532	F	Per Ilion, replace trigger, check over, and test at 50% discount
9677	700	27514	223 REM	21-Jul-99	N	s	13-Dec-13	13-Dec-13	Fired on Safe Release	Broken or Missing Parts	330694	F	The state of the s
9678	700	n/a	7MM REM MA	27 8460 00	N	s	12 Dec 12	12 Dec 12	Fired on Safe Release	Improper Maintenance	330594	F	Per Ilion - Quote to repair under BLM
90/8	700	nya	IVIA	27-May-80	IN	3	13-Dec-13	13-060-13	Fired on Sale Release	Altered Adjustments or	330594		Per Ilion - Quote to repair
9679	700	n/a	243 WIN	27-Nov-79	N	S	13-Dec-13	13-Dec-13	Fired on Bolt Closing	Components	330563	F	under BLM
		250,5-000	Separate ex	H-28 - C-			G-55 - G-6		CONTRACTOR	Not Examined by Product		- 10	Customer refused to send
9684	700	25793	3006 SPRG	21-May-12	N	S	13-Dec-13	13-Dec-13	Fired on Safe Release	Service	n/a	F	gun in for exam
9682	770	85634	308 WIN	30-Mar-11	N	PD/S	13-Dec-13	20-Jan-14	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	332334	F	Replace TA & test fire @ n/c
9695	700	n/a	308 WIN		N	s	16-Dec-13	8-Jan-14	Fired on Bolt Closing	Could Not Duplicate Concern	332874	F	Per Ilion - Repair at n/c
9696	700	25771	270 WIN	1-Mar-90	N	s	16-Dec-13	9-Jan-14	Fired on Bolt Closing	Could Not Duplicate Concern	333104	F	Per Ilion - Quote to repair @ a discount
9697	700	N/A	270 WIN	31-Mar-80	N	5	16-Dec-13	20-Jan-14	Fired on Safe Release	Could Not Duplicate Concern	334543	F	Per Ilion, quote to repair BLN
						-				337733311		1	Per Ilion - Quote to repair
9698	700	n/a	308 WIN	1-May-78	N	S	16-Dec-13	9-Jan-14	Fired on Bolt Closing Delayed Firing -	Improper Maintenance Could Not Duplicate	333009	F	
9702	760	n/a	308 WIN	26-Apr-73	Υ	5	16-Dec-13	27-Feb-14	Firearms	Concern	339039	F	discount
9689	700	n/a	3006 SPRG	1-Jun-71	N	5	17-Dec-13	17-Dec-13	Fired on Safe Release	Altered Adjustments or Components	331034	F	Per Ilion - Quote to repair under BLM
9690	700	N/A	3006 SPRG	16-Jul-75	N	s	17-Dec-13	17-Dec-13	Fired on Bolt Closing	Could Not Duplicate Concern	331046	F	Per Ilion, quote to repair BLN

9692	700	25775	308 WIN	1-Jun-85	N	s	17-Dec-13	17-Dec-13	Fired on Safe Release	Could Not Duplicate Concern	331116	F	Per Ilion, offer to replace trigger assembly, check over, and test at 50% discount
9693	700	84515	3006 SPRG	21-Apr-10	N	5	17-Dec-13	17-Dec-13	Fired on Bolt Closing	Could Not Duplicate Concern	331044	F	Per Ilion, replace trigger, check over and test fire at no charge
9713	700	27361	270 WIN	2-Jan-07	N	s	17-Dec-13	14-Apr-15	Fired on Safe Release	Not Examined by Product Service	n/a	F	Gun not returned to Ilion fo exam
9707	CARBON 15	90689	223/5.56	11-Mar-13	N	s		18-Dec-13	Went Automatic	Sent in for Evaluation	331180	F	Per Ilion, check over completely and repair at no charge
9708	700	26309	270 WSM	23-Sep-05	N	s	18-Dec-13	18-Dec-13	Fired on Safe Release	Altered Adjustments or Components	331233	F	Per Ilion, replace trigger, check over, and test at 50% discount
9710	700	n/a	2506 REM	31-Mar-82	N	s	18-Dec-13	18-Dec-13	Fired on Safe Release	Altered Adjustments or Components	331237	F	
9724	700	N/A	270 WIN	15-Sep-77	N	s	18-Dec-13	16-Apr-15	Fired on Safe Release	Not Examined by Product Service		F	Gun not returned to Ilion fo exam
9717	770	85632	270 WIN	2-Apr-09	N	S	19-Dec-13	19-Dec-13	Fired With Safe ON	Could Not Duplicate Concern	331390	0	Per Ilion - Repair @ n/c - goodwill
9719	700	84218	308 WIN	28-May-13	N	s	19-Dec-13	19-Dec-13	Fired on Bolt Closing	Altered Adjustments or Components	331345	F	Per Ilion, replace trigger, check over, and test at 50% discount
9720	770	85632	270 WIN	4-Oct-11	N	s	19-Dec-13	19-Dec-13	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	331361	F	Per Ilion, replace TPA, check over and test at no charge
9721	Seven	29551	7MM SAUM	31-Jan-03	N	5	19-Dec-13	19-Dec-13		Could Not Duplicate Concern	331377	0	Per Ilion - Quote to repair
9722	700	N/A	270 WIN	22-Apr-80	N	s		19-Dec-13	Unexplained Discharge - No Mention of Safety Position		331414		
9726	SEVEN	24784	6MM REM	1-Jul-83	N	PD/S	19-Dec-13	3-Feb-14	Delayed Firing - Firearms	Altered Adjustments or Components	334254	F	Per llion, quote to repair BLI Check over completely, repa as needed, and test fire at a 50% discount
9727	700	N/A	3006 SPR	11-Nov-76	N	s	19-Dec-13	16-Jan-14	Fired on Safe Release	Improper Maintenance	334111	0	Per Ilion, quote to repair BL!
9729	700	N/A	270 WIN	29-Aug-77	N	s	20-Dec-13	20-Dec-13	Fired on Bolt Closing	Improper Maintenance	331539	F	Per Ilion, quote to repair BLN
9730	700	84515	3006 SPRG	15-Feb-10	N	5	20-Dec-13	20-Dec-13	Fired on Safe Release	Could Not Duplicate Concern	331586	F	Per Ilion, replace TPA, check over and test at no charge
9732	700	N/A	3006 SPRG	1-Oct-69	N	5	23-Dec-13	23-Dec-13	Fired on Safe Release	Improper Maintenance	331732	F	Per Ilion, quote to repair BLN Converting to 22 WMR as
9733 9737	597	26516 27095	17 HMR 3006 SPRG	24-Nov-04 7-Dec-11	N	PD/S	23-Dec-13 26-Dec-13	23-Dec-13 6-Feb-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms Could Not Duplicate	331717 335058	F	requested by customer, repair and check over completely at no charge. Repair @ n/c- to restore
5/3/	700	2/095	SOUR SPRG	1-Dec-11	N		26-Dec-13	0-rep-14	rifed on safe kelease	Concern Could Not Duplicate	335058		Per Ilion - Quote to repair
9738	700	n/a	3006 SPRG	1-Sep-76	N	S	26-Dec-13	17-Jan-14	Fired on Safe Release	Concern Altered Adjustments or	334252	F	under BLM Repair @ n/c - goodwill
9739	700	85430	25-06 REM	17-Aug-11	N	PD/S	26-Dec-13	24-Jan-14	Fired on Bolt Closing	Components Altered Adjustments or	333194	F	
9742	700	n/a	25-06 REM	1-Feb-73	N	s	26-Dec-13	9-Jan-14	Fired on Bolt Closing	Components	333107	F	under BLM
9743	7	24739	243 WIN	29-Apr-02	N	s	27-Dec-13	20-Jan-14	Fired on Bolt Closing	Could Not Duplicate Concern	334542	F	Per Ilion - Quote to repair @ a discount

9744	700	n/a	243 WIN	20-Feb-80	N	s	30-Dec-13	30-Dec-13	Fired With Safe ON	Could Not Duplicate Concern	332053	F	Repaired @ n/c - Consumer Serv. supervisor
										Could Not Duplicate			
9745	700	N/A	3006 SPRG	14-Feb-79	N	S	30-Dec-13	30-Dec-13	Fired on Safe Release	Concern	332153	F	Per Ilion, quote to repair BLN Per Ilion, replace trigger,
9746	700	27099	300 WIN	17-Feb-06	N	s	30 Dec 13	30-Dec-13	Fired on Bolt Closing	Altered Adjustments or Components	332169	F	check over, and test at 50% discount
9748	597	80875	22 LR	20-Sep-13	N	PI/S		16-Jan-14	Broken Part	Sent in for Evaluation	332990	F	
21.40		0.007.0	20.00	to sep 15		1,45	50 000 15	20 3411 24		Could Not Duplicate	502550	-	Trepart & Tyle Harranty
9749	700	N/A	270 WIN	1-Nov-72	N	S	30-Dec-13	17-Jan-14	Fired on Safe Release	Concern	334250	F	Per Ilion, quote to repair BLN
													Per Ilion, replace trigger
2.25			7MM REM	200	12.7	- 2	4272 922	2200 200	200 2000	Altered Adjustments or	22222		assembly and repair as
9752	700	26933	MA	6-Nov-95	N	S	30-Dec-13	27-Jan-14	Fired on Safe Release	Components	335391	F	needed at 50% discount Gun not returned to Illon for
9753	770	85633	3006 SPR	6-Jun-13	N	PI/S	30-Dec-13	15-Apr-15	Delayed Firing - Firearms	Not Examined by Product Service	n/a	F	
9757	700	27478	3006 SPRG	4-Jan-02	N	s	31-Dec-13	7-Feb-14	Fired on Safe Release	Could Not Duplicate Concern	336874	F	Per Ilion - Quote to repair
3/3/	700	2/4/0	3000 3FNG	4-3411-02		,	31-000-13	7-7-0-14	Fired Oil Sale Release	Concern	330074	- 6	Per mon - quote to repair
9758	700	N/A	3006 SPR	24-Jul-75	N	S	31-Dec-13	14-Feb-14	Fired on Safe Release	Improper Maintenance Could Not Duplicate	337823	F	Per Ilion, quote to repair BLN
9759	700	N/A	3006 SPR	18-Feb-77	N	s	31-Dec-13	19-Mar-14	Fired on Bolt Closing	Concern	340874	c	Per Ilion, quote to repair BLN
		1977	3000 3111	2010077		-	34 040 33	22.1100.21	The on our closing	Altered Adjustments or	310011	-11	To many quote to repair unit
9761	700	N/A	222 REM	1-Jan-73	N	S	2-Jan-14	24-Jan-14	Fired on Safe Release	Components	335203	F	Per Ilion, quote to repair BLN
													Per Ilion, replace trigger,
07501	1222		200000000		2.5	12	255-326	-20-50		Could Not Duplicate	220.00	-	check over, and test at 50%
9652	700	N/A	308 WIN	20-Jul-06	N	5	3-Jan-14	3-Jan-14	Fired on Safe Release	Concern	332426	F	discount
										Could Not Duplicate			Per Ilion, replace TPA, check
9765	660	N/A	222 REM	1-Sep-68	Y	s	3-Jan-14	3-Jan-14	Fired on Safe Release	Concern	332388	F	
9766	700	25773	3006 SPRG	12-Jan-94	N	s	3-Jan-14	3-Jan-14	Fired on Safe Release	Improper Maintenance	332428	F	Per Ilion, replace trigger assembly and repair as needed at 50% discount
9768	700	N/A	280 REM		N	s	3-Jan-14	3-Jan-14	Fired on Bolt Closing	Altered Adjustments or Components	332489	F	Per Ilion, offer to replace trigger assembly, check over and test at 50% discount
9771	597	26516	17 HMR	21-Jun-04	N	PD/S	3-Jan-14	23-Jan-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	334981	F	Converting to 22 WMR as requested by customer, repair and check over completely at no charge.
										Other - Unspecified or			Replacing with Ramac 70743
9772	597	N/A	17 HMR	12-Feb-03	N	PI/PD/S	3-Jan-14	23-Jan-14	My Gun Blew Up	Undetermined - Firearms	334122	0	
3772	337	140	47 1111111	11 100 03		1410/5	3 7411 24	23 2011 24	my dan blew op	Ondetermined Friedring	334122	-	Per Ilion - Quote to repair @
9774	Seven	not avail.	308 WIN		N.	S	3-Jan-14	6-Feb-14	Fired on Safe Release	Sent in for Evaluation	336719	F	discount
										Altered Adjustments or			Per Ilion - Quote to repair
9775	700	n/a	3006 SPRG	12-Jul-75	N	5	3-Jan-14	6-Feb-14	Fired on Safe Release	Components	336716	F	
9776	721	n/a	270 WIN		Y	PD/S	3-Jan-14	15 May 14	Fired on Bolt Closing	Could Not Duplicate Concern	342133	F	Repair @ n/c - goodwill gesture
9776	/21	n/a	270 WIN		1	PU/S	3-Jan-14	15-Iviay-14	Fired on Boit Closing	Concern	392133	- 1	Converting to 22 WMR as
9777	597	26516	17 HMR	23-Sep-03	N	PD/S	3-Jan-14	28-Jan-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	335536	F	requested by customer, repair and check over
			A	-3 5tp 33		12,3	3 2301 24	20.7544	,	Altered Adjustments or	33333	1	precess and compet
9782	600	n/a	243 WIN	1-Mar-66	Υ	S	3-Jan-14	30-Jan-14	Fired on Bolt Closing	Components	335992	F	Per Ilion - Repair at n/c
-									Louis No. of Contract of Contr				Per Ilion, replace trigger,
9510	700	25771	270 WIN	21-Oct-96	N	s	6-Jan-14	6-Jan-14	Unexplained Discharge Safe OFF	Improper Maintenance	332598	F	
_			7MM REM							Altered Adjustments or			Returned as Received -

9786	870	81282	12 GA	10-Jun-09	N	s	6-Jan-14	30-Jan-14	Unexplained Discharge Safe OFF	Could Not Duplicate Concern	335854	F	Per Ilion - Quote to repair @ discount - goodwill
							2.274.741			Altered Adjustments or	Anna		Ilion repaired at n/c under
9789	700	n/a	223 REM	26-Mar-69	N	S	6-Jan-14	28-Oct-14	Fired on Safe Release	Components	472983	F	
										Could Not Duplicate			Per Ilion, replace trigger, check over and test fire at no
9793	700	84643	270 WIN	6-Aug-12	N	s	6-Jan-14	27-Jan-14	Fired on Safe Release	Concern	335334	F	
9795	597	26516	17 HMR	2-Sep-05	N	PD/S	7-Jan-14	19-Feb-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	335603	F	The second of the best of the party of the p
9797	700	25858	6MM REM	1-Nov-83	N	s	7-Jan-14	20-Jan-14	Delayed Firing - Firearms	Could Not Duplicate Concern	334534	F	Per Ilion, replace trigger, check over, and test at 50% discount
			7MM REM							Altered Adjustments or			
9798	700	N/A	MA	1-May-72	N	S	7-Jan-14	24-Jan-14	Fired on Safe Release	Components	335161	F	Per Ilion, quote to repair BLN
9800	700	25771	270 WIN	1-Oct-84	N	PD/S	9-Jan-14	9-Jan-14	Fired on Safe Release	Improper Maintenance	333001	F	
			252111011							Could Not Developed			Per Ilion, replace trigger,
9801	700	84545	257 WBY MA	8-Aug-13	N	s	9-Jan-14	9-Jan-14	Fired on Bolt Closing	Could Not Duplicate Concern	332977	F	check over and test fire at no charge
2001	700	01313		0 H06 13		-	2301124	3301124	The on boil crosing	CONCENT	332377	- '	Charge
									Delayed Firing -	Could Not Duplicate			Per Ilion, replace TPA, check
9802	770	85660	243 WIN	19-May-10	N	S	9-Jan-14	9-Jan-14	Firearms	Concern	333135	F	CONTRACTOR DE LA CONTRACTOR DEL CONTRACTOR DE LA CONTRACTOR DE LA CONTRACTOR DE LA CONTRACT
9803	700	25898	264 WIN MA	13-May-86	N	s	9-Jan-14	24-Jan-14	Delayed Firing - Firearms	Could Not Duplicate Concern	335162	F	Per Ilion, replace trigger, check over and test fire at no charge
2003	700	25050	22-250	43 Willy 00		3	3.5411.24	2,4-2001-24	Pileditis	Altered Adjustments or	333402	1	Per Ilion - Quote to repair @
9805	700	29743	REM	3-Jan-03	N	S	10-Jan-14	6-Feb-14	Fired on Safe Release	Components	336678	F	discount
	1000									Not Examined by Product	202001		Gun not returned to Ilion for
9806	722	N/A			Y	5	10-Jan-14	1-Apr-15	Fired on Bolt Closing Unexplained	Service	n/a	F	exam
9808	887	82500	12 GA	26-Mar-10	N	s	13-Jan-14	13-Jan-14	Discharge - No Mention of Safety Position	Could Not Duplicate Concern	333272	F	Check over completely, repair as needed, and test fire at no charge
9811	700	84200	17 FB	20 500 07	N	s	13-Jan-14	13 ton 14	Fired on Safe Release	Altered Adjustments or Components	333418	F	Per Ilion, check over, repair a needed, and test at 50% discount
9811	700	84200	17 FB	20-Sep-07	TV.	3	15-Jan-14	13-Jan-14	Fired on Sale Release	Components	333418	- 1	Repair @ n/c - goodwill
9817	700	n/a	3006 SPRG	25-Mar-69	N	PD/S	13-Jan-14	17-Mar-14	Fired on Bolt Closing	Improper Maintenance	338472	F	
		2-22								Not Examined by Product	14		Customer does not want to
9832	700	84273	270 WIN	21-Jun-13	N	S	13-Jan-14	22-Jan-14	Other - Firearms	Service	n/a	F	send rifle in for exam
9826	700	n/a	270 WIN	4-Dec-78	N	5	14-Jan-14	6-Feb-14	Fired on Safe Release	Altered Adjustments or Components	336756	F	Per Ilion - Quote to repair under BLM
2010	100	1,7.0	7MM REM	4 500 70		-	24 2011 24	010024	The on our necess.	Not Examined by Product	330730	-1	Gun not returned to Ilion for
9823	700	not avail.	MA		N	S	14-Jan-14	1-Apr-15	Fired on Safe Release	Service	n/a	F	exam
9822	XM15E2S	90391	223/5.56	22-Feb-13	N	s	15-Jan-14	15-Jan-14	Went Automatic	Could Not Duplicate Concern	333917		Per Ilion, check over, repair a needed, and test at no charge
3022	VIAITZES	90391	223/3.30	22-PEO-13	14	3	12-101-14	13-7811-14	Went Automatic	Concern	333917		needed, and test at no charge
9843	700	25773	3006 SPRG	1-May-84	N	S	15-Jan-14	31-Jan-14	Fired on Safe Release	Improper Maintenance	336157	F	Per Ilion - Quote to repair
										the or the state of the state o			
9829	BACR	90838	223/5.56	27-Sep-13	N	5	16-Jan-14	16-Jan-14	Went Automatic	Could Not Duplicate Concern	334105		Per Ilion, check over, repair a needed, and test at no charge
2029	DACK	90036	223/3.36	z/*5ep-13	TV.	3	10-Jan-14	16-Jan-14	went Automatic	Concern	334105	- 1	Per Ilion, replace trigger,
										Could Not Duplicate			check over and test fire at no
9833	600	N/A	6MM REM	1-Jun-66	Υ	S	16-Jan-14	30-Jan-14	Fired on Bolt Closing	Concern	335940	F	
										Altered Adjustments or			Per Ilion, replace trigger, check over, and test at 50%

9841	700	N/A	300 WIN MA	1-Aug-74	N	PD/S	17-Jan-14	11-Mar-14	Fired on Safe Release	Improper Maintenance	337209	F	Per release, replace trigger a no charge and \$2027.78 comp for truck damage.
9848	700	25791	270 WIN	27-Nov-90	N	s	20-Jan-14	20-Jan-14	Fired on Safe Release	Improper Maintenance	334454	F	Per Ilion, offer to replace trigger assembly, check over and test at 50% discount
9849	Handi-Rifle	HSCY42S	44 REM MAG	17-Jul-06	N	s	20-Jan-14	20-Jan-14	Delayed Firing - Firearms	MIN LOCK UP ON BBL CATCH	334449	F	Check over completely, repair as needed, and test fire
0054	710	27410	2005 5885	27.505			20 1 44	5 F-1- 44	Final on Balk Clasins	Residence Mission Reside	225700	F	Per Ilion, replace trigger, check over and test fire at no
9851	710	27410	3006 SPRG	27-Sep-05	Y	S	20-Jan-14	6-Feb-14	Fired on Bolt Closing	Broken or Missing Parts	336700	F	charge Converting to 22 WMR as requested by customer,
9853	597	26536	17 HMR	29-May-03	N	PI/PD/S	20-Jan-14	4-Mar-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	339455	F	
9854	700	25791	270 WIN	1-Dec-84	N	s	21-Jan-14	21-Jan-14	Fired on Bolt Closing	Altered Adjustments or Components	334694	F	Per Ilion, replace trigger, check over, and test at 50% discount
9858	700	85446	243 WIN	28-Sep-12	N	s	22-Jan-14	22-Jan-14	Fired on Safe Release	Could Not Duplicate Concern	334912	F	Per Ilion, replace trigger, check over and test fire at no charge
9862	700	84203	308 WIN	23-Apr-12	N	s	23-Jan-14	23-Jan-14	Fired on Safe Release	Could Not Duplicate Concern	334960	F	Per Ilion, replace trigger, check over and test fire at no charge
		C. M. Service	7MM REM				erueMintelaria (es Sint		Unexplained Discharge - No Mention of Safety	Could Not Duplicate	MATTOSOFFIN		Per Ilion, replace trigger, check over, and test at 50%
9863 9864	700	25803 N/A	MA 3006 SPRG	1-Mar-04 3-Feb-81	N	S	23-Jan-14 23-Jan-14	23-Jan-14 23-Jan-14	Position  Fired on Bolt Closing	Concern Could Not Duplicate Concern	334045 334996	F	discount  Per Ilion, quote to repair BLN
9870	710	27416	243 WIN	19-Mar-06	Y	s	23-Jan-14		Fired on Safe Release	Other - Unspecified or	340072	F	Per Ilion, replace trigger, check over and test fire at no charge
9871	700	27095	3006 SPRG	16-Jul-12	N	PI/S	23-Jan-14		Fired on Safe Release	Could Not Duplicate Concern	337551	F	Repair @ n/c
9866	600	N/A	243 WIN	26-Feb-77	N	S	24-Jan-14	24-Jan-14	Fired on Bolt Closing	Altered Adjustments or Components	335188	F	Per Ilion, quote to repair BLM
9867	700	N/A	270 WIN	26-Nov-78	N	s	24-Jan-14	24-Jan-14	Fired With Safe ON	Improper Maintenance	335197	F	Per Ilion, quote to repair BLIV
9872	700ML	27572	50 CAL	20-Jan-97	Y	S	24-Jan-14	6-Feb-14	Fired on Safe Release	Sent in for Evaluation	336763	F	
9875	700	27267	270 WIN	22-Sep-09	N	s	27-Jan-14	27-Jan-14	Fired on Safe Release	Could Not Duplicate Concern	335398	F	Per Ilion, replace trigger, check over and test fire at no charge
9879	700	27478	3006 SPRG	25-Mar-02	N	s	27-Jan-14	13-Feb-14	Fired on Safe Release	Altered Adjustments or Components	337565	F	Per Ilion, replace trigger, check over, and test at 50% discount
9877	700	27011	270 WIN	24-Mar-04	N	s	27-Jan-14	6-Apr-15	Unexplained Discharge - No Mention of Safety Position	Not Examined by Product Service	n/a	F	Gun not returned to Ilion for exam
9880	700	N/A	22 250 REM	20-Feb-70	N	s	28-Jan-14	28-Jan-14	Fired With Safe ON	Altered Adjustments or Components	335508	F	Per Ilion, quote to repair BLN
9886	700	n/a	7MM REM MA	1-Jun-68	N	s	29-Jan-14	29-Jan-14	Fired With Safe ON	Improper Maintenance	335681	F	
9889	700	27478	3006 SPRG	15.Oct.05	N	s	30-Jan-14	30-tan-14	Fired on Bolt Closing	Improper Maintenance	335831	F	Per Ilion, replace trigger, check over, and test at 50% discount

9893	700	27502	7MM STW	10-Feb-98	N	S	30-Jan-14	17-Feb-14	Fired With Safe ON	Altered Adjustments or Components	337866	F	Per Ilion, replace trigger, check over, and test at 50% discount
										Not Examined by Product			Gun not returned to Ilion for
9894	700	n/a	270 WIN		N	S	30-Jan-14	6-Apr-15	Fired on Bolt Closing	Service Could Not Duplicate	n/a	F	exam
9897	710	27410	3006 SPRG	26-Oct-01	Υ	PD/S	31-Jan-14	27-Mar-14	Fired on Bolt Closing	Concern	339779	F	Check over & test @ n/c
			300 WIN							Not Examined by Product			Gun not returned to Ilion fo
9899	700	not avail.	MA		N	S	31-Jan-14	6-Apr-15	Fired With Safe ON	Service Could Not Duplicate	n/a	F	exam
9903	700	N/A	3006 SPRG	24-Aug-76	N	s	3-Feb-14	3-Feb-14	Fired on Safe Release	Concern	336205	F	Per Ilion, quote to repair BLN
2200		1.90	300031110	arring re	-		37.45.47	0.140.41				Ť	Per Ilion, replace trigger,
										Could Not Duplicate			check over and test fire at no
9904	700	84207	308 WIN	8-Aug-13	N	s	3-Feb-14	3-Feb-14	Fired on Bolt Closing	Concern	336236	F	
									Unexplained Discharge - No				
									Mention of Safety				
9905	700	N/A	3006 SPRG	19-Oct-81	N	S	3-Feb-14	3-Feb-14	Position	Improper Maintenance	336288	F	Per Ilion, quote to repair BLN
2000		9,000,00	22-24	nunyers		- 20	B = 7(0.0 V		e-oranie socialismo	Could Not Duplicate			Per Ilion - Repair at n/c -
9906	1187	25343	12 GA	11-Feb-05	N	S	3-Feb-14	3-Feb-14	Fired on Bolt Closing	Concern	336057	F	goodwill
										Could Not Duplicate			
9907	700	n/a	270 WIN	4-May-82	N	S	3-Feb-14	17-Apr-14	Fired on Safe Release	Concern	341255	F	
		-00000000000000000000000000000000000000		201000000000000000000000000000000000000			100000000000000000000000000000000000000			Altered Adjustments or			Per Ilion - Quote to repair
9909	700	not avail.	3006 SPRG	17-Jun-74	N	S	3-Feb-14	17-Feb-14	Fired on Bolt Closing	Components	337867	F	75.100.000
													Per Ilion, replace trigger,
C070-000		50000000	-0.000000000	-2750 (0.5		20	TRESUCCIO		DOMESTIC PROJECTIONS	Could Not Duplicate			check over and test fire at ne
9913	770	85656	30-06	22-Aug-08	N	5	4-Feb-14	4-Feb-14	Fired on Bolt Closing	Concern	336476	F	
										Could Not Duplicate		-17	Per Ilion - Quote to repair @
9919	700	not avail.	280 REM	11-Jan-88	N	S	4-Feb-14	20-Feb-14	Fired on Safe Release	Concern	338340	F	discount
9921	597	26514	17 HMR	17-May-07	N	PD/S	4-Feb-14	3-Mar-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	339366	F	
9915	1911	96329	45 ACP	3-Dec-12	N	s	5-Feb-14	5-Feb-14	Light Trigger Pull	Could Not Duplicate Concern	336377	F	Check over completely, repair as needed, and test fire at no charge
												- 111	
0015		00000	15.450	20 1 1 42				F F W K 4	First Head For Committee	Provide for Production	336300		Per Ilion, check over, repair a
9916	1911	96324	45 ACP	30-Jul-13	N	S	5-Feb-14	5-Feb-14	Fired With Safe ON	Sent in for Evaluation	336390	- 1	needed, and test at no charge
9926	7	29551	7MM SAUM	11-Sep-02	N	s	6-Feb-14	6-Feb-14	Fired on Safe Release	Could Not Duplicate Concern	336674	F	Per Ilion, replace trigger, check over, and test at 50% discount
9920		29551	257 WBY	11-3ep-02	IV	3	0-Feb-14	0-160-14	Fired on sale nelease	Could Not Duplicate	330074	- 1	Per Ilion - Repair at n/c -
9927	700	84545	MA	8-Aug-13	N	5	6-Feb-14	12-Feb-14	Fired on Bolt Closing	Concern	337361	F	
3327	100	01313	100	o nug 13		-	010014	1010014	The on boil closing	Content	337301	T,	Hornary
States		1000000	122077020			8	0/0/12/17/23			Other - Unspecified or			Replacing with Ramac 70741
9928	597	26536	17 HMR	5-Nov-02	N	S	6-Feb-14	14-Mar-14	Fired Out of Battery	Undetermined - Firearms	336773	F	The second secon
													Converting to 22 WMR as requested by customer,
9932	597	26516	17 HMR	31-Jan-05	N	PD/S	6-Feb-14	28-Feb-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	339125	F	repair and check over completely at no charge.
										Co. Id No. D			O-W- ded
9934	887	82502	12 GA	20-May-10	N	5	7-Feb-14	7-Feb-14	Fired Out of Battery	Could Not Duplicate Concern	336823	F	Per Ilion, check over, repair a needed, and test at no charg
		. 3								Altered Adjustments or			
9935	700	N/A	3006 SPRG	1-Sep-66	N	S	7-Feb-14	7-Feb-14	Light Trigger Pull	Components	336819	F	Per Ilion, quote to repair BLN
9937	700	not avail.	3006 SPRG	6-Jul-79	N	s	7-Feb-14	7-Feb-14	Fired on Safe Release	Could Not Duplicate Concern	336922	F	With the property and the first of the first
9940	700	27107	3006 SPRG	29-Aug-06	N	S	10-Feb-14	10-Feb-14	Fired on Safe Release	Altered Adjustments or Components	337129	F	Per Ilion, replace trigger, check over, and test at 50% discount

9941	Handi Rifle	HSB206L	308 WIN	19-Mar-01	N	PI/S	10-Feb-14	15-Apr-15	Personal Injury while using firearm	Not Examined by Product Service	339199	F	Gun not examined by Produc Service in Ilion
										Not Examined by Product			Gun not returned to Ilion for
9947	700	26909	270 WIN	16-Oct-03	N	S	10-Feb-14	6-Apr-15	Fired on Safe Release	Service	n/a	F	exam
	53555		100000000		0.50		20000000000		O las arrestations de la constantion de la const	Not Examined by Product			Gun not returned to Ilion for
9948	700	N/A	3006 SPR		N	S	10-Feb-14	6-Apr-15	Fired With Safe ON	Service	n/a	F	exam
9944	1187	29891	20 GA	4-Feb-05	N	S	11-Feb-14	11-Feb-14	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	337231	F	Per Ilion - Repair at n/c
		25400.200			000.0	62.		7000-0000	Unexplained Discharge - No Mention of Safety	Could Not Duplicate	Carlossidantes		Per Ilion, replace trigger, check over, and test at 50%
9945	710	27418	243 WIN	21-Jun-06	N	S	11-Feb-14	11-Feb-14	Position	Concern	337286	F	
9953	600	n/a	6MM REM	1-Mar-67	Y	s	11-Feb-14	25-Feb-14	Fired on Safe Release	Altered Adjustments or Components	338746	F	
										Not Examined by Product			Gun not returned to Ilion for
9952	700	84600	223 REM	23-Jul-11	N	PD/S	11-Feb-14	13-Apr-15	Fired on Bolt Closing	Service	n/a	F	
9955	700	N/A	3006 SPRG	1-0ct-72	N	5	13-Feb-14	13-Feb-14	Fired on Safe Release	Altered Adjustments or Components	337587	F	Per Ilion, replace trigger, check over, and test at 50% discount
9956	7	27253	7MM08 REM	4-Jan-11	N	s	13-Feb-14	13-Feb-14	Fired With Safe ON	Could Not Duplicate Concern	337699	F	Replace trigger, check over, and test at no charge
										CONTRACTOR NO. 18			
9957	700	25771	270 WIN	26-Feb-98	N	s	13-Feb-14	13-Feb-14	Fired on Bolt Closing	Could Not Duplicate Concern	337549	F	Replace trigger, check over, and test at no charge
9958	700	27194	243 WIN	8-Jun-11	N	S	13-Feb-14	13-Feb-14	Fired With Safe ON	Could Not Duplicate Concern	337582	F	Per Ilion, check over, repair as needed, and test at no charge
									5 5 5	Could Not Duplicate			
9961	600	N/A	308 WIN	30-Jan-76	N	S	14-Feb-14	14-Feb-14	Fired on Bolt Closing	Concern	337801	F	Per Ilion, quote to repair BLN
9964	597	26516 25793	17 HMR 3006 SPRG	15-Oct-03 31-May-96	N	PD/S	17-Feb-14	17-Feb-14	My Gun Blew Up Fired on Bolt Opening	Other - Unspecified or Undetermined - Firearms Altered Adjustments or Components	334338 406892	F	Repair @ n/c - goodwill
3314	700	23733	SOUD STITLE	Ja way 50		10/3	17 100 14	4300.44	Орстипу	Not Examined by Product	400052	-	Gun not returned to Ilion for
9966	1100	N/A	12 GA		N	S	17-Feb-14	13-Apr-15	Fired With Safe ON	Service	n/a	F	
9977	700	N/A	22-250 REM	30-Mar-84	N	PD/S	18-Feb-14	10-Apr-14		Altered Adjustments or Components	340286	F	Check over completely, repair as needed, and test fire at a 50% discount
9970	660	not avail.	308 WIN	14-Apr-70	Υ	s	19-Feb-14	19-Feb-14	Fired on Safe Release	Altered Adjustments or Components	337922	F	The control of the co
	100001	W-1000	000000000	. 2007/09/09		100		Santa S	Delayed Firing -	Transport to the Control of the Cont	100000000000000000000000000000000000000		Per Ilion - Quote to repair @
9972	700	25795	308 WIN	1-Mar-84	N	5	19-Feb-14	19-Feb-14	Firearms	Improper Maintenance	338178	F	
9978	597	26536	17 HMR	23-Mar-03	N	PD/S	19-Feb-14	28-Jul-14	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	339928	F	Replacing with Ramac 70703 in exchange and 5 boxes of 17 HMR ammo
9979	700	N/A	308 WIN	1-Mar-68	N	s	20-Feb-14	20-Feb-14	Fired on Safe Release	Improper Maintenance	338234		Per Ilion, quote to repair BLN
9981	887	82500	12 GA	25-Jun-12	N	s		21-Feb-14	Dissatisfied with Service - Firearms	Could Not Duplicate Concern	338353		Per Ilion, check over, repair a: needed, and test at no charge Per Ilion, replace trigger,
9982	700	85536	3006 SPRG	7-Sep-10	N	s	21-Feb-14	21-Feb-14	Fired on Bolt Closing	Could Not Duplicate Concern	338362	F	check over and test fire at no charge